

**SONY**

Hi-Fi Products  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** SS-U310

**No.** 172

**Subject:** Part Number Correction

**Date:** February 28, 1991

**Symptom:**  
(\*\*)

The part number listed in the service manual for the Wire Kit, which includes L1 and C1, is incorrect.

**Solution:** Please correct your service manual with the information listed below:

Description	Incorrect	Correct
Wire Kit	1-9690-012-A	T-9690-012-A

CSA-13 Speakers