

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D-T66

No. 179

Subject: Extension Cable Availability

Date: March 29, 1991

Symptom:
(**)

An extension cable is now available for connecting the main board to the control board when repairing.

Solution: Please update your service manual with the part number information listed below:

Part Number	Number of Pins	Points Connected
J-6181-038-A	16	CN801 - CN802

