

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: DTC-1000ES

No. 201

Subject: Power Transformer Clarification - T901

Date: July 29, 1991

Symptom: The Service Manual shows two different part numbers for the power transformer, without specifying destination (US, UK, AEP, etc.).
(**)

Solution: Please update the following part numbers in your Service Manual:

REFERENCE NUMBER	DESCRIPTION	PART NUMBER
T-901	POWER TRANSFORMER (UK)	1-449-017-11
T-901	POWER TRANSFORMER (AEP)	1-449-017-11
T-901	POWER TRANSFORMER (US)	1-449-018-11

CSA-13 DAT

