

**SONY**

Hi-Fi Products  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** STR-D390

**No. 337**

**Subject:** Part Number Correction - Reference No. Q712,  
2SD2064

**Date:** April 23, 1993

**Symptom:**

(\*\*)

The part number listed on page 40 of the Service Manual for Ref # Q712,  
2SD2064, is incorrect.

**Solution:**

Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
Q712	2SD2064	8-729-016-17	8-729-016-07

Receiver  
CSA-13



PRINTED ON RECYCLED PAPER

Reference: FPR-Q0071  
Autoflagged - NO

PRINTED IN U.S.A.  
CSA-13493-6