

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: HCD-H61M

No. 338

Subject: Extension Cable Jig Now Available


Date: April 23, 1993

Symptom:
(**)

A extension cable jig is now available to aid in the repair of this unit.

Solution: Order the extension cable jig as shown in the chart below.

NO. TERMINALS	POINTS CONNECTED	PART NUMBER
9 PIN	MAIN BOARD CN604 TO TC BOARD CN408	J-2501-052-A



CSA-13 Compact System



PRINTED ON RECYCLED PAPER

Reference: FPR-01268
Autoflagged - NO

PRINTED IN U.S.A.
CSA-13493-6