

SONY.

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: TA-AV531

No. 361

Subject: Part Numbers Missing - Reference No.'s Q712,
Q762 (2SC2921) and Q713, Q763 (2SA1215)

Date: November 30, 1993

Symptom:

(**)


The part numbers for Ref #'s Q712, Q762 (2SC2921) and Q713, Q763 (2SA1215) which are shown on page 19 of the Service Manual, are not listed in the parts list for this model.

Solution:

Please add the following part numbers to the Service Manual.

REF	DESCRIPTION	PART NUMBER
Q712	2SC2921	8-729-320-96
Q713	2SA1215	8-729-300-22
Q762	2SC2921	8-729-320-96
Q763	2SA1215	8-729-300-22

[MAIN BOARD]



Reference: FPR-O2742
Autoflagged - NO



PRINTED IN USA
CSA-131193-2