

SONY.

Audio Products
Service Bulletin

CSA-11

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: MZ-E2

No. 310

Subject: Displaying Disc Information When A Car Connecting Pack Is Used.

Date: August 5, 1994

Symptom:
(13)

The customer may complain that the use of a car connecting pack (cassette adapter) prevents using the remote controller/display.

Solution:

If the customer complains of this, suggest that he/she purchase the plug adapter and extension cord as shown below.

REF	DESCRIPTION	PART NUMBER
-	MICRO- 2 WAY PLUG	1-696-928-21
-	PLUG ADAPTER	PC231S

