Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services A Division of Sony Electronics Inc. Sony Drive, Park Ridge, New Jersey 07656

Model: HCD-C70/C90 No. 441


Subject: Extension Board Available **Date:** June 2, 1995

Symptom:

(**) The following Extension Board is now available under part number J-2501-078-

Α

Solution: Use the PFJ-1 Jig and 15 pin cable (P/N 1-751-469-11) to connect the jig and Extension board. See diagram below.





Audio Products Service Bulletin No. xxx

Filename: HFP0441.SB

Directory: J:\SBDOC\JUN95

Template: C:\WINWORD\TEMPLATE\S_BULL.DOT

Title: Subject:

Author: Hoyt Wing Lee

Keywords: Comments:

Creation Date: 06/02/95 11:33 AM

Revision Number: 3

Last Saved On: 06/05/95 1:07 PM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 2 Minutes

Last Printed On: 04/01/96 9:08 AM

As of Last Complete Printing Number of Pages: 2

Number of Words: 108 (approx.)

Number of Characters: 616 (approx.)