

SONY.

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: MHC-C7EX/C9EX

No. 445


Subject: New Extension Board Available

Date: July 20, 1995

Symptom:

(**) A new extension board is now available. The part number is J-2501-063 A.

Solution: See diagram below.



Other Applicable units:

5P Cable 1-751-541-11: (MHC-7900) ST-H7900, CDP-H7900, TC-H7900

15P Cable 1-751-469-11: (HCD-70/90) HCD-C70, HCD-C90, (will not operate the HCD-S70C or HCD-S90C tuner).

Reference: Technical News AU95002
Autoflagged - NO



PRINTED IN USA