

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: SEN-205, TC-FX205, TC-FX430

No. 477

Subject: Replacement Cassette Holder Available

Date: March 25, 1996


Symptom:

(**)

The original cassette holder (A-2173-013-A or X-3318-918-1) is no longer available. Use the following part number when ordering X-3318-945-1.

Solution:

To correctly mount the replacement Cassette Holder, it is necessary to add the Left Spring (3-307-371-00) and the Right Spring (3-307-372-00). See diagram below.



Filename: HFP0477.SB
Directory: J:\SBDOC\MAR96
Template: C:\WINWORD\TEMPLATE\S_BULL.DOT
Title:
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 03/25/96 10:17 AM
Revision Number: 2
Last Saved On: 03/25/96 10:17 AM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 0 Minutes
Last Printed On: 04/01/96 9:36 AM
As of Last Complete Printing
Number of Pages: 1
Number of Words: 127 (approx.)
Number of Characters: 727 (approx.)