



Sony Service Company
National Technical Services
A Division of Sony Electronics Inc.
Park Ridge, New Jersey 07656

CONFIDENTIAL

CSA-13

Service Bulletin Hi-Fi Products

Model: CDP-XA3ES

No. 532

Subject: Variable TIME FADE Does Not Set Up

Date: June 12, 1997

Symptom:

(22)

When the EDIT FADE TIME is set and the power is switched OFF and ON the FADE TIME entered may not be held in memory.

Solution: Replace the Microprocessor outlined below.

[MAIN BOARD]

