

CONFIDENTIAL

CSA-13

Sony Service Company National Technical Services A Division of Sony Electronics Inc. Park Ridge, New Jersey 07656

Service Bulletin Hi-Fi Products

Model: HCD-RX70 No. 566

Subject: Part Number Correction - Reference No. 419, Date: June 8, 1998

Spring (FR), Torsion

Symptom:

(**) The part number listed on page 92 of the Service Manual for Ref # 419, Spring (FR),

Torsion, is incorrect.

Solution: Please note the correct part number as shown below.

| REF | DESCRIPTION | PART NUMBER | |
|-----|----------------------|--------------|--------------|
| | | INCORRECT | CORRECT |
| 419 | SPRING (FR), TORSION | 3-914-111-01 | 3-911-114-01 |

Reference: Japan Technical Bulletin AU01198

PRINTED IN USA