

# SONY®

## Service Bulletin

NO: ME3-97-002

---

**SUBJECT: TEST MODE PROCEDURE FOR SLED MOVEMENT OPERATION**

---

**DATE: AUGUST 1997**

**MODEL (S): MDX-C150**

---

### FOR INTERNAL USE ONLY

**SYMPTOM:** The procedure in the service manual is not fully outlined. When the MDX-C150 is in test mode (4 5 1), you may not be able to move the sled motor when pressing the (<<PRST/DISC+>>) button. This button allows the sled to move reverse and forward.

**SOLUTION:** The test mode procedure should be as follows, to test the MDX-C150 sled movement operation.

1. Place unit in test mode press **4,5, and 1 (hold 1 for 2 seconds)**.
2. Press **MD** button.
3. Press **4** (this stops and sets the unit in test mode).
4. Follow the rest of the procedure that is listed in the service manual for the Laser adjustment. In this case you probably would want to press the (<<-PRST/ISC+>>) key.

SONAM 423