

SONY®

Service Bulletin

NO:HIF11-00-012

SUBJECT: Characters added when using "Name In" Function

DATE: July 2000

MODEL (S): HCD-MDX10, DHC-MDX10

Symptom: The customer complaint states there is unrelated information added when inputting letters while using the "Name In" Function of MD.

Ex. Input – "CHECK". Indicated in Display - "CHECK OPTIN"

Solution: Replace the following with improved

| Model | REF | FORMER | | NEW | |
|---------------|-------|-----------------|--------------|---------------|--------------|
| | | DESCRIPTION | PART NUMBER | DESCRIPTION | PART NUMBER |
| DISPLAY | IC610 | TMP88CS77F-6003 | 8-759-582-73 | MDX10 IC KIT | X-4952-960-1 |
| MD DIGITAL | IC316 | M30624MG-A01FP | 8-759-585-60 | M3062MG-A16FP | 8-759-657-09 |

Sony of Canada Ltd.

115 Gordon Baker Road, Toronto, Ontario M2H-3R6
NATIONAL LAB - CONSUMER SERVICE

SONAM618
AU-99064