



## Repair Tips

---

**SUBJECT:** Unit Will Load Discs But Will Not Spin Or Eject Them

---

**DATE:** May 2001

**MODEL (S):** MDS-M9

---

**Symptom:** Unit will load discs but will not spin or eject them.

**Solution:** The fault was the home limit switch S101 for the optical. It will cause IC431 to burn up. It looks like a power supply fault when you first see it. The intermittent home switch causes load while the unit is ejecting (Optic not home error) - IC431 burns up.

**Submitted By:** PHD Electronics, Brian Street