

# PRODUCT DISCONTINUANCE BULLETIN



**Issue Date:** March 7, 2003

**PDB #:**PDB\_D\_bc330-530SBX.doc

## Product(s)

Datum Model bc330SBX Time Code Reader  
Datum Model bc530SBX Time Code Generator

## Overview

Symmetricom is announcing the discontinuance of the Datum bc330SBX Time Code Reader and the Datum bc530SBX Time Code Generator. The bc330SBX and bc530SBX have reached the end of their technology product lifecycle and the manufacturing of these products are being discontinued.

## Product Obsolescence Timeline

Milestone	Date
Last Day to Order	June 7, 2003

## Affected Models and Replacement Product Summary

Current Model	Current Part #	Replacement Model
Datum bc330SBX Time Code Reader	BC11403-1000	none
Datum bc530SBX Time Code Generator	BC11433-1000	

## Support Policy

Product support services (telephone technical support, on-site maintenance, training, spares support, etc.) and repairs are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. All services may not be available for every product. Interested customers should contact SGS to check a product's eligibility for services and any applicable terms.

## Contact Information

Symmetricom Global Services      1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide

Symmetricom Customer Service:      1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide  
support@symmetricom.com  
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.  
Santa Rosa, CA 95403  
Telephone: 707-528-1230  
Facsimile: 707-527-6640