

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: March 7, 2003

PDB #: PDB_D_bc330STD.doc

Product(s)

Datum Model bc330STD Time Code Reader

Overview

Symmetricom is announcing the discontinuance of the Datum bc330STD Time Code Reader. The bc330STD has reached the end of its technology product lifecycle and the manufacturing of this product is being discontinued.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	June 7, 2003

Affected Models and Replacement Product Summary

Current Model	Current Part #	Replacement Model
Datum bc330STD Time Code Reader	BC11593-1000	none

Support Policy

Product support services (telephone technical support, on-site maintenance, training, spares support, etc.) and repairs are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. All services may not be available for every product. Interested customers should contact SGS to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640