

# Release Notes Addendum



## **MCS-300 Software Release 5.6.1**

**061-4180-00**

# Contacting Tektronix

		<b>Voice</b>	<b>Fax</b>	<b>Addresses</b>	<b>Web Site</b>
<b>Customer Support</b>	North America	(800) 547-8949	(530) 478-3181	Tektronix, Inc.	<a href="http://www.tektronix.com">http://www.tektronix.com</a>
	Elsewhere	Distributor or sales office from which equipment was purchased.		Tektronix Grass Valley Products P.O. Box 1114 Grass Valley, CA 95945, USA	
<b>Product, Service, Sales Information</b>	North America	(800) 547-8949	(503) 627-7275	Tektronix, Inc.	<a href="http://www.tektronix.com">http://www.tektronix.com</a>
	Europe	44 (10) 1628 40 3300	44 (0)1628 40 3301	Video and Networking Division P.O. Box 500	
	Asia	(852) 2585-6688	(852) 2802-2996	M.S. 58-965	
	Japan	81 (3) 5992 0621	81 (3) 5992 9377	Beaverton, OR 97077-0001, USA	
	Latin America	(305) 477-5488	(305) 477-5385		

Copyright © Tektronix, Inc. All rights reserved.

This document may not be copied, in whole or in part, or otherwise reproduced, except as specifically permitted under U.S. copyright law, without the prior written consent of Tektronix, Inc., P.O. Box 1000, Wilsonville, Oregon 97070-1000. TEKTRONIX is a registered trademark and Grass Valley is a trademark of Tektronix, Inc. All registered trademarks and trademarks are property of their respective holders. Tektronix products are covered by U.S. and foreign patents, issued and pending. Product options and specifications subject to change without notice. The information in this manual is furnished for informational use only, is subject to change without notice, and should not be construed as a commitment by Tektronix, Inc. Tektronix assumes no responsibility or liability for any errors or inaccuracies that may appear in this publication.

Version **5.6.1**  
*March, 1999*

## MCS-300 v5.6.1 Defect List

This document lists unresolved defects in the Tektronix MCS-300 v5.6.1 Software Release. See the v5.6.1 Release Notes for the new features and resolved defects for this release.

### Unresolved Software Defects

- Site Controller gets “No further info available” after conflict check (GVGaa07815).  
After adding a reservation via Site Controller, you may get the message “No further info available.” Even though the reservation passes conflict check, it is in the database and the session runs.
- Two alarm ports allowed (GVGaa08139).  
You can modify an alarm port, which results in two alarm ports being saved into the DB. When entering new ports, only one alarm port is allowed.
- Archived Reservation Report should show weekdays (GVGaa07748).  
Archived reservation report should print out the days of the week when the reservation ran.

