

# Read This First



## TVS600 and TVS600A Series Waveform Analyzers

**001-1340-00**

### TVS PV/Cal Software Change

As of November 1, 2001, TVS PV/Cal Software (Part Number 063-2874-01) is no longer included with these products and will not be supported. Any reference to this software and related procedure instructions in the *TVS600 and TVS600A Series Waveform Analyzers Service Manual* (Part Number 070-9915-XX) should be ignored.

Please contact your nearest Tektronix Service Center for any performance verification or calibration services required. To return an instrument to Tektronix for service, see *Contacting Tektronix* on the back of this sheet.

[www.tektronix.com](http://www.tektronix.com)



001134000

## Contacting Tektronix

<b>Phone</b>	1-800-833-9200*
<b>Address</b>	Tektronix, Inc. Department or name (if known) 14200 SW Karl Braun Drive P.O. Box 500 Beaverton, OR 97077 USA
<b>Web site</b>	<a href="http://www.tektronix.com">www.tektronix.com</a>
<b>Sales support</b>	1-800-833-9200, select option 1*
<b>Service support</b>	1-800-833-9200, select option 2*
<b>Technical support</b>	Email: <a href="mailto:techsupport@tektronix.com">techsupport@tektronix.com</a> 1-800-833-9200, select option 3*  6:00 a.m. – 5:00 p.m. Pacific time

---

\* This phone number is toll free in North America. After office hours, please leave a voice mail message. Outside North America, contact a Tektronix sales office or distributor; see the Tektronix web site for a list of offices.