

## Installing Badges on Liftgate

Classification Parts and Section/Group 12 - Exterior Country/Region North America

Accessories Fittings

Bulletin

Year 2012-2013 Model Model S Version All

**Bulletin Classification:** This bulletin provides instructions and guidelines for a vehicle procedure that is not the result of a defect. This bulletin might not be VIN-specific. These instructions assume knowledge of motor vehicle and high voltage electricity repairs, and should only be executed by trained professionals. Tesla Motors assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

This Service Bulletin supersedes SB-13-12-002, dated 13-Apr-13. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

## Condition

A liftgate-mounted badge that indicates the battery size is now available. A reusable template can be used to retrofit this badge to earlier vehicles. An additional reusable template is available for installation of the liftgate-mounted Model S badge.

## Correction

Upon customer request, install a battery badge and/or a Model S badge on the liftgate.

Required Part(s):	<b>Part Number</b> 1013738-00-C	<b>Description</b> MODEL S BADGE	Quantity 1
	One of the following:		
	1014879-00-D	P85 BADGE	1
	1016270-00-B	85 BADGE	1
	1016271-00-B	60 BADGE	1
	1016273-00-B	40 BADGE	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Special Tool(s): 1024723-00-A MODEL S BADGE FIXTURE

1024725-00-A LOWER BATTERY DESIGNATION FIXTURE UPPER BATTERY DESIGNATION FIXTURE

Correction Description	Correction	Time
Vehicle Inspection Only; Badge Installation Not Required	S011312002	0.1
Install Battery Badge On Liftgate	S021312002	0.3
Install Model S Badge On Liftgate	S031312002	0.3
Install Battery Badge And Model S Badge On Liftgate	S041312002	0.6

## **Procedure**

1. Install a battery badge and/or a Model S badge on the liftgate (refer to the "Installation Using Fixture Tools" section of Service Manual procedure 12050602).

NOTE: Badge fixture tools are required to retrofit badges on the liftgate.

Affected VIN(s) Affected Model S vehicles built before approximately March 12, 2013.

**NOTE:** This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email <u>ServiceBulletinFeedback@teslamotors.com</u>.