

VESTEL ELEKTRONİK A.Ş.	CHANGE BULLETIN (TCN)	CHANGE NO: 68 REF NO : UMB 1257
-----------------------------------	----------------------------------	--

AFFECTED MODELS: ALL MODELS WITH 11AK20S-2 CHASSIS.

NOTE 1: 11TR20 BOARD MUST BE INSERTED INSTEAD OF Q604 SO THAT THE COMPONENT SIDE POINTS THE FBT (fly-back transformer).

START DATE : 22.11.1999

REASONS OF CHANGE: PROTECTION OF Q604 (HORIZONTAL DRIVER TRANSISITOR).

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK20S-2	30001455	TR BC558B	Q604	1

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK20S-2	20034026	11TR20 BOARD	Q604 (NOTE 1)	1

APPLICATION ENGINEER	APPLICATION ENGINEERING CHIEF	APPLICATION ENGINEERING MANAGER
-	YILDIRAY BAŞKURT	CELAL ÖZKUL