

Please note the following changes to user's manual IM WX1-03E.

■ **Page 1-2 Note the addition of the following to “Hardware Requirements.”**

- GP-IB port : Required for GPIB communications between the software and a WT series instrument.
Please use the PCI-GPIB or PCMCIA-GPIB by National Instruments.