

Technical Comments

Erratum: "Bending-Torsion Transfer Matrices Associated with Swept Surfaces"

KENT L. LAWRENCE*
Arlington State College, Arlington, Texas

[J. Aircraft 3, 478 (1966)]

EQUATION (5) should read:

$$M^R = M^L - \Omega^2(I + me^2 \sin^2 \beta) \psi + \Omega^2(me \sin \beta) w + \Omega^2(me^2 \sin \beta \cos \beta) \phi + [(f_3 h + f_2 e) \sin \beta - (Q_1 + Q_2 + Q_3)]$$

Received October 25, 1966.

* Assistant Professor of Engineering Mechanics. Member AIAA.

Erratum: Subject Index, 1966

[J. Aircraft 3, 608 (1966)]

THE paper by Eugene H. Handler entitled "Tilt and vertical float aircraft for open ocean operations" should be indexed under "Aircraft" instead of under "Marine Technology."