Technical Comments

Erratum: "Bending-Torsion Transfer Matrices Associated with Swept Surfaces"

Kent L. Lawrence*
Arlington State College, Arlington, Texas

[J. Aircraft 3, 478 (1966)]

RQUATION (5) should read:

$$M^{R} = M^{L} - \Omega^{2}(I + me^{2}\sin^{2}\!\beta)\psi + \Omega^{2}(me\sin\!\beta)w + \Omega^{2}(me^{2}\sin\!\beta\cos\!\beta)\phi + [(f_{3}h + f_{2}e)\sin\!\beta - (Q_{1} + Q_{2} + Q_{3})]$$

Received October 25, 1966.

Erratum: Subject Index, 1966

[J. Aircraft 3, 608 (1966)]

THE paper by Eugene H. Handler entitled "Tilt and vertical float aircraft for open ocean operations" should be indexed under "Aircraft" instead of under "Marine Technology."

^{*} Assistant Professor of Engineering Mechanics. Member AIAA.