



Corrigendum

Corrigendum to “Preparation of Cu/ZnO/Al<sub>2</sub>O<sub>3</sub> catalyst  
for a micro methanol reformer”  
[J. Power Sources 150 (2005) 20–26]

Yoshihiro Kawamura<sup>a,\*</sup>, Kazuto Yamamoto<sup>a</sup>, Naotsugu Ogura<sup>a</sup>,  
Takashi Katsumata<sup>b</sup>, Akira Igarashi<sup>b</sup>

<sup>a</sup> CASIO Computer Co., Ltd., 3-2 Fujihashi 3-chome, Ome-shi, Tokyo 198-0022, Japan

<sup>b</sup> Department of Environmental Chemical Engineering, Kogakuin University, 2665-1 Nakano-machi, Hachioji-shi, Tokyo 192-0015, Japan

Available online 5 December 2005

---

The authors regret that some errors occurred during the editing process of the original pre-print of the above-mentioned article. An EDX spectrum of “point 1” in Fig. 4 should have been published as in the revised version of the figure below. In addition, in page 3, line 211, “TG-DTA2010” should be replaced to “TG-DTA2000” and, in page 6, line 361, Co<sub>3</sub><sup>2+</sup> should be replaced to Co<sub>3</sub><sup>2-</sup>.

---

DOI of original article: [10.1016/j.jpowsour.2005.02.030](https://doi.org/10.1016/j.jpowsour.2005.02.030).

\* Corresponding author. Tel.: +81 428 32 1741; fax: +81 428 31 7651.

E-mail address: [kawamuy@rd.casio.co.jp](mailto:kawamuy@rd.casio.co.jp) (Y. Kawamura).




Fig. 4.