



Erratum

Erratum to “Corrosion resistance characteristics of stamped and hydroformed PEMFC metallic bipolar plates” [J. Power Sources 195 (11) (2010) 3546–3552]

F. Dunder^{a,b}, Ender Dur^a, S. Mahabunphachai^{a,c}, Muammer Koc^{a,*}

^a NSF I/UCRC Center for Precision Forming (CPF), Virginia Commonwealth University, Richmond, VA, USA

^b Department of Materials Science and Engineering, Gebze Institute of Technology, Turkey

^c National Metal and Materials Technology Center (MTEC), Pathumthani, Thailand

The publisher regrets that in Fig. 8(a) and (b) sections are the same. The correct figure is shown below. The publisher would like to apologise for any inconvenience this may have caused to the authors of this article and readers of the journal.




Fig. 8. Effect of pressure and stamping force on corrosion resistance with purging (a) H₂ gas, and (b) O₂ gas.

DOI of original article: [10.1016/j.jpowsour.2009.12.040](https://doi.org/10.1016/j.jpowsour.2009.12.040).

* Corresponding author. Tel.: +1 804 827 7029; fax: +1 804 827 7030.

E-mail address: mkoc@vcu.edu (M. Koc).