



Erratum

Erratum to ‘Dependence of the non-swelling
in-reactor steady-state creep component of austenitic phase
alloys on the stacking fault energy’
[J. Nucl. Mater. 298 (2001) 321–328] ☆

Edgar Robert Gilbert ¹, John Paul Foster *

Commercial Nuclear Fuel Business Division, Westinghouse Electric Company, P.O. Drawer R, Columbia, SC 29250, USA

In the final printed version of the paper, the data in the final column (Bo) were incorrect. The correct version of the complete table (Table 2) is shown below.

Table 2
Summary of Bo and SFE results for helices irradiated in the DFR [23,24]

Alloy	Specimen	Test rig	Temperature (°C)	Dose (dpa)	SFE (mJ/m ²)	Bo ($\times 10^{-6}$ MPa ⁻¹ dpa ⁻¹)
17Cr14NiMoTiNb 20% CW M316-1	1(3)	395	290–304	4.5	17.2	1.2
	4(3)		271–290	4.7		1.0
17Cr14NiMo 20% CW M316-2	4(4)	9(3)	247–290	3.9	19.6	1.7
	9(3)			4.6		1.6
17Cr13NiMo 20% CW M316-3	6(2)	7(2)	271–290	4.4	20.2	1.3
	7(2)			4.4		1.1
17Cr12NiMo 20% CW M316-II	15(2)			4.0	18.6	1.2
17Cr12NiMoNb 20% CW FV548-1	4(2)	546	500	4.4	21.8	1.5
	9(2)			4.7		2.0
	1(1)			3.1		1.7
	4(1)			2.7		2.1
	4(3)			4.7		2.1
17Cr11NiMoNb 20% CW FV548-II	14(2)	395	290	4.3	22.8	1.8
18Cr9NiMoTi 20% CW EN58B-1	6(3)	15(1)	271–290	4.4	23.0	2.0
	10(4)		3.1	2.1		
	15(1)		271	3.3		2.2
18Cr11NiMo 20% CW EN58E-1	7(1)	12(2)	271–290	3.6	31.3	4.0
	12(2)		271–304	4.6		4.0
17Cr9NiMo 20% CW EN58J-1	7(3)	12(3)	271–290	4.5	23.0	2.2
	12(3)		271–304	4.6		2.2
17Cr12NiMo EN58J-II	1(3)	456	271–290	3.0	21.5	2.0

☆ PII of original article: S0022-3115(01)00646-8.

* Corresponding author. Tel.: +1-803 647 3632; fax: +1-803 695 4148.

E-mail address: fosterjp@westinghouse.com (J.P. Foster).

¹ Pacific Northwest National Laboratory, Richland, WA, USA.