BY ORDER OF THE COMMANDER, 36TH AIR BASE WING (PACAF)

36 AIR BASE WING INSTRUCTION 84-101 4 DECEMBER 2003

History



STATIC DISPLAY PROGRAM

COMPLIANCE WITH THIS PUBLICATION IS MANDATORY

NOTICE: This publication is available digitally on the AFDPO WWW site at: http://www.e-publishing.af.mil.

OPR: 36 MXS/MXMF (MSgt Bryan D. Tieszen)

Supersedes 36 ABWI 84-101, 16 November 1997

Certified by: 36 MXG/CC (Col. Charles G. Crawford) Pages: 2 Distribution: F

This instruction implements AFPD 84-1, Historical Information Property and Art and is supplementary to guidance found in AFI 84-103, U.S. Air Force Heritage Program, paragraph 7.3. This publication does not apply to the Air National Guard (ANG) or US Air Force Reserve and their units.

SUMMARY OF REVISIONS

This revision incorporates procedures formally published in 36 ABWI 84-101. It aligns procedures with AFPD 84-1 and clarifies responsibilities within the wing. A (|) indicates revision form the previous edition.

1. General. The purpose of this program is to preserve the heritage of the 36th Air Base Wing and Andersen Air Force Base through professional, well-maintained outdoor aircraft displays.

2. Responsibilities.

- 2.1. The 36 MXG/CC will:
 - 2.1.1. Provide personnel to perform maintenance and preservation requirements.
- 2.2. The 36 MXS/CC will:

2.2.1. Provide supervisory oversight for all maintenance and refurbishment through the Fabrication Flight.

2.2.2. Appoint a Historical Property Custodian (HPC) who will maintain the official aircraft forms in their office.

2.2.3. Ensure both the B-52 and the F-4 are rinsed every 120 days, washed and inspected for corrosion semi-annually. Treat corrosion, accomplish structural repairs and touch up paint as necessary annually. Actions will be documented in the aircraft forms.

2.2.4. Ensure the names of the 13th Air Force Commander, Vice Commander, Command Chief Master Sergeant and First Sergeant found on the F-4's canopy are updated as required.

2.2.5. Ensure security of canopies, windows, doors, hatches and panels to prevent public entry to aircraft.

2.3. The 36 ABW/HO will:

2.3.1. Provide general administration of the wing's program.

2.4. The 36 SFS/CC will:

2.4.1. Perform security/resource protection assessment of static displays. Evaluate display lighting to curb vandalism and damage to the display.

2.5. The 36 CES/CC will:

2.5.1. Repair/replace light fixtures as required.

2.6. The 36 ABW/SE will:

2.6.1. Conduct an annual safety inspection of each static display and forward the results to the MXG/CC and ABW/CC.

3. Location.

3.1. The B-52 aircraft is located at the Arc Light Memorial. The F-4 display is located on Bonins Boulevard.

NOTE:

4. Funding. The 36 ABW will provide reimbursement funds to the 36 MXG for purchase of materials needed to accomplish the above maintenance requirements.

5. Safety. Structural integrity of the displays and visitors safety is paramount.

JOSEPH F. MUDD, JR., Colonel, USAF Commander, 36th Air Base Wing