

**M9 ACE**

**COLD WEATHER OPERATION**

***This abbreviated checklist is not to be used as a replacement for the -23 series Tech Manual or any other PMCS guide.***

**Operation in extreme cold**

1. Check Coolant
2. Clean and lube Fire Extinguisher Actuators
3. Check Hydraulic oil
4. Check final drive oil
5. Check Engine oil
6. Check belt and tensioner
7. Check for fuel leaks
8. DO YOUR PMCS
9. Follow procedures in Operation in Extreme Cold pg 2-95 TM 5-2350-262-10, and TB 43-0245-5.

Approved for public release: distribution is unlimited

Distributor: U.S Training Support Center

June 2006