## DEPARTMENTS OF THE ARMY AND AIR FORCE TECHNICAL BULLETIN

## WARRANTY PROGRAM

**FOR** 

# M1083A1 SERIES, 5 TON, 6X6, MEDIUM TACTICAL VEHICLES (MTV)

Contract Number DAAE07-98-C-M005 Contract Number DAAE07-03-C-S023

## Headquarters, Department of the Army, Washington, DC Headquarters, Department of the Air Force, Washington, DC

#### REPORTING ERRORS AND RECOMMENDING IMPROVEMENTS

You can help improve this publication. If you find any mistakes or if you know of a way to improve the procedures, please let us know. Submit your DA Form 2028-2 (Recommended Changes to Equipment Technical Publications), through the Internet, on the Army Electronic Product Support (AEPS) website. The Internet address is <a href="http://aeps.ria.army.mil">http://aeps.ria.army.mil</a>. If you need a password, scroll down and click on "ACCESS REQUEST FORM". The DA Form 2028 is located in the ONLINE FORMS PROCESSING section of the AEPS. Fill out the form and click on SUBMIT. Using this form on the AEPS will enable us to respond quicker to your comments and better manage the DA Form 2028 program. You may also mail, fax or email your letter, DA Form 2028, or DA Form 2028-2 direct to: Commander, U.S. Army Tank-automotive and Armaments Command, ATTN: AMSTA-LC-CIP-WT, Rock Island, IL 61299-7630. The email address is TACOM-TECH-PUBS@ria.army.mil">http://aeps.ria.army.mil</a>. The fax number is DSN 793-0726 or Commercial (309) 782-0726.

#### SECTION I

FMTV A1's Serial Numbers Through 099999 Contract Number DAAE07-98-C-M005 (See Section II for FMTV A1's Serial Numbers 100001 and up)

1. General. The FMTVA1, serial numbers up through 09999, has an S&S Extended Warranty and Pass-Through Warranties, which are Vendor's (Allison, Caterpillar, Michelin) Commercial Warranties. These vehicles may also have some additional warranty coverage described in paragraphs 6 through 10. All are administered by Stewart & Stevenson Tactical Vehicle Systems, LP (TVSLP). The items identified in Table 1. Supplier Summary Section are items which have Pass-Through Warranties available. The terms, duration, warranty start dates, etc., vary greatly between the Vendors. For example, some Vendor's Warranties

begin when the item is manufactured, others begin when the end item ships from TVSLP. For some warranties, TVSLP must review documentation to find out if an item is still covered by warranty. The items identified in Table 2. S&S Extended Summary Section are items warranted by TVSLP. To find out if a Pass-Through Warranty for an item listed in Table 1. Supplier Summary Section, an S&S Extended Warranty for an item listed in Table 2, or additional warranty coverage described in paragraphs 6 through 10 are still in effect, simply contact your local WARCO. Your local WARCO can contact TVSLP at 1-800-221-3688, and ask for the

**<u>DISTRIBUTION STATEMENT A.</u>** Approved for public release; distribution is unlimited.

Warranty Department, or contact them through their website at www.tvsonlinesupport.com. The Warranty Department will need the information in paragraph 3.b. to determine if the Warranty is still in effect. This bulletin provides implementation instructions for the Pass-Through, S&S Extended Warranties, and additional warranty coverage described in paragraphs 6 through 10 on the M1083A1 Series, 5 Ton, 6X6, Medium Tactical Vehicles (MTV). It contains instructions for obtaining services and/or supplies covered under warranty. This bulletin also describes methods of processing warranty claims. For additional warranty information on the M1083A1 Series, 5 Ton, 6X6, Medium Tactical Vehicles (MTV) or any U.S. Army Tank-automotive and Armaments Command (TACOM) equipment, contact your local Warranty Control Office/Officer (WARCO) or TACOM Logistics Assistance Representative (LAR). If your WARCO or TACOM LAR is not available, or if additional information is required, contact TACOM. The number to call is DSN 786-8081, COMMERCIAL (810) 574-8081. The caller should be prepared to provide: (1) name, (2) DSN and commercial telephone numbers, (3) complete unit designation, (4) identification of the vehicle, to include the serial number(s), (5) a brief description of the problem, (6) the contract number (see paragraph 3), and (7) operating hours or miles on the equipment.

#### 2. Explanation of Terms.

- **a. Abuse.** The improper use, maintenance, repair or handling of warranted items that may cause the warranty of those items to become void, for example, not following service intervals, using the vehicle for other than what is intended.
- **b.** Acceptance. The execution of the Acceptance Block and signing of DD Form 250, by the authorized Government representative.
- c. Acceptance Date. The date an item of equipment is accepted into the Army's inventory by the execution of the Acceptance Block and signing of a DD Form 250 or, in case of S&S Extended Warranty, date of shipment for purposes of fielding. Pass-Through Warranties may be different.
- **d. Contractor.** The supplier of equipment who enters into an agreement directly with the Government to furnish supplies.
- e. Correction. The elimination of a defect.

- **f. Defect.** Any condition or characteristic in supplies furnished by the Contractor that does not function as intended.
- **g. Pass-Through Warranty.** A vendor's (e.g., Caterpillar) commercial warranty that provides warranty coverage.
- **h. Failure.** A part, component, or end item that fails to perform its intended use.
- **i. Owning Unit.** The Army Unit authorized to operate, maintain, and use the equipment.
- **j. Repair.** A maintenance action required to restore an item to serviceable condition without affecting the warranty.
- **k. Supplies.** All assemblies, subassemblies, and down parts to the lowest level that comprise an end item.
- I. WARCO. Serves as the intermediary between the troops owning the equipment and the local dealer, Contractor, or manufacturer. All warranty claim actions will be processed through the WARCO.
- **m. Warranty.** A written agreement between a Contractor and the Government which outlines the rights and obligations of both parties for defective supplies.
- **n. Warranty Claim.** Action started by the equipment user for authorized warranty repair or reimbursement.
- o. Warranty Expiration Date. The date the warranty is no longer valid. This date will vary depending on each vendors Pass-Through Warranty. The S&S Extended Warranty expires 16 months after the Government Acceptance Date. Additional warranty coverages identified in paragraphs 6 through 10 will vary.
- **p. Warranty Period.** Time during which the warranty is in effect. Normally measured as the maximum number of years, months, days, miles, or hours used.
- **q. Warranty Start Date.** The date the warranty is put into effect.

- 3. Coverages-Specific. The FMTVA1, serial numbers up through 099999, has S&S Extended and Pass-Through Warranties, which are Vendor's (Allison, Caterpillar, Michelin) Commercial Warranties, as well as some additional warranty coverage described in paragraphs 6 through 10, that are administered by Stewart & Stevenson Tactical Vehicle Systems, LP (TVSLP). The items identified in Table 1. Supplier Summary Section are items which have Pass-Through Warranties available. The terms, duration, warranty start dates, etc., vary greatly between the Vendors. For example, some Vendor's Warranties begin when the item is manufactured, while others begin when the end item ships from TVSLP. For some warranties, TVSLP must review documentation to find out if an item is still covered by warranty. The items identified in Table 2. S&S Extended Summary Section are items warranted by TVSLP. The additional coverages identified in paragraphs 6 through 10 may be warranted by a Vendor or S&S. To find out if a Pass-Through Warranty for an item listed in Table 1. Supplier Summary Section, an S&S Extended Warranty for an item listed in Table 2., or any additional coverage as described in paragraphs 6 through 10 are still in effect, simply contact your local WARCO. Your local WARCO can contact TVSLP at 1-800-221-3688, and ask for the Warranty Department, or online through their website at www.tvsonlinesupport.com. The Warranty Department will need the information in paragraph 3.b. to determine if the Warranty is still in effect. This Technical Bulletin applies to the vehicles listed. The items are manufactured by Stewart & Stevenson Tactical Vehicle Systems, LP (TVSLP) under contract number DAAE07-98-C-M005. Inquiries to TVSLP can be made by calling 1-800-221-3688 or going to the website at www.tvsonlinesupport.com. These are the M1083A1 series models and the National Stock Numbers (NSN) for each:
  - TRUCK, CARGO, MTV, M1083A1; w/o wn 2320-01-447-3890, w/wn 2320-01-447-3884
  - TRUCK, CARGO, MTV, W/MHE, M1084A1;
     2320-01-447-3887
  - TRUCK, RESUPPLY VEHICLE, HIMARS, M1084A1; 2320-01-495-0110
  - TRUCK, CARGO, MTV, LONG WHEELBASE, M1085A1; w/o wn 2320-01-447-3891, w/wn 2320-01-447-3897

- TRUCK, CARGO, MTV, LONG WHEELBASE, W/MHE, M1086A1; 2320-01-447-3895
- TRUCK, TRACTOR, MTV, M1088A1; w/o wn 2320-01-447-3893, w/wn 2320-01-447-3900
- TRUCK, WRECKER, MTV, M1089A1; 2320-01-447-3892
- TRUCK, DUMP, MTV, M1090A1; w/o wn 2320-01-447-3899, w/wn 2320-01-447-6344
- TRUCK, CHASSIS, MTV, M1092A1; 2320-01-447-3894
- TRUCK, CHASSIS, MTV, LONG WHEELBASE, M1096A1; 2320-01-447-3885
- TRUCK, CHASSIS, HIMARS, XM1140; 2320-01-491-3436
- **a. Defect.** If a defect/failure is caused by (or falls within) any of the following categories, it is not considered warrantable and a claim should not be initiated:
  - (a) Misuse or negligence
  - (b) Accidents
  - (c) Improper operation
  - (d) Improper storage
  - (e) Improper transport
  - (f) Improper or insufficient maintenance service
  - (g) Improper alterations or repairs
  - (h) Defect/failure discovered or occurring after warranty expiration date
  - (i) Fair wear and tear items (brake shoes, CTIS seals, pads, armatures, brushes, etc)
  - (j) Foreign object damage
  - (k) Improper packing or handling
  - (I) Combat damage
  - (m) Consequential damages resulting from a defect or failure
- b. Pass-Through, S&S Extended Warranties, and Additional Coverages Described in
   Paragraphs 6 Through 10. Take advantage of coverage provided by these warranties. Pass-Through Warranties are provided by the vendors in

Table 1. Supplier Summary Section, but will be administered by TVSLP through your local WARCO. S&S Extended Warranties in Table 2. S&S Extended Summary Section, are supplied by TVSLP through your local WARCO. Additional coverages described in paragraphs 6 through 10 may be supplied by either source. To obtain services for Pass-Through, S&S Extended Warranties, or additional coverages described in paragraphs 6 through 10, your local WARCO simply contacts TVSLP at 1-800-221-3688, asks for the Warranty Department, or goes to their website at <a href="https://www.tvsonlinesupport.com">www.tvsonlinesupport.com</a>, and provides the following information:

- 1) Vehicle S/N
- 2) Vehicle mileage
- 3) Defective Component P/N
- 4) Description of the Defect
- 5) Component Serial No. or Date Code, if available
- 6) Quantity
- 7) Person to Contact on the Request for Warranty, to include: telephone, fax number and shipping address. This information can be sent by your local WARCO through the TVSLP website at

<u>www.tvsonlinesupport.com</u>, or via electronic mail (tvswarranty@ssss.com) utilizing DA Form 2407.

#### c. Warranty Start Dates:

- (a) Information to determine Pass-Through Warranty start dates for Allison, Caterpillar, and Michelin are listed later in the Bulletin. S&S Extended Warranties start at shipment of the vehicle for purposes of fielding. Additional coverages described in paragraphs 6 through 10 outline start dates in their respective paragraphs.
- (b) For Pass-Through, S&S Extended Warranty, or additional coverages described in paragraphs 6 through 10 your local WARCO simply contacts TVSLP online at <a href="https://www.tvsonlinesupport.com">www.tvsonlinesupport.com</a> or calls 1-800-221-3688, asks for the Warranty Department, and provides the information in paragraph 3.b. TVSLP will obtain the warranty start date and notify the Government if the warranty period has expired.

## 4. Pass-Through Warranties. Serial Numbers up through 099999

Table 1. Supplier Summary Section

VENDOR	GOV'T PART NO	NSN	DESCRIPTION
Allison	12421787-002	2520-01-460-9681	ECU
Allison	12421786	-	Shift Selector
Allison	29534235	2520-01-467-8473	Transmission, Hydraulic
Caterpillar	129-3191	2815-01-470-5796	Camshaft Assembly
Caterpillar	7E6794	2815-01-360-4450	Camshaft Followers
Caterpillar	12422551-002	-	Electronic Control Module
Caterpillar	12421794-002	-	Engine, Diesel <sup>1</sup>
Caterpillar	173-9267	2910-01-470-6177	Fuel Injector
Caterpillar	144-3472	-	Intake Manifold Gasket
Caterpillar	143-5985	-	Turbo Compressor Housing
Caterpillar	166-0331	-	Turbo Turbine Housing
Caterpillar	145-6098	-	Turbocharger Cartridge
Michelin	12378858	2610-01-356-9098	Tire, Pneumatic

<sup>&</sup>lt;sup>1</sup> Engine for Dressed Engine 12414398-006, NSN 2815-01-467-2373.

#### a. Allison

1. **Warranty Period.** The warranty start date is 3 months from date indicated in Block 3 of the DD250 and expires 24 months from that

date, unless a failure occurs within the first 3 months from DD250 date, that failure date then becomes the warranty start date and expires 24 months later. It does not cover accident damage, misuse, alterations, damage

due to lack of maintenance or use of fluids not recommended, normal maintenance such as filters, screens, and fluids, repairs by unauthorized dealers, and use of other than Allison transmission parts. The warranty includes the transmission, ECU and Shift Selector.

- 2. **Coverage.** Repairs or replacement, at Allison's option, to correct any transmission malfunction resulting from defects in material or workmanship during the warranty period. All repairs will be performed using the method Allison determines most appropriate under the circumstances. Labor costs for the removal and reinstallation of the transmission are covered when necessary to make a repair. An authorized Allison distributor must perform all warranty repairs.
- 3. **Towing.** Towing to the nearest Allison Distributor or authorized Dealer is covered only when necessary to prevent further transmission damage. Field service is provided under this warranty. If the vehicle can be driven, at Allison's request, they may require the vehicle be delivered to the nearest authorized repair center within a reasonable amount of time. A reasonable amount of time must be allowed for the repair center to perform repairs.
- 4. **Procedure.** Unit will submit a DA Form 2407 to their WARCO for submittal to TVSLP for warranty consideration.

#### b. Caterpillar

1. **Warranty Period.** 36 months or 150,000 miles, from TVSLP's warranty start date, whichever occurs first. This is a worldwide warranty. In addition, Caterpillar provides a 60 month, 100,000 mile, emissions warranty for vehicles operating in the United States. Both warranties cover genuine Caterpillar components only; this is not a dressed engine warranty.

- 2. **Towing.** The user must deliver the vehicle to the nearest Caterpillar dealer. If the vehicle in not in driving condition, Caterpillar will pay for towing.
- 3. **Procedure.** After submittal of warranty request to TVSLP, a Notification of Failure will be submitted to the nearest authorized Caterpillar dealer. The dealer is requested to contact the WARCO to arrange for warranty evaluation. The customer must provide access to electronic data stored in the ECU and the engine must remain in the vehicle.
- 4. Emissions Warranty Parts Covered. Fuel Injectors, Camshaft Assembly, Engine Rocker Arms, Turbocharger, Intake Manifold Gasket, Electronic Control Module (ECM). (See Parts Listing for Part Numbers). Items such as aftercooler core, pipes, hoses and clamps are TVSLP supplied items and are not covered by this warranty.

#### c. Michelin

- 1. **Warranty Period.** 5 years from the date of manufacture of the tire or the life of the original usable tread down to 2/32nds of and inch of tread remaining.
- 2. **Coverage.** User must pay for the cost of a new tire on a pro-rata basis calculated by multiplying the current negotiated TACOM replacement price or the Government Open Market price, whichever is applicable, by the percentage of usable tread. This does not include any mounting, balancing or other charges.
- 3. **Procedure.** ALL CONUS claims must be addressed through the Michelin Government Sales Department at 1-800-TIRE-HELP. ALL OCONUS claims must be forwarded to TVSLP for processing through Michelin's 1-800-TIRE-HELP line.

## 5. S&S Extended Warranties. Serial Numbers up through 099999

Table 2. S&S Extended Summary Section

VENDOR	GOV'T PART NO	NSN	DESCRIPTION
C.E. Niehoff	N1506-1	6115-01-419-4033	Generator, Alternator
C.E.Niehoff	N2003	6130-01-502-2579	Device, Control, Load

Table 2. S&S Extended Summary Section (Cont)

Holland	VENDOR	GOV'T PART NO	NSN	DESCRIPTION
Dana Chelsea         12378814-001         2520-01-362-3573         Power Take-off (PTO)           Dana Spicer         12421947-001         6150-01-470-3139         Cable Assembly, CTIS           Dana Spicer         12421947-003         6150-01-470-5891         Cable Assembly, CTIS           Dana Spicer         12378682-001         2920-01-470-5711         ECU, CTIS           Dana Spicer         124173831         5930-01-372-9484         Switch, Pressure           Dana Spicer         12417339-001         -         Valve Assembly, CTIS           Dana Spicer         12417383-002         4820-01-370-2751         Valve, Angle           Dana Spicer         12378688         2530-01-360-6198         Valve, Brake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Brake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Rake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Rake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Rake, Pneumatic           Dana Spicer         1241806         2530-01-361-5075         Compressor, Reciprocatir           Holladex         12378830-001         2530-01-361-6072         Compressor, Reciprocatir	Commercial Intertech	12419930	4320-01-425-3704	Pump, Rotary
Dana Spicer         12421947-003         6150-01-470-5891         Cable Assembly, CTIS           Dana Spicer         12378682-001         2920-01-470-5711         ECU, CTIS           Dana Spicer         12417381         5930-01-372-9484         Switch, Pressure           Dana Spicer         12417383-001         -         Valve Assembly, CTIS           Dana Spicer         12417383-002         4820-01-370-2751         Valve, Angle           Dana Spicer         12418057         4820-01-372-2769         Valve, Brake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Regulating           Haldex         12414366-001         4730-01-361-2173         Air Drier and Cooler           Haldex         12436-001         2530-01-361-5075         Compressor, Reciprocatir           Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421817         2520-01-463-9188         Axle Assembly           Meritor         12421816         2520-01-464-4566         Clutch, Fan           Meritor         RP-15611-NFSF-16-780         2520-01-464-5267         Axle Assembly           Meritor         RP-15611-NFSF-16-780         2520-01-472-4495         Axle Assembly           Meritor         4	Dana Chelsea	12378814-001	2520-01-362-3573	-
Dana Spicer         12378682-001         2920-01-470-5711         ECU, CTIS           Dana Spicer         12417381         5930-01-372-9484         Switch, Pressure           Dana Spicer         12417383-001         Valve Assembly, CTIS           Dana Spicer         12417383-002         4820-01-370-2751         Valve, Angle           Dana Spicer         12417383-003         4820-01-370-0133         Valve, Angle           Dana Spicer         12378688         2530-01-360-6198         Valve, Brake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Regulating           Haldex         1241366-001         4730-01-361-2073         Air Drier and Cooler           Haldex         12378830-001         2530-01-361-5075         Compressor, Reciprocatir           Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421816         2520-01-464-4568         Axle Assembly           Meritor         RP-15611-NFSF-14         2520-01-464-4568         Axle Assembly           Meritor         RP-15611-NFSF-18-780         2520-01-472-4496         Axle Assembly           Meritor         483-49-048-322 <t< td=""><td>Dana Spicer</td><td>12421947-001</td><td>6150-01-470-3139</td><td>Cable Assembly, CTIS</td></t<>	Dana Spicer	12421947-001	6150-01-470-3139	Cable Assembly, CTIS
Dana Spicer         12417381         5930-01-372-9484         Switch, Pressure           Dana Spicer         12417339-001         -         Valve Assembly, CTIS           Dana Spicer         12417383-002         4820-01-370-2751         Valve, Angle           Dana Spicer         12417383-003         4820-01-370-0133         Valve, Angle           Dana Spicer         12378688         2530-01-360-6198         Valve, Regulating           Haldex         12414366-001         4730-01-361-2173         Air Drier and Cooler           Haldex         12378830-001         2530-01-361-5075         Compressor, Reciprocatir           Holland         MSS1117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421817         2520-01-463-9188         Axle Assembly 2           Meritor         12421816         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-49-050-256         2520-01-472-4496         Drive Shaft Assembly           Meritor <td>Dana Spicer</td> <td>12421947-003</td> <td>6150-01-470-5891</td> <td>Cable Assembly, CTIS</td>	Dana Spicer	12421947-003	6150-01-470-5891	Cable Assembly, CTIS
Dana Spicer         12417339-001         -         Valve Assembly, CTIS           Dana Spicer         12417383-002         4820-01-370-2751         Valve, Angle           Dana Spicer         12417383-003         4820-01-370-0133         Valve, Angle           Dana Spicer         12378688         2530-01-360-6198         Valve, Brake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Regulating           Haldex         12414366-001         4730-01-361-2173         Air Drier and Cooler           Haldex         12378830-001         2530-01-361-5075         Compressor, Reciprocatir           Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421816         2520-01-464-4568         Axle Assembly           Meritor         12421816         2520-01-464-4568         Axle Assembly           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly           Meritor         RP-15611-NFSF-18-780         2520-01-464-4569         Axle Assembly           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-	Dana Spicer	12378682-001	2920-01-470-5711	ECU, CTIS
Dana Spicer         12417339-001         -         Valve Assembly, CTIS           Dana Spicer         12417383-002         4820-01-370-2751         Valve, Angle           Dana Spicer         12417383-003         4820-01-370-0133         Valve, Angle           Dana Spicer         12378688         2530-01-360-6198         Valve, Brake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Regulating           Haldex         12414366-001         4730-01-361-2173         Air Drier and Cooler           Haldex         12378830-001         2530-01-361-5075         Compressor, Reciprocatir           Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421816         2520-01-464-4568         Axle Assembly           Meritor         12421816         2520-01-464-4568         Axle Assembly           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly           Meritor         RP-15611-NFSF-18-780         2520-01-464-4569         Axle Assembly           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-	Dana Spicer	12417381	5930-01-372-9484	Switch, Pressure
Dana Spicer         12417383-002         4820-01-370-2751         Valve, Angle           Dana Spicer         12417383-003         4820-01-370-0133         Valve, Angle           Dana Spicer         12378688         2530-01-360-6198         Valve, Brake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Regulating           Haldex         12414366-001         4730-01-361-5075         Ompressor, Reciprocatir           Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421816         2520-01-463-9188         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4570         Axle Assembly 2           Meritor         483-49-048-322         2520-01-464-4590         Axle Assembly 2           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-49-050-356         2520-01-472-4495         Drive Shaft Assembly           Mer		12417339-001	-	1
Dana Spicer         12417383-003         4820-01-370-0133         Valve, Angle           Dana Spicer         12378688         2530-01-360-6198         Valve, Brake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Regulating           Haldex         12414366-001         4730-01-361-2173         Air Drier and Cooler           Haldex         12378830-001         2530-01-361-5075         Compressor, Reciprocatin           Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421816         2520-01-463-9188         Axle Assembly 2           Meritor         12421816         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4569         Axle Assembly 2           Meritor         483-49-048-322         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-49-050-210         2520-01-472-4499         Drive Shaft Assembly           Meritor         483-49-050-335         2520-01-472-4499         Drive Shaft Assembly           Merito		12417383-002	4820-01-370-2751	-
Dana Spicer         12378688         2530-01-360-6198         Valve, Brake, Pneumatic           Dana Spicer         12418057         4820-01-372-2769         Valve, Regulating           Haldex         12414366-001         4730-01-361-2173         Air Drier and Cooler           Haldex         12378830-001         2530-01-361-5075         Compressor, Reciprocatir           Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421817         2520-01-463-9188         Axle Assembly 2           Meritor         12421816         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-5267         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4509         Axle Assembly 2           Meritor         483-49-048-322         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly <td< td=""><td></td><td>12417383-003</td><td>4820-01-370-0133</td><td>Valve, Angle</td></td<>		12417383-003	4820-01-370-0133	Valve, Angle
Dana Spicer         12418057         4820-01-372-2769         Valve, Regulating           Haldex         12414366-001         4730-01-361-2173         Air Drier and Cooler           Haldex         12378830-001         2530-01-361-5075         Compressor, Reciprocatir           Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421817         2520-01-463-9188         Axle Assembly 2           Meritor         12421816         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-5267         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-478-7594         Drive Shaft Assembly 2           Meritor         483-49-048-322         2520-01-472-4495         Drive Shaft Assembly 2           Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly 2           Meritor         483-49-050-356         2520-01-472-4494         Drive Shaft Assembly 2 <tr< td=""><td></td><td>12378688</td><td>2530-01-360-6198</td><td>Valve, Brake, Pneumatic</td></tr<>		12378688	2530-01-360-6198	Valve, Brake, Pneumatic
Haldex         12414366-001         4730-01-361-2173         Air Drier and Cooler           Haldex         12378830-001         2530-01-361-5075         Compressor, Reciprocatin           Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421816         2520-01-463-9188         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-5267         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-5267         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-472-4496         Axle Assembly 2           Meritor         483-49-048-322         2520-01-478-7594         Drive Shaft Assembly 2           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly 2           Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly 2           Meritor         483-49-050-356         2520-01-472-4494         Drive Shaft Assembly 2           Meritor         483-49-050-356         2520-01-472-4494         Drive Shaft Assembly 2	Dana Spicer	12418057	4820-01-372-2769	
Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421817         2520-01-463-9188         Axle Assembly 2           Meritor         12421816         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-5267         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4570         Axle Assembly 2           Meritor         483-49-048-322         2520-01-478-7594         Drive Shaft Assembly 2           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly 2           Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly 2           Meritor         483-49-050-335         2520-01-472-4494         Drive Shaft Assembly 2           Meritor         483-49-050-356         2520-01-472-4496         Drive Shaft Assembly 2           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly 2           Meritor         483-94-002-167         2530-01-368-9501         Pump Assembly 2 <tr< td=""><td>Haldex</td><td>12414366-001</td><td>4730-01-361-2173</td><td>Air Drier and Cooler</td></tr<>	Haldex	12414366-001	4730-01-361-2173	Air Drier and Cooler
Holland         MS51117-1         2540-00-047-3926         Pintle Assembly           Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421817         2520-01-463-9188         Axle Assembly 2           Meritor         12421816         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-5267         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4570         Axle Assembly 2           Meritor         483-49-048-322         2520-01-478-7594         Drive Shaft Assembly 2           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly 2           Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly 2           Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly 2           Meritor         483-49-050-356         2520-01-472-4496         Drive Shaft Assembly 2           Meritor         483-94-002-167         2520-01-472-4496         Drive Shaft Assembly 2           Meritor         483-94-002-167         2520-01-376-3699         Pump Assembly 2 <tr< td=""><td>Haldex</td><td>12378830-001</td><td>2530-01-361-5075</td><td>Compressor, Reciprocating</td></tr<>	Haldex	12378830-001	2530-01-361-5075	Compressor, Reciprocating
Kysor Cooling         12421971         2930-01-331-6660         Clutch, Fan           Meritor         12421817         2520-01-463-9188         Axle Assembly 2           Meritor         12421816         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-5267         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4570         Axle Assembly 2           Meritor         483-49-048-322         2520-01-478-7594         Drive Shaft Assembly 2           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly 2           Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly 2           Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly 2           Meritor         483-49-050-356         2520-01-472-4496         Drive Shaft Assembly 2           Meritor         483-94-002-167         2520-01-472-4497         Drive Shaft Assembly 2           Meritor         483-94-002-167         2520-01-376-369-501         Pump Assembly 2           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Rotary 2	Holland	MS51117-1	2540-00-047-3926	-
Meritor         12421817         2520-01-463-9188         Axle Assembly 2           Meritor         12421816         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-5267         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-478-7594         Drive Shaft Assembly 2           Meritor         483-49-048-322         2520-01-478-7594         Drive Shaft Assembly 2           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly 2           Meritor         483-49-050-256         2520-01-472-4495         Drive Shaft Assembly 2           Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly 2           Meritor         483-49-050-356         2520-01-472-4497         Drive Shaft Assembly 2           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly 2           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly 2           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly 2           Meritor         482-94-002-167         2520-01-472-4498         Drive Sh	Kysor Cooling	12421971	2930-01-331-6660	
Meritor         12421816         2520-01-464-4568         Axle Assembly 2           Meritor         RP-15611-NFSF-14         2520-01-464-5267         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4570         Axle Assembly 2           Meritor         483-49-048-322         2520-01-478-7594         Drive Shaft Assembly           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly           Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly           Meritor         483-49-050-356         2520-01-472-4497         Drive Shaft Assembly           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly           Meritor         12422207         -         ECU, ABS           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmissic           Sprague		12421817	2520-01-463-9188	
Meritor         RP-15611-NFSF-14         2520-01-464-5267         Axle Assembly 2           Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4570         Axle Assembly 2           Meritor         483-49-048-322         2520-01-478-7594         Drive Shaft Assembly           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly           Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly           Meritor         483-49-050-356         2520-01-472-4497         Drive Shaft Assembly           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly           Meritor         12422207         -         ECU, ABS           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Assembly, Power           Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmissic           Sprague         12417493-002         2540-01-376-3676         Control, Directional           St	Meritor	12421816	2520-01-464-4568	
Meritor         RP-15611-NFSF-16-780         2520-01-464-4569         Axle Assembly 2           Meritor         RP-15611-NFSF-18-780         2520-01-464-4570         Axle Assembly 2           Meritor         483-49-048-322         2520-01-478-7594         Drive Shaft Assembly           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly           Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly           Meritor         483-49-050-356         2520-01-472-4497         Drive Shaft Assembly           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly           Meritor         12422207         -         ECU, ABS           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Assembly, Power           Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmissic           Sprague         12417597         6220-01-376-3676         Control, Directional           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr	Meritor	RP-15611-NFSF-14	2520-01-464-5267	
Meritor         RP-15611-NFSF-18-780         2520-01-464-4570         Axle Assembly 2           Meritor         483-49-048-322         2520-01-478-7594         Drive Shaft Assembly           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly           Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly           Meritor         483-49-050-356         2520-01-472-4497         Drive Shaft Assembly           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly           Meritor         12422207         -         ECU, ABS           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Assembly, Power           Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmission           Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12				Axle Assembly <sup>2</sup>
Meritor         483-49-048-322         2520-01-478-7594         Drive Shaft Assembly           Meritor         483-49-050-210         2520-01-472-4495         Drive Shaft Assembly           Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly           Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly           Meritor         483-49-050-356         2520-01-472-4497         Drive Shaft Assembly           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly           Meritor         12422207         -         ECU, ABS           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Assembly, Power           Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmission           Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12417493-002         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-001         2540-01-376-3998         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         124		RP-15611-NFSF-18-780		
Meritor         483-49-050-256         2520-01-472-4494         Drive Shaft Assembly           Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly           Meritor         483-49-050-356         2520-01-472-4497         Drive Shaft Assembly           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly           Meritor         12422207         -         ECU, ABS           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Assembly, Power           Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmission           Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12414349         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Meritor	483-49-048-322	2520-01-478-7594	-
Meritor         483-49-050-335         2520-01-472-4496         Drive Shaft Assembly           Meritor         483-49-050-356         2520-01-472-4497         Drive Shaft Assembly           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly           Meritor         12422207         -         ECU, ABS           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Assembly, Power           Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmission           Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12414349         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Meritor	483-49-050-210	2520-01-472-4495	Drive Shaft Assembly
Meritor         483-49-050-356         2520-01-472-4497         Drive Shaft Assembly           Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly           Meritor         12422207         -         ECU, ABS           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Assembly, Power           Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmission           Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12414349         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Meritor	483-49-050-256	2520-01-472-4494	Drive Shaft Assembly
Meritor         483-94-002-167         2520-01-472-4498         Drive Shaft Assembly           Meritor         12422207         -         ECU, ABS           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Assembly, Power           Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmission           Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12414349         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Meritor	483-49-050-335	2520-01-472-4496	Drive Shaft Assembly
Meritor         12422207         -         ECU, ABS           Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Assembly, Power           Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmission           Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12414349         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Meritor	483-49-050-356	2520-01-472-4497	Drive Shaft Assembly
Sauer Sundstrand         12414372-001         2530-01-368-9501         Pump Assembly, Power           Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmission           Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12414349         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Meritor	483-94-002-167	2520-01-472-4498	Drive Shaft Assembly
Sauer Sundstrand         12414359         4320-01-363-2294         Pump, Rotary           Serck         12422174         -         Cooler, Fluid, Transmission           Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12414349         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Meritor	12422207	-	ECU, ABS
Serck         12422174         -         Cooler, Fluid, Transmission           Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12414349         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Sauer Sundstrand	12414372-001	2530-01-368-9501	Pump Assembly, Power
Sprague         12417597         6220-01-376-3676         Control, Directional           Sprague         12414349         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Sauer Sundstrand	12414359	4320-01-363-2294	Pump, Rotary
Sprague         12414349         2540-01-361-5201         Motor, Windshield Wiper           Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Serck	12422174	-	Cooler, Fluid, Transmission
Steyr         12417493-002         2540-01-376-3998         Handle, Door           Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Sprague	12417597	6220-01-376-3676	Control, Directional
Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Sprague	12414349	2540-01-361-5201	Motor, Windshield Wiper
Steyr         12417493-001         2540-01-376-3999         Handle, Door           Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel	Steyr	12417493-002	2540-01-376-3998	Handle, Door
Steyr         12417511         2430-01-377-6614         Housing, Steering           Steyr         12417884         2530-01-378-6001         Steering Wheel		12417493-001	2540-01-376-3999	Handle, Door
		12417511	2430-01-377-6614	Housing, Steering
	Steyr	12417884	2530-01-378-6001	Steering Wheel
		12418168	2510-01-420-9972	Support, Cab Assembly
Tex-A-Draulics 12421800 4820-01-470-5581 Valve, Thermal Bypass			4820-01-470-5581	
			2540-01-470-6026	Pedal, Control, Accelerator

<sup>&</sup>lt;sup>2</sup> Applies to down parts of axle assemblies only, not the complete axle assembly.

**b.** Coverage. This is a replacement part warranty only. Labor is not included. In the case of axles, this warranty only provides for replacement down parts of the axle assembly. Fair wear and tear items are not included

**a.** Warranty Period. The warranty period for all items listed in Table 2. S&S Extended Summary Section is 16 months and begins with shipment of the vehicle for purposes of fielding.

- c. Procedure. Unit will submit a DA Form 2407 to their WARCO for submittal to TVSLP for warranty consideration. Upon claim approval, TVSLP will ship replacement parts to their Field Service Representative. The Field Service Representative will exchange the replacement part for the defective part with the WARCO. OCONUS requirements (excluding Alaska and Hawaii) will be shipped to a Government provided APO. If the part is too heavy for APO shipment, the unit and WARCO must provide a CONUS Port of Embarkation and make arrangements for shipment from that CONUS Port. Installations not represented by a Field Service Representative will be provided replacement parts through their WARCO. The WARCO will be responsible for returning defective supplies to TVSLP using the replacement part/container.
- 6. Exhaust Brake Solenoid (Vehicles S/N 11438 17413. P/N 12421985-001, NSN 5945-01-480-0484). Warranty period for exhaust brake solenoid on above listed vehicles is forty-eight (48) months from DD250 date. If exhaust brake fails to exhaust, remove exhaust brake from vehicle and check butterfly for damage. If butterfly is damaged, request brake kit P/N C10374. Kit comes with installation instructions. Both parts, the solenoid and brake kit, will be shipped to field location directly from Pac Brake.
- 7. Radiator (Vehicles S/N 11438 21,728. P/N 12378882-005, NSN 2930-01-363-8145). Warranty period for radiator on above listed vehicles is thirty-six (36) months from DD250 date. Radiator is warranted if it has poor fin-tube bonding, tank to header joint seam leaks, or outlet/inlet tube to header joint seam leaks. Follow the instructions in paragraphs 3B and 5c, S&S Extended Warranties.
- Secondary Battery Box Latch (Vehicles S/N ranges: 16307 16431, 16446 16710, 16759 16948, 16995 17211, 17264 17432, 17477 17689, 17739 17891, 17955 18101, 18117 18320, 18376 18514. P/N 12420089, NSN 6160-01-442-9783). Warranty period for secondary battery box latch on above vehicles is thirty-six (36) months from shipment of vehicle. If plastic latch breaks, replacement latch kit and installation instructions will be shipped to repair battery box. Follow the instructions in paragraphs 3b and 5c, S&S Extended Warranties.

9. Ohio Casting Produced Parts (Vehicle S/N range 21604 – 25268). Warranty Period for Ohio Casting produced parts installed in above listed vehicles is fifty-four (54) months from DD250 date. Follow the instructions in paragraphs 3b and 5c, S&S Extended Warranties. Part numbers applying to Medium Tactical Vehicles (MTV) include:

Gov't P/N	<u>NSN</u>	<u>Description</u>
12414306	2590-01-443-2208	Bracket, Alternator
12414277	2530-01-369-4933	Supp Link, Rear Axle
12417307	2530-01-377-6617	Bracket, Steering
12417393	5340-01-371-1077	Plate, Spring Clamp
12417394	5340-01-369-1399	Plate, Spring Clamp
12417397	2510-01-369-4785	Supp, Shock-Rear
Left		
12417399	2510-01-443-3325	Supp, Shock-Rear
Right		
12417404	2510-01-377-3206	Bracket, Stabilizer
Bar		
12417407	2510-01-370-2726	Bracket Spring, Front
12417408	2510-01-370-2725	Supp, Shock-Fwd
Right		
12417411	2510-01-387-8469	Bracket, Stiffener
12417412	2510-01-370-4791	Supp, Shock-Fwd
Left		
12417413	2510-01-370-4792	Supp, V-Rod
Forward		
12417417	2510-01-370-4793	Supp, V-Rod Rear

- 10. Intermediate Input Seal (Vehicle S/N range 11438 20216. P/N A-1205-D-2500, NSN 5330-01-432-2689). Arvin Meritor will warrant leaking intermediate input seals on above vehicles for a period of three (3) years beginning 8 April 2003. Upon receipt of the information in paragraph 3.b, S&S will forward claim information to Arvin Meritor who will provide replacement parts and labor to complete the repair. This warranty is contingent upon not using the Central Tire Inflation System (CTIS) when outside temperature drops below 0F (-18C). When temperatures are below 0F (-18C) the CTIS switch must be in the "OFF" position and circuit breaker number forty (40) must be removed by maintenance personnel.
- 11. Contractor Responsibilities. The Pass-Through Warranties are provided by vendors in Table 1. Supplier Summary Section, but will be administered by TVSLP through your local WARCO. S&S Extended Warranties in Table 2. S&S Extended Summary Section are provided by TVSLP through your local WARCO. To obtain services for Pass-Through or S&S Extended Warranties, your local

WARCO simply contacts TVSLP through their website at <a href="https://www.tvsonlinesupport.com">www.tvsonlinesupport.com</a>, or at 1-800-221-3688, asks for the Warranty Department, and provides the information in paragraph 3.b.

12. Government Responsibilities. The Major Subordinate Command for the M1083A1 Series, 5 Ton, 6X6, Medium Tactical Vehicles (MTV) is the U.S. Army Tank-automotive and Armaments Command (TACOM), Warren, MI 48397-5000. TACOM is responsible for managing and implementing the warranty. Warranty claims will be reported to:

Commander

U.S. Army Tank-automotive and Armaments

Command

ATTN: AMSTA-AC-NML Rock Island, IL 61299-7630

Email: tacom-tech-pubs@ria.army.mil

Fax: DSN 793-0726

Commercial: (309) 782-0726

#### a. TACOM will:

- (a) Verify, review, process and if valid and complete, submit claims (reimbursable and/or disputes) to the Contractor.
- (b) Reject claims that are not valid and send them back to the local WARCO with a short explanation of why the claim is rejected.
- (c) Request additional information for incomplete claims.
- (d) Provide warranty claim acknowledgment/ closeout letters and/or parts/assemblies disposition instructions to the local WARCO.
- (e) Ensure the Contractor performs in accordance with the terms of the contract.

#### b. Equipment owning unit will:

- (a) Identify defects/failures and verify that the defects/failures are warrantable.
- (b) Submit warranty claims, using DA Form 2407 and DA Form 2407-1 Maintenance Request Claims through channels to the supporting repair facility.

(c) Tag and retain parts, pieces of parts and/or assemblies removed at the owning unit level and as a result of a warrantable defect/ failure and/or correction, in accordance with DA PAM 738-750 The Army Maintenance Management System (TAMMS) and this Technical Bulletin.

## c. Supporting repair facility will:

- (a) Identify defects/failures as warrantable (if owning unit has not already identified them). Verify defects/failures are warrantable.
- (b) Review, process and submit valid warranty claims to the local WARCO if the DA Form 2407 and DA Form 2407-1 are complete and correctly filled out.
- (c) Reject invalid warranty claims or request additional information for incomplete and incorrect claims.
- (d) Coordinate with the owning unit and decide which option for repair is desired to correct the warrantable defect/failure.
- (e) Depending upon which repair option was selected (Government or contract repair), provide labor/parts required to accomplish the warrantable repairs.
- (f) Tag and retain (in accordance with DA PAM 738-750 The Army Maintenance Management System (TAMMS) and this Technical Bulletin) all parts, pieces or parts and/or assemblies removed as a result of warrantable defect/failure and/or correction.

#### d. Local WARCO will:

- (a) Verify, administer, and process warranty claims to the TACOM WARCO (in accordance with DA PAM 738-750 The Army Maintenance Management System (TAMMS) and this Technical Bulletin).
- (b) Act as a liaison with the owning unit, the Contractor, supporting repair facility, and TACOM.
- (c) Notify the owning units of all warranty claim acknowledgments/closeouts, information and/or instructions received from TACOM or the Contractor.

- (d) Act as a liaison between local dealers and the Army.
- **e. Alterations/Modifications.** Alterations/ modifications shall not be applied unless authorized by TACOM.
- **f.** Lubrication and Service. The manufacturer's lubrication and service intervals must be followed at all times.

#### 13. Claim Procedures.

- **a.** The procedures for reporting warranty claims are found in DA PAM 738-750 The Army Maintenance Management System (TAMMS) and this Technical Bulletin. Responsibilities of the Major Army Command (MACOM) are found in AR 700-139 Army Warranty Program, Concepts and Policies. Units should use DA Form 2407 and DA Form 2407-1 for making warranty claims. It is very important to fill in the blocks on the forms as accurately as possible.
- b. The Contractor shall be notified in writing via their website (www.tvsonlinesupport.com), or electronic mail (tvswarranty@ssss.com) utilizing DA Form 2407 by the local WARCO following the discovery of a defect in supplies which requires Contractor/vendor repair and/or replacement parts. This shall constitute formal notification of a warranty claim. The notification shall include, but not be limited to furnishing the equipment serial number, operating hours, part number or NSN of the defective part and circumstances surrounding the defect(s). Upon completion of Contractor/vendor repair, forward completed warranty claims (Information Only) to TACOM.
- c. Identification of Failed Items. Failed warranty items shall be tagged/identified to prevent improper repair or use. Documents that describe the use of DA Form 2402 Exchange Tag and DA Form 2407 Maintenance Request shall be referenced. Items requiring special handling, storage or shipment during the processing of claims shall be identified.
- **d. Disposition.** The repair activity shall return defective supplies to the Contractor's representative or ship them back at their expense using the replacement part carton/container.

- e. Invalid Warranty Claims. When supplies are inspected by the Contractor/vendor and found to be non-warrantable, or the supplies are found to be serviceable, the repair activity submitting the claim will be required to make reimbursement for Contractor/vendor services. Additionally, regarding Contractor/vendor repair, the local WARCO must stipulate at the time of request for services that either non-warranty work be stopped at the time it is determined non-warrantable or be prepared to pay for completion of such work. In either case, the WARCO must be prepared to pay for diagnosis and trip charges for non-warranty service.
- **f. Air Force Warranty Claims.** Air Force warranty claims shall be submitted as follows:
  - (1) For letter warranty claims:

WR-ALC/LVR 225 Ocmulgee CT Robbins AFB, GA 31098-1647 DSN 468-7161 COML (912) 926-7126

(2) For Teletype warranty claims:

WR-ALC ROBBINS AFB GA//LVR

- 14. Reimbursement for Army Repair. The Contractor shall reimburse the Government by submitting monies quarterly to United States Army Tank-automotive and Armaments Command, ATTN: SFAE-CSS-TV-M (PM, MTV Office), Warren, Michigan 48397-5000. All checks will be made payable to the "Treasurer of the United States". In the event that the repair activity should receive any reimbursement from the Contractor, the monies must be forwarded to the above address.
- **15. Claim Denials/Disputes.** TACOM will handle all denials or disputes.
- 16. Reporting. Reporting or recording action on a failed item shall be as specified in DA PAM 738-750 The Army Maintenance Management System (TAMMS). Forms that are unique to the Contractor or Repair Activity shall not be used.

## 17. Storage/Shipment/Handling.

a. Storage. Not applicable.

- **b. Shipment.** See paragraphs 5.c, 12.b, 12.c, 13.c, and 13.b.
- **c. Handling.** See paragraphs 5.c, 12.b, 12.c, 13.c, and 13.b.

#### **SECTION II**

FMTV A1's Serial Numbers 100001 Through 199999 Contract Number DAAE07-03-C-S023 (See Section I for FMTV A1's Serial Numbers up to 099999)

- **1. General.** This Section provides information and implementation instructions for the Warranty on the FMTVA1, serial numbers 100001 through 199999, manufactured under contract DAAE07-03-C-S023. It contains instructions for obtaining services and/or supplies covered under warranty. This Section also describes methods of processing warranty claims. For additional information on the FMTV or any U.S. Army Tank-automotive and Armaments Command (TACOM) equipment. contact your local Warranty Control Office/Officer (WARCO) or TACOM Logistics Assistance Representative (LAR). If your WARCO or TACOM LAR is not available or if additional information is required, contact TACOM. The number to call is DSN 786-8081. COMMERCIAL (810) 574-8081. The caller should be prepared to provide: (1) name, (2) DSN and commercial telephone numbers, (3) complete unit designation, (4) identification of the vehicle, to include the serial number(s), (5) a brief description of the problem, (6) the contract number (see paragraph 3), and (7) operating hours or miles on the equipment.
- 2. Explanation of Terms.
  - **a. Abuse.** The improper use, maintenance, repair, or handling of warranted items that may cause the warranty of those items to become void, for example, not following service intervals, using the vehicle for other than what is intended.
  - **b. Acceptance.** The execution of the Acceptance Block and signing of DD Form 250, by the authorized Government representative.
  - **c.** Acceptance Date. The date an item of equipment is accepted into the Army's inventory by the execution of the Acceptance Block and

- signing of a DD Form 250 or, in case of Material and Workmanship Warranty, date of hand off as evidenced by the user's hand receipt or property book. Pass-Through Warranties may be different.
- **d. Contractor.** The supplier of equipment who enters into an agreement directly with the Government to furnish supplies.
- **e.** Correction. The elimination of a defect.
- **f. Defect.** Any condition or characteristic in supplies furnished by the Contractor that does not function as intended.
- **g. Pass-Through Warranty.** A vendor's (e.g., Caterpillar) commercial warranty that provides warranty coverage.
- **h. Failure.** A part, component, or end item that fails to perform its intended use.
- **i. Owning Unit.** The Army Unit authorized to operate, maintain, and use the equipment.
- **j.** Reimbursement. A written provision in this warranty in which the Using/Support Unit requests replacement parts from the Contractor to make the necessary repairs, and the Government will be reimbursed for the labor required to correct or repair the end item.
- **k. Repair.** A maintenance action required to restore an item to serviceable condition without affecting the warranty.
- **I. Supplies.** All assemblies, subassemblies, and down parts to the lowest level that comprise an end item.

- **m. WARCO.** Serves as the intermediary between the troops owning the equipment and the local dealer, Contractor, or manufacturer. All warranty claim actions will be processed through the WARCO.
- **n. Warranty.** A written agreement between the Contractor and the Government which outlines the rights and obligations of both parties for defective supplies.
- **o. Warranty Claim.** Action started by the equipment user for authorized warranty repair or reimbursement.
- p. Warranty Expiration Date. The date the warranty is no longer valid. This date will vary depending on each vendor's Pass-Through Warranty. The Material and Workmanship Warranty expires 24 months after the Government Acceptance Date. Ohio Cast parts described in paragraph 6 expire 60 months from the DD250 date.
- **q. Warranty Period.** Time during which the warranty is in effect. Normally measured as the maximum number of years, months, days, miles, or hours used.
- **r.** Warranty Start Date. The date the warranty is put into effect.
- **3. Coverages-Specific.** The FMTVA1R, serial numbers 100001 through 199999, have Material and Workmanship and Pass-Through Warranties, which are Vendor's (Allison, Caterpillar, Michelin) Commercial Warranties, as well as Ohio Casing warranty described in paragraph 6, that are administered by Stewart & Stevenson Tactical Vehicle Systems, LP (TVSLP). The items identified in Table 1. Supplier Summary Section are items which have Pass-Through Warranties available. The terms, durations, warranty start dates, etc., vary greatly between the Vendors. For example, some Vendor's Warranties begin when the item is manufactured, while others begin when the end item ships from TVSLP. Regardless of Pass-Through Warranties, all items may be warranted by TVSLP under the 24 month Material and Workmanship Warranty which covers parts and labor for claims having a total value of \$300.00 or more. Ohio Casting warranty, described in paragraph 6, begins with

DD250 date. To find out if a Pass-Through Warranty for an item listed in Table 1. Supplier Summary Section, the Material and Workmanship Warranty, or Ohio Casting warranty, described in paragraph 6 are still in effect, simply contact your local WARCO. Your local WARCO can inquiry TVSLP's website (www.tvsonlinesupport.com) or contact TVSLP at 1-800-221-3688, and ask for the Warranty Department. The Warranty Department will need the information in paragraph 3.b. to determine if the warranty is still in effect. This Technical Bulletin, Section II, applies to the vehicles listed. The items are manufactured by Stewart & Stevenson Tactical Vehicle Systems, LP (TVSLP) under contract number DAAE07-03-C-S023. Inquiries to TVSLP can be made by calling 1-800-221-3688 or visiting their website at www.tvsonlinesupport.com. These are the M1083A1 series models and the National Stock Numbers (NSN) for each:

- TRUCK, CARGO, MTV, M1083A1; w/o wn 2320-01-447-3890, w/wn 2320-01-447-3884
- TRUCK, CARGO, MTV, W/MHE, M1084A1; 2320-01-447-3887
- TRUCK, CARGO, MTV, LONG WHEELBASE, M1085A1; w/o wn 2320-01-447-3891, w/wn 2320-01-447-3897
- TRUCK, CARGO, MTV, LONG WHEELBASE, W/MHE, M1086A1; 2320-01-447-3895
- TRUCK, VAN EXPANSIBLE, M1087A1; w/o wn 2320-01-459-0362
- TRUCK, TRACTOR, MTV, M1088A1; w/o wn 2320-01-447-3893, w/wn 2320-01-447-3900
- TRUCK, WRECKER, MTV, M1089A1; 2320-01-447-3892
- TRUCK, DUMP, MTV, M1090A1; w/o wn 2320-01-447-3899, w/wn 2320-01-447-6344

- TRUCK, CHASSIS, MTV, M1092A1; 2320-01-447-3894
- TRUCK, CHASSIS, MTV, LONG WHEELBASE, M1096A1: 2320-01-447-3885
- **a. Defects.** If a defect/failure is caused by (or falls within) any of the following categories, it is not considered warrantable and a claim should not be initiated:
  - i. Misuse or negligence
  - ii. Accidents
  - iii. Improper operation
  - iv. Improper storage
  - v. Improper transport
  - vi. Improper or insufficient maintenance service
  - vii. Improper alterations or repair
  - viii. Defect/failure discovered or occurring after warranty expiration date
  - ix. Fair wear and tear items (brake shoes, CTIS seals, pads, armatures, brushes, etc)
  - x. Foreign object damage
  - xi. Improper packing or handling
  - xii. Combat damage
  - xiii. Consequential damages resulting from a defect or failure
  - xiv. Failure of parts/components resulting in less than \$300.00 cost, labor and parts (Not applicable to Pass-Through Warranties)
- b. Pass-Through, Material and Workmanship, and Ohio Casting **Warranties**. Pass-Through Warranties are provided by the vendors in Table 1. Supplier Summary Section, but will be administered by TVSLP through your local WARCO. Material and Workmanship Warranties and Ohio Casting warranty as described in paragraph 6 are supplied by TVSLP through your local WARCO. To obtain services for Pass-Through, Material and Workmanship, or Ohio Casting Warranties, your local WARCO contacts TVSLP through their website (www.tvsonlinesupport.com) or calls 1-800-221-3688, asks for the Warranty Department, and provides the following information:

- i. Customer work order number
- ii. Customer complete address
- iii. Vehicle serial number
- iv. Vehicle mileage
- v. Defective component part number
- vi. Manufacturer cage code
- vii. Defective component National Stock Number
- viii. Description of the defect including codes from the electronic boxes
- ix. Component serial number or date code, if available
- x. Quantity
- xi. Person to contact on the request for warranty, to include: telephone, fax number and shipping address. This information can be sent by your local WARCO to TVSLP's website (www.tvsonlinesupport.com) or electronic mail (tvswarranty@ssss.com).

## c. Warranty Start Dates.

- i. Information to determine Pass-Through Warranty start dates for Allison, Caterpillar, and Michelin are listed later in this Bulletin. Material and Workmanship Warranties start at hand off as evidenced by the user's hand receipt or property book and expire 24 months later. Ohio Casting warranty described in paragraph 6 starts at DD250 and expires 60 months later.
- ii. For Pass-Through, Material and Workmanship, or Ohio Casting Warranty, your local WARCO contacts TVSLP through their website (www.tvsonlinesupport.com) or calls 1-800-221-3688, asks for the Warranty Department, and provides the information in paragraph 3.b. TVSLP will obtain the warranty start date and notify the Government if the warranty period has expired.
- 4. Material and Workmanship Warranties.
  - **a. Warranty Period**. The warranty period for the Material and Workmanship Warranty is 24

months and begins with hand off to the unit as evidenced by the unit's hand receipt or property book.

- **b. Coverage.** The Material and Workmanship Warranty covers the complete vehicle, parts and labor, excluding those items identified in paragraph 3.a. No warranty claims will be
- submitted for less than \$300.00 total value, parts and labor.
- **c. Procedure.** The unit will submit a DA Form 2407 or DA Form 5504 to their local WARCO for submittal to TVSLP for warranty consideration. Upon claim approval, TVSLP will begin appropriate repair action as identified by the warranty claim.
- 5. Pass-Through Warranties. FMTV A1's serial numbers 100001 through 199999

VENDOR	VENDOR PART NO	NSN	DESCRIPTION
Allison	ECB007AW		ECU
Allison	29538371	-	Shift Selector
Allison	12378396-009		Transmission, Hydraulic
Caterpillar	212-4284		Camshaft Assembly
Caterpillar	7E6794	2815-01-360-4450	Camshaft Followers
Caterpillar	12422551-002	-	Electronic Control Module
Caterpillar	209-2395	-	Engine, Diesel <sup>1</sup>
Caterpillar	222-5962		Fuel Injector
Caterpillar	229-9769	-	Intake Manifold Gasket
Caterpillar	192-0953	-	Turbo Compressor Housing
Caterpillar	223-9087	-	Turbo Turbine Housing
Caternillar	224-4859	_	Turbocharger Cartridge

2610-01-356-9098

Tire, Pneumatic

**Table 1. Supplier Summary Section** 

#### a. Allison

Michelin

1. Warranty Period. The warranty start date is 90 days from the date indicated in Block 3 of the DD Form 250 and expires 24 months from that date, unless the vehicle is placed in service prior to the 90 days. When placed into service prior to the 90 days, then the actual inservice date becomes the warranty start date. It does not cover accident damage, misuse, alterations, or damage due to lack of maintenance, use of fluids not recommended, normal maintenance such as filters, screens, and fluids, repairs by unauthorized dealers, and use of other than Allison transmission parts. This warranty includes the transmission, ECU and shift selector.

12378858

**2. Coverage.** Repairs or replacement, at Allison's option, to correct any transmission malfunction resulting from defects in material and workmanship during the warranty period. All repairs will be performed using the method

- Allison determines most appropriate under the circumstances. Labor costs for the removal and reinstallation of the transmission are covered when necessary to make a repair. An authorized Allison Distributor must perform all warranty repairs.
- **3. Towing.** Reasonable towing (i.e., motor pool to Dealer, hazard free area, etc.) to the nearest Allison Distributor or authorized Dealer is covered only when necessary to prevent further transmission damage. Field service is provided under this warranty. If the vehicle can be driven, at Allison's request, they may require the vehicle be delivered to the nearest authorized repair center within a reasonable amount of time. A reasonable amount of time must be allowed for the repair center to perform repairs.

Engine for Dressed Engine 12414398-005, NSN 2815-01-467-8471.

**4. Procedure.** Unit will submit a DA Form 2407 or DA Form 5504 to their WARCO for submittal to TVSLP for warranty consideration.

#### b. Caterpillar

- 1. Warranty Period. The warranty period is 36 months or 150,000 miles and begins with shipment of the vehicle from TVSLP. This is a worldwide warranty to U.S. military FMTV trucks. In addition, Caterpillar provides the 60 month, 100,000 mile emissions warranty for vehicles operating in the United States. Both warranties cover genuine Caterpillar components only; this is not a dressed engine warranty. Accident damage, misuse, alterations, or damage due to lack of maintenance, use of fluids not recommended. normal maintenance such as filters, screens, and fluids, repairs by unauthorized dealers. and use of other than Caterpillar engine parts are not covered by this warranty
- 2. Coverage. Repair or replacement, at Caterpillar's option, to correct any engine malfunction resulting from defects in material and workmanship during the warranty period. All repairs will be performed using the method Caterpillar determines most appropriate under the circumstances. Labor costs for the removal and reinstallation of the engine are covered when necessary to make a repair. An authorized Caterpillar Dealer must perform all warranty repairs. The engine must remain in the vehicle and all historical ECM codes must be made available to Caterpillar.
- **3. Towing.** The user must deliver the vehicle to the nearest Caterpillar Dealer. If the vehicle is not in driving condition, as determined by Caterpillar, Caterpillar will pay for reasonable towing (i.e., motor pool to Dealer, hazard free area, etc.) for the first 12 months of the warranty period.
- **4. Procedure.** Unit will submit a DA Form 2407 or DA Form 5504 to their WARCO for submittal to TVSLP for warranty consideration.
- **5. Emissions Warranty Parts Covered.**Camshaft Assembly, Electronic Control Module (ECM), Fuel Injectors, Intake Manifold Gasket, Turbocharger. (See Table 1. Supplier Summary Section for part numbers.)

#### c. Michelin

- 1. Warranty Period. The warranty is 5 years from the date of tire manufacture, or the life of the original usable tread down to 2/32nds of an inch of tread remaining. The date of manufacture is determined from the "DOT" number on the lower side above the bead. It will end in "X" and 4 numerics. The numerics represent the week and year of manufacture (i.e., "4804" = 48<sup>th</sup> week of 2004)
- 2. Coverage. The user must pay for the cost of a new tire on a pro-rata basis calculated by multiplying the current negotiated TACOM replacement price or the Government Open Market price, whichever is applicable, by the percentage of usable tread. This warranty does not include any mounting, balancing or other charges.
- 3. Procedure. Unit will submit a DA Form 2407 or DA Form 5504 to their WARCO for warranty consideration. During the first 2 years of vehicle warranty, the WARCO will address all claims to TVSLP under the Material and Workmanship Warranty. Upon expiration of the Material and Workmanship Warranty, the WARCO will address all claims to the Michelin Government Sales Department at webtruck@us.michelin.com.
- 6. Ohio Casting Produced Parts (Vehicle S/N Range 100001 100050). Warranty Period for Ohio Casting produced parts installed in above listed vehicles is sixty (60) months from DD250 date. Follow the instructions in paragraphs 3.b. to submit a claim for these components. When the cost of the part and labor combined is \$300.00 or more total value, follow paragraph 4. Material and Workmanship Warranty. If the vehicle is outside of the Material and Workmanship Warranty, TVSLP will provide replacement material to complete Government repair. Part numbers applying to Medium Tactical Vehicles (MTV) include:

Go	v't P/N	<u>NSN</u>	<u>Description</u>
12	414306	2590-01-443-2208	Bracket, Alternator
12	414277	2530-01-369-4933	Supp Link, Rear
Ax	le		
		2530-01-377-6617	
12	417393	5340-01-371-1077	Plate, Spring Clamp

12417394 5340-01-369-1399 Plate, Spring Clamp 12417397 2510-01-369-4785 Supp, Shock-Rear Left 12417399 2510-01-443-3325 Supp, Shock-Rear Right 12417404 2510-01-377-3206 Bracket, Stabilizer Bar 12417407 2510-01-370-2726 Bracket Spring, Front 12417408 2510-01-370-2725 Supp, Shock-Fwd Right 12417411 2510-01-387-8469 Bracket, Stiffener 12417412 2510-01-370-4791 Supp, Shock-Fwd Left 12417413 2510-01-370-4792 Supp, V-Rod Forward 12417417 2510-01-370-4793 Supp, V-Rod Rear

## 7. Contractor Responsibilities.

- a. Government Correction. When the owning unit has elected to perform corrective action, the Contractor will ship all replacement parts required to affect correction within 3 calendar days of notification. If the Contractor is unable to meet the 3 calendar days, the repair site will be notified of any delay and the anticipated ship date. CONUS requirements, including Alaska and Hawaii, will be shipped to the repair location. OCONUS requirements will be shipped to a Government provided APO or CONUS Port of Embarkation. The Contractor shall reimburse the Government for the cost of labor involved in Government correction. Labor will be calculated at the current fiscal years labor rate for the maintenance level identified in the Maintenance Allocation Chart (MAC) multiplied by the actual number of labor hours incurred, not to exceed the labor hours in the MAC. The Government will notify the Contractor in writing via DA Form 2407 for the reimbursement required.
- **b. Contractor Correction.** When the owning unit has directed the Contractor to correct the Supplies, the Contractor will furnish all material required to correct the defective supplies. The Contractor will complete repairs on site or at an approved repair facility, and will maintain an overall repair time equal to 5 calendar days or less from the notification date.
- c. Defective Parts. The Contractor has the right to inspect parts found to be defective and will be allowed to take possession of failed parts following their replacement. All freight charges for the return of defective/failed parts are the responsibility of the Contractor.
- 8. Government Responsibilities. The Major Subordinate Command for the M1083A1 Series, 5 Ton, 6X6, Medium Tactical Vehicles (MTV) is the U.S. Army Tank-automotive and Armaments Command (TACOM), Warren, MI 48397-5000. TACOM is responsible for

managing and implementing the warranty. Warranty claims will be reported to:

Commander

U.S. Army Tank-automotive and Armaments Command

ATTN: AMSTA-AC-NML Rock Island, IL 61299-7630

Email: tacom-tech—pubs@ria.army.mil

Fax: DSN 793-0726

Commercial: (309) 782-0726

#### a. TACOM will:

- **a.** Verify, review, process and if valid and complete, submit claims (reimbursable and /or disputes) to the Contractor.
- **b.** Reject claims that are not valid and send them back to the local WARCO with a short explanation of why the claim is rejected.
- **c.** Request additional information for incomplete claims.
- **d.** Provide warranty claim acknowledgement/closeout letters and/or parts/assemblies disposition instructions to the local WARCO.
- **e.** Ensure the Contractor performs in accordance with the terms of the contract.

#### b. Equipment owning unit will:

- **a.** Identify defects/failures and verify that the defects/failures are warrantable.
- **b.** Submit warranty claims, using DA Form 2407 and DA Form 2407-1 or DA Form 5504 Maintenance Request through channels to the supporting repair facility.
- **c.** Tag and retain, pieces of parts and/or assemblies removed at the owning unit level and as a result of a warrantable defect/failure and/or correction, in accordance with DA PAM 738-750 The Army Maintenance Management System (TAMMS) and this Technical Bulletin.

#### c. Supporting repair facility will:

**a.** Identify defects/failures as warrantable (if owning unit has not already identified them). Verify defects/failures are warrantable.

- **b.** Review, process, and submit valid warranty claims to the local WARCO if the Maintenance Request is complete and correctly filled out.
- **c.** Reject invalid warranty claims or request additional information for incomplete and incorrect claims.
- **d.** Coordinate with the owning unit and decide which option for repair is desired to correct the warrantable defect/failure.
- **e.** Depending upon which repair option was selected (Government or Contractor repair), provide labor and Contractor furnished parts to accomplish the warrantable repairs.
- **f.** Tag and retain (in accordance with DA PAM 738-750 The Army Maintenance Management System (TAMMS) and this Technical Bulletin) all parts, pieces or parts and/or assemblies removed as a result of warrantable defect/failure and/or correction.

#### d. Local WARCO will:

- **a.** Verify, administer, and process warranty claims to the TACOM WARCO (in accordance with DA PAM 738-750 The Army Maintenance Management System (TAMMS) and this Technical Bulletin).
- **b.** Act as a liaison with the owning unit, the Contractor, supporting repair facility, and TACOM.
- **c.** Notify the owning units of all warranty claim acknowledgements/closeouts, information and/or instructions received from TACOM or the Contractor.
- **d.** Act as a liaison between local dealers and the Army.

#### e. Alterations/Modifications.

Alterations/modifications shall not be applied unless authorized by TACOM.

**f. Lubrication and Service.** The manufacturer's lubrication and service intervals must be followed at all times.

#### 9. Claim Procedures.

a. The procedures for reporting warranty claims are found in DA PAM 738-750 The Army Maintenance Management System (TAMMS) and this Technical Bulletin. Responsibilities of the Major Army Command (MACOM) are found in AR 700-139 Army Warranty Program, Concepts and Policies. Units should use DA Form 2407 or DA Form 5504 for making warranty claims. It is very important to fill in the blocks on the forms as accurately as possible.

The Contractor may be notified in writing via their website, (www.tvsonlinesupport.com), electronic mail (tvswarranty@ssss.com), or telephonically (1-800-221-3688), followed up in writing by DA Form 2407 or DA Form 5504 from the local WARCO following the discovery of a defect in supplies which requires Contractor/Vendor repair and/or replacement parts. This shall constitute formal notification of a warranty claim. The notification shall include all items identified in paragraph 3.b of this Technical Bulletin. At this time, the Contractor will further be informed whether the owning unit has elected: (1) to correct the defect themselves or: (2) to direct the Contractor to correct the defect. Upon completion of Contractor/Vendor repair, forward completed warranty claims (Information Only) to TACOM. Additionally, the local WARCO will forward claims to TACOM utilizing DA Form 2407 or DA Form 5504 for any warrantable repairs accomplished by the owning unit which requires Contractor reimbursement to the Government.

**c.** The Contractor shall reimburse the Government for the cost of labor involved in the Government correction of a defect. The cost of labor involved will be computed at the current Fiscal Years labor rate for the maintenance level identified in the Maintenance Allocation Chart (MAC) multiplied by the number of actual hours incurred, not to exceed the labor hours in the MAC. The Contractor shall ship replacement parts for Government correction in accordance with paragraph 7.a.

- d. Identification of Failed Items. Failed warranty items shall be tagged/identified to prevent improper repair or use and must identify the vehicle number and mileage from the vehicle which they were removed. Documents that describe the use of DA Form 2402 Exchange Tag and DA Form 2407 Maintenance Request shall be referenced. Items requiring special handling, storage or shipment during the processing of claims shall be identified.
- **e. Disposition.** The repair activity shall return defective supplies to the Contractor's representative or ship them back at the Contractor's expense using the replacement part carton/container.
- f. Invalid Warranty Claims. When supplies are inspected by the Contractor/Vendor and found to be non-warrantable, or the supplies are found to be serviceable, the repair activity submitting the claim will be required to make reimbursement for Contractor/Vendor services. Additionally, regarding Contractor/Vendor repair, the local WARCO must stipulate at the time of request for services that either non-warranty work be stopped at the time it is determined non-warrantable or be prepared to pay for completion of such work. In either case, the WARCO must be prepared to pay for diagnosis and trip charges for non-warranty service.
- **g. Air Force Warranty Claims.** Air Force warranty claims shall be submitted as follows:
  - (1) For letter warranty claims:

WR-ALC/LVR 225 Ocmulgee Ct Robbins AFB, GA 31098-1647 DSN 468-7161 COML (912) 926-7126

(2) For teletype warranty claims:

WR-ALC ROBBINS AFB GS/LVR

10. Reimbursement for Army Repair. The Contractor shall remit payment by the fifteenth (15) day of the month for all warrantable claims by the Government for reimbursement which were received by the Contractor in the previous month. Payment shall be sent to the PM, MTV, Attn: Business Management Office, with checks made payable to

- "The Treasurer of the United States". In the event that the repair activity should receive any reimbursement from the Contractor, the monies must be forwarded to the PM, MTV.
- **11. Claim Denials/Disputes.** TACOM will handle all denials or disputes.
- 12. Reporting. Reporting or recording action on a failed item shall be as specified in DA PAM 738-750 The Army Maintenance Management System (TAMMS). Forms that are unique to the Contractor or Repair Activity shall not be used.

#### 13. Storage/Shipment/Handling.

- **a. Storage.** See paragraphs 2.c, 3.a, 3.c, 5.a and TM Care and Storage Requirements for the Vehicle, Refer to TM 9-2320-392-20.
- **b. Shipment.** See paragraphs 3.a, 7.a, 7.c, 8.b, 8.c, 9.d, and 9.e.
- **c. Handling.** See paragraphs 3.a, 7.a, 7.c, 8.b, 8.c, 9.d, and 9.e.

By Order of the Secretary of the Army:

PETER J. SCHOOMAKER General, United States Army Chief of Staff

Official:

SANDRA R. RILEY
Administrative Assistant to the
Secretary of the Army
0501308

By Order of the Secretary of the Air Force:

JOHN P. JUMPER General, United States Air Force Chief of Staff

Official:

GREGORY S. MARTIN General, United States Air Force Commander, Air Force Materiel Command

Distribution:

To be distributed in accordance with the initial distribution number (IDN) 381088, requirements for TB 9-2300-427-15.

## RECOMMENDED CHANGES TO PUBLICATIONS AND BLANK FORMS

For use of this form, see AR 25-30; the proponent agency is OAASA

Use Part II (reverse) for Repair Parts and Special Tool Lists (RPSTL) and Supply Catalogs/Supply Manuals (SC/SM).

DATE

Date you filled out this form

TO: (Forward to proponent of publication or form) (Include ZIP Code)

FROM: (Activity and location) (Include ZIP Code)

Enter your mailing address

	X	•	ART I - A	ALL PUBLI	CATIONS	S (EXCEPT RPSTL AND SC/SM) AND BLANK FORMS
UBLICA	TION/FORM			••••••		DATE TITLE
					1 3 Card	Publication Date Publication Title
		Sali La	tion in			Tubication lite
ITEM	PAGE	PARA- GRAPH	LINE	FIGURE NO.	TABLE	RECOMMENDED CHANGES AND REASON
10	15-33	15-7	,	4	ndjetja ku j	Item 10. Change Illustration. Reason: Text calls out 90-degree fitting. Art shows straight fitting. Text is correct.
	19-6	19-2				Step (4) of removal says to disconnect four hydraulic hoses from manifold. The correct number of hydraulic hoses is five correct the text to reflect the actual quantity of hydraulic
	: SK44					hoses. The supporting illustration is correct.
X :						
				4, O41		
44.13 15						
PED N	AME, GRAD	E OR TITI		eference	Y	umbers within the paragraph or subparagraph. HONE EXCHANGE/AUTOVON, SIGNATURE
					PLUS EX	XTENSION SIGNATIONS
	You	ur title			You	ur telephone number Your signature

TO: <i>(Fo</i>	rward dir	rect to edu	dressee listed in publicati	ion) FRON	A: (Activity	and loc	ation) (Include Z	IP Code)	DATE
					Enter	your r	mailing addre	<b>:ss</b>	Date you filled out this form.
		PAR'	T II - REPAIR PARTS AND	D SPECIAL TO	OL LISTS A	ND SUP	PLY CATALOGS	S/SUPPLY MAI	NUALS
PUBLIC/	ATION NU			DATE			TITLE		
* .4518 .4				Ru	ublication	Date		Your Title	
PAGE NO.	COLM NO.	LINE NO.	NATIONAL STOCK NUMBER	REFERENCE NO.	E FIGURE NO:	ITEM NO.	TOTAL NO. OF MAJOR ITEMS SUPPORTED	REC	OMMENDED ACTION
	1000								
			M		Marian San San San San San San San San San S				
		Parkering and State of the Stat		1//	N	har i			
					14				
					K				
	Par	OT III . REI	MARKS (Any general rem						
			blank forms. Add	ditional blank s	theets may	be used	if more space is	needed.)	Ubucamina anu
	Alberta Language Language Language Language Language Language	in the section of the							
TYPED N	and transletting	RADE OR 1	me J	TELEPHONE EX PLUS EXTENSIO				and the second	
	Yo	our title		Your tel	lephone n	ıumber	ř l	Y	our signature

RECO	RECOMMENDED CHANGES TO PUBLICATION BLANK FORMS				CATION	S AND	Special Too	ol Lists	ee) for Repair Parts and (RPSTL) and Supply Manuals (SC/SM).	DATE
	For use of this	s form, see AR	25-30; the p	proponent ag	jency is OAA	SA				
TO: (For	ward to prop	ponent of p	oublication	n or form)	) (Include .	ZIP Code)	FROM: (A	ctivity a	and location) (Include ZIP	Code)
PUBLICA	TION/FORM			LL PUBLI	CATIONS	DATE	PSTL AND S	SC/SM) TITLE	AND BLANK FORMS	
ITEM	PAGE	PARA- GRAPH	LINE	FIGURE NO.	TABLE		RE	COMMI	ENDED CHANGES AND R	EASON
			I							
			l							
			I							
			l							
			l							
			l							
			l							
			l							
			l							
			l							
			l							
			l							
			l							
			I							
			l							
			l							
			l							
			I							
			I							
			l							
		<u>_</u>	* <i>F</i>	Reference	to line nu	mbers with	in the paragi	raph or	subparagraph.	<u> </u>
TYPED N	iame, grad	DE OR TITL	.E		TELEPH PLUS E	IONE EXCH XTENSION	ANGE/AUTO	OVON,	SIGNATURE	

TO: (For	ward dir	ect to add	dressee listed in publica	FROM: (Activity and location) (Include ZIP Code)  DATE										
	PART II - REPAIR PARTS AND SPECIAL TOOL LISTS AND SUPPLY CATALOGS/SUPPLY MANUALS													
PUBLICATION NUMBER DATE TITLE														
PAGE NO.	COLM NO.	LINE NO.	NATIONAL STOCK NUMBER	REFERENCE NO.				FIGURE NO.	ITEM NO.	OF M	AL NO. MAJOR EMS PORTED	RECO	OMMENDED ACTION	
	PAF	RT III - REI									oublications and			
			blank forms. A	dditional	blank sh	eets may l	be used	if more	space is	needed.)				
PART III - REMARKS (Any general remarks or recommendations, or suggestions for improvement of publications and blank forms. Additional blank sheets may be used if more space is needed.)														
TYPED N	AME, G	RADE OR	TITLE	TELEPH( PLUS E)	ONE EXC (TENSIO	CHANGE/A IN	UTOVO	N,	SIGNAT	URE				

PIN: 077747-000