

E. B. Bigelow. Loom.

Nº 169.

Palented Apr. 20, 1837.






E. B. Bigelow. Loom.

Nº 169.


Patented Apr. 20,1837.



E. B. Bigelow. Loom.

Nº 169.

Patented Apr. 20,1837.



UNITED STATES PATENT OFFICE.

ERASTUS B. BIGELOW, OF WEST BOYLSTON, MASSACHUSETTS.

POWER-LOOM FOR WEAVING COACH-LACE AND OTHER SIMILAR FABRICS.

Specification forming part of Letters Patent No. 169, dated April 20, 1837; Reissued September 26, 1846, No. 87.

To all whom it may concern:

Be it known that I, Erastus Brigham BIGELOW, of West Boylston, in the county of Worcester and State of Massachusetts, have invented new and useful improvements in looms to weave coach-lace and such other similar wrought fabrics as may be woven by the said machinery, which improvements combined are denominated "Boylston's 10 Power Coach-Lace Loom," and that the following description, with the drawings annexed thereto, compose my specification of the said improvements, as invented by me.

These improvements consist in construct-15 ing, combining, and applying to use, certain mechanical contrivances in such a manner as to perform the entire operation of weaving coach-lace, &c., by water, steam, or other

rotary power.

Figure 1, is a front elevation of the loom. Fig. 2, is a profile elevation of the right end of the loom. Fig. 3, shows the driving parts of the loom on the left end. Fig. 4, is a horizontal view of the cams and treadles, with 25 the upper part of the loom removed. Fig. 5, is a sectional view of the figuring works, detached from the machine. Fig. 6, is a horizontal view, of the parts of the loom, forward of the shuttle boxes. Fig. 7, rep-30 resents the stop motion. Fig. 8, is a side view of the pliers or forceps, with one standard removed. Fig. 9, is a front view of the apparatus to shift the wires, detached from the machine. Fig. 10, is a back view of the apparatus to push the wires toward the pliers or forceps. Fig. 11, represents the shuttle and bobbin. Fig. 12, represents the temples or cloth guides.

The same letters refer to the same parts 40 when they occur in any of the figures.

a, a, a, are four upright posts, which are connected together, by horizontal rails b, b, b, b. c, c, are two other upright posts resting on the cross rails b, b. f, f, f, f, are cross horizontal rails for connecting the ends of the framework.

The warp beam g, containing the linen or ground warp, and the warp beam h containing the worsted or that warp which is raised 50 above the ground warp to conceal the weft, are mounted on axles turning in bearings attached to the framework.

The bobbins i i i contain the figuring warp and are supported by the creel j. From n', is affixed, which takes into the teeth of these beams and bobbins, the warp threads the cogged wheel o', and revolves the cylin-

pass over their respective whip-rollers k, l, m, thence through the raddle n, headles o, o, and p, p, and reed q, in the ordinary way. r is a weight suspended by a friction cord passing around the warp-beam h, to 60 keep the warp at a proper degree of tension. The weights s, s, s, s, in the same manner preserve the tension of the figuring warp.

The cloth produced by the intervention of the warp and weft threads in front of the 65 reed, passes over the roller t, turning in bearings in the breast beam u, and is wound upon the cloth roller v. w, is a lever turning on the stud of the ratchet wheel, x, with the clicks y, y, jointed to its short arm. 70 These clicks act on, and turn the ratchet wheel x, when the lever w, is moved by the cam c'. The pinion gear z on the side of the ratchet wheel x takes into the teeth of the cogged wheel a', affixed to the axle of 75 the cloth roller v. b', b', are clicks playing on a stud attached to the post a, (being hid in the drawing behind the post a) which act on the teeth of the ratchet wheel x, to secure the lace that has been wound up, when the 80 clicks y, y, release their hold to act on other teeth.

The pulley or rigger d' receives its motion from the mill work, by the belt e' and moves the loom when the clutch f' connects it with 85 the pinion gear g'. This pinion takes into the cogged wheel h' affixed to the main axle i'. The axle i' is arranged horizontally across the loom, and turns in the bearings j', j'. This axle, by means of an endless 90 screw, and cams or wipers attached thereto, gives the principal motions of all the operations performed by the machine. The first of these operations to be described, is the giving out of the linen warp as fast as it is 95 filled by the weft; second, that which raises and depresses the warp, to receive the shuttle; third, regulating the variations in the pattern or figure; fourth, driving the shut-tle to and fro; fifth, beating up the weft; 100 sixth, shifting the wires over which the figure is wrought.

The linen or ground warp, is given out as follows: The worm or endless screw k'. is affixed to the end of the shaft i', and takes 105 into the teeth of the cogged wheel l', on the end of the axle m'. To the reverse end of the axle m', another worm or endless screw

der p', on its axle in the bearings r', r'. The axle m', turns in bearings q', q', at-

tached to the frame-work.

The diameter of the cylinder p', and the number of teeth of the cogged wheels l', o', are so proportioned, as to move the disk or circumference of the cylinder p', at each throw of the shuttle, through a space equal to the length of the linen warp filled by the 10 thread of the weft, thus introduced.

The upper extremities of the wires s', s', hook on to the ends of the axle of the warpbeam g, and are connected at their lowerextremities by the cross-bar t'. The weight 15 w', is suspended from the lever v', resting on the cross-bar t', and presses the warp on the warp beam g, against the disk of the cylinder p', thus causing the beam g to turn with the cylinder p', and deliver a certain length of warp at each revolution of the cylinder, however much the diameter of the warp around the beam may vary.

The whip-roller l over which the linen warp passes, turns in bearings in the arms 25 r^7 , r^7 , extending from the axle s^7 which turns in the bearings t^7 , t^7 . u^7 is an arm extending from the axle s^7 , from which the weight v^7 , is suspended; which weight serves to tighten the warp, and at the same 30 time allow the whip-roller l, to move forward and prevent too great tension of the warp when the heddles are raised to form

the sheds.

The raising and depressing of the warp to The raising and depressing of the warp to receive the shuttle are effected as follows: The cams or wipers w', w', W', are affixed to the axle i', and act on the levers or treadles y', y', Y', which play on the fulcra x', x', X'. The straps or cords z', z', Z', 40 connect the treadles y, y', Y', to the arms a^2 , a^2 , A^2 , Fig. 5, extending from the axles b^2 , b^2 . B², which turn in the bearings b^2 , b^2 , B^2 , which turn in the bearings c^2 , c^2 , C^2 . d^2 , d^2 , D^2 , are arms extending from the reverse sides of the axles b^2 , b^2 , B^2 , 45 from which the heddles o, o, O are suspended by the cords e^2 , e^2 , E^2 . f^2 , f^2 , F^2 , are weights connected to the bottom of heddles o, o, O.

As the shaft i, revolves the eccentric parts of the cams come around at proper inter-50 vals, and force down the treadles y', y', Y', which by means of the cords z', z', Z', turns the axles b^2 , b^2 , B^2 , raises the heddles and forms the sheds of the warp. When the cams relieve their action on their respective 55 treadles, the headles are again depressed by

the weights f^2 , f^2 , F^2 .

The two leaves of heddles o, o, are sufficient to weave laces with plain grounds, or fabrics, but in weaving those laces in which 60 certain of the warp threads are overlaid, the third leaf O is required, which leaf being raised relatively at such distant intervals of time, require a graduated motion of the cam which moves it. This is effected as fol-55 lows;—the cogged wheel g^2 , Fig. 4, affixed to

the axle i', takes into the teeth of the largest part of the pinion wheel, h^2 , which turns on the stud i^2 attached to the frame-work. The teeth of the small part of the cogged pinion h^2 , takes into the teeth of the cogged wheel j^2 , affixed to the cam W' which revolves loose on the shaft i'. The number of teeth of these cogged wheels may be so calculated as to give different degrees of relative motion to the cam W', according to the number 75 of threads of the weft, overlaid by the warp;—thus when the warp overlays three threads of the weft, two revolutions of the axle i' will be required to one of the cam.

The third operation or that which regu- 80 lates the variations in the pattern or figure, is next described. l^2 , l^2 , are upright post or side-pieces (see Fig. 5), which are connected together by the cross bars, or rails m^2 , n^2 , o^2 . When this part is connected with 35 the main frame-work, the ends of the crossbars n^2 , o^2 , rest on the horizontal rails b, b, and are bolted or otherwise affixed thereto. p^2 , p^2 , p^2 , are horizontal wires, sliding with a reciprocatory motion in holes through the 90 plates of iron q^2 , r^2 , s^2 , which are screwed to the cross rails n^2 , o^2 : Between the plates of iron r^2 , s^2 , a spiral spring is encircled around each horizontal wire p^2 , p^2 , one end of which is attached thereto by the pin 95 t^2 , inserted in the wire, the other abuts against the plate of iron r^2 . This spring yields to any gentle pressure, made on that extremity projecting beyond the plate of iron s^2 , and returns again when that pres- 100 sure is removed till the pin t^2 strikes against the plate s^2 . Eyes are formed in the central parts of these horizontal wires, through which the vertical wires u^2 , u^2 , pass. The wires u^2 , u^2 , are hooked at the upper ex- 105 tremity and arranged vertically over the lifting bar. In the lower extremities of the vertical wires, eyes are formed, to which the cords v^2 v^2 are attached. From these eyes the cords v^2 , v^2 , pass through the guide 110 holes in the cross-pieces w^2 , w^2 , to the heddles p, p, suspended therefrom.

 x^2 , x^2 , are weights attached to the heddles p, p, to depress them after they have been raised by the lifting-bar, and preserve 115 their tension during the operation of the other parts of the loom. The lifting bar y^2 has a vertical reciprocating motion in the guides r^2 , r^2 , which are attached to the side-pieces of the frame t^2 , t^2 . The wires a^3 , a^3 , 120 connect the lifting bar y^2 , to the arms b^3 , b^3 , extending from the axle c^3 .

 d^3 , is the reverse arm of the axle c^3 , to which is attached the upper extremity of the cord e^3 , Fig. 2 which connects it with 125 the treadle f^3 , Fig. 4. The lifting-bar y^2 , Fig. 5 is raised by the cam g^3 acting on the treadle f^3 , Fig. 4 and when the cam relieves its action thereon, it falls again by its own gravity.

130

169

It is evident from what has been described that when the lifting bar y^2 is raised it will carry up with it all the vertical wires u^2 , u^2 , and heddles connected with 5 them, and no variation will be produced in the pattern or figure; but, if before we raise the lifting bar, we push back certain of the horizontal wires p^2 , p^2 , p^2 , and thus withdraw the vertical wires connected with them, 10 from its action, it will carry up with it, those vertical wires and heddles only, the horizontal wires of which have not been pushed back, and a corresponding variation will be produced in the pattern or figure.

The apparatus to push back certain of the horizontal wires is thus described. The cylinder h^3 , is mounted on an axle turning in bearings in the frame l^3 , which oscillates on the axis j^3 . In the circumference of this 20 cylinder as many longitudinal rows of holes are formed, directly opposite to the ends of the horizontal wires p^2 , p^2 , p^2 , as there are variations to be made in the pattern or figure.

The number and position of the holes in each row, are varied according to the variation to be made in the figure; that is, holes are bored in any one of the rows, opposite to the ends of those horizontal wires only, 30 which connect with the heddles required to be raised when the said row swings against

the horizontal wires.

The ratchet wheel k^3 Fig. 2 having as many teeth as there are longitudinal rows 35 of holes in the cylinder h^3 , is attached to the axel of the said cylinder, and is acted on by the click l3, which (being concealed in the drawing behind the horizontal rail b) is attached to the framework. m^3 Fig. 1, is an-40 other ratchet wheel, which has as many teeth and is affixed to the axle like the former, and is acted on by the spring n^3 , attached to the frame i^3 Fig. 5.

The bars o^3 , o^3 , connect the frame t^3 , with 45 the arms p^3 , p^3 , extending from the axle q. From the reverse side of this axle another arm r^3 , extends which is connected with the treadle s^3 , Fig. 4 by the cord t^3 , Fig. 2. u^3 , is a spring one extremity of which is attached to the arm r^3 , the other to the framework. v^3 is a cam or wiper attached to the axle i^1 . This apparatus operates as follows: The cam v^3 forces down the treadle s^3 ,

and turns the axle q^3 , which being connected with the frame i^3 , carries the cylinder away from the horizontal wires.

As the cylinder is thus moved back, one tooth of the ratchet wheel k^3 , strikes against the click 13, which overcomes the elastic force of the spring n^3 , and turns the cylinder on its axis the distance of one tooth of the ratchet wheel, or in other words, the distance between the centers of any two rows of holes in its circumference; at this instant the spring n^3 , takes into a new space 1 of the ratchet wheel m^3 , and secures the cylinder in its proper position.

When the cam \hat{v}^3 , relieves its action on the treadle s^3 , the spring u^3 , raises the arm r3, and forces the cylinder against the wires, 70 and pushes back those which have no holes opposite to them in the cylinder, while, those wires which have corresponding holes in the cylinder, enter therein, and remain at rest, with the hooked wires connected 75 with them over the lifting-bar.

The cylinder thus presenting a new row of holes, and swinging against the ends of the horizontal wires, and pushing certain of the hooked wires, from the action of the 80 lifting-bar every time it is raised, produces variations in the pattern, or figure corresponding with the variations of the holes in its circumference.

The fourth operation is that which drives 85 the shuttle to and fro, and may be understood as follows. The shuttle boxes w^3 w^3 Fig. 6 are affixed to the posts c, c, at a suitable distance to allow the rod to pass between them; x^3 , x^3 , are picker-rods; y^3 , y^3 , y^3 , represent the shuttle binders; z^3 , z^3 , Fig. 1 are openings or mortices in the front side of the shuttle boxes, to receive the guide wire of the shuttle.

The pickers a^4 , a^4 , Fig. 6 slide on the rods 95 x^3 , x^3 , with their lower extremities playing in mortices b^4 , b^4 , in the bottom of the boxes; c^4 , c^4 , Fig. 2 are picker-strings connecting the pickers a^4 , a^4 , to the pickerstaff d^4 , which is affixed to the pulley e^4 , Fig. 1. This pulley turns on a stud attached to the cross-bar f^4 . The strap g^4 passing over the pulley connects it to the treadle h^4 , h^4 . i^4 , i^4 , are cam-bolts attached to the cams on the main axle i^1 , and as they re- 105 volve with the said axle force down the treadle h^4 , h^4 , alternately, and by means of the strap g^4 , vibrates the picker-staff and throws the shuttle to and fro.

The weft is beat up as follows:—the lay 110 is mounted on an axle turning in bearings j^4 , j^4 Fig. 2, attached to the framework; k^4 , k^4 , are the swords of the lag; l^4 is the top shell, which receives and supports the upper edge of the rod.

The bars of iron m^4 , m^4 are affixed to the top shell and extend downward to the lower shell of the lay n^4 , and supports the lower edge of the rod. o^4 o^4 are straps with one extremity of each attached to the top 120 shell of the lag t^4 , the other end of each to the framework. The upright arm p^4 , extending from the axle of the lag, is connected by the cord q^4 , to the lever r^4 , which is attached to the pulley s^4 . The pulley s^4 , is 125 suspended between the posts a, a, by the cord t^4 , passing through the holes u^4 , u^4 , in the pulley, and the holes v^4 , v^4 , in the posts a, a. The pulley is turned to twist the cord, which offers a degree of resistance in pro- 13v

portion to the tension of the twist, and serves to bring forward the lag to beat up the west. The cord w^4 , attached to the lag, passes from them over the pulley y^4 , to the treadle y^4 . The cam z^4 on the main axle i^1 , forces down the treadle y^4 , which by means of the cord w^4 , draws back the lag, and increases the tension of the cord t, which cord, as the cam relieves its action on the 10 treadle, throws the lag forward and beats up the weft. The degree of motion given to the lag by the cord t^4 is determined by the straps o^4 , o^4 .

We now come to the sixth operation, or 15 that which shifts the wires over which the

figure is wrought.

a⁵, is a frame similar in form to an inverted T (see Fig. 10.) which is mounted on an axis turning in the bearings b^5 , b^5 , on an axis turning in the bearings b, b, f ig. 2. c^5 , Fig. 10 is a cam turning on the bearings b^5 , b^5 , Fig. 2. c^5 , Fig. 10 is a cam turning on the stud d^5 , affixed to the frame a^5 , with the studs e^5 , f^5 , extending from one of its sides. The stud g^5 , extending from the 25 frame a^5 determines the quantity of motion of the cam in the direction toward it.

The spring h^5 attached to the frame a^5 always tends to move the cam toward the stud g^5 . The bar i^5 is made flat and point-80 ed at the upper extremity and has a vertical reciprocating motion in the guide j^5 j^5 . The lever k⁵ has a groove at its upper extremity in that edge which presents toward the wires l^5 , l^5 , l^5 , and turns on the fulcrum m^5 35 attached to the frame a^5 . n^5 represents the guide iron attached to the upper extremity of the frame a^5 . o^5 , Fig. 2 represents a spring inserted between the frame a^5 and the breast beam u. This spring presses the **40** guide iron n^5 against the last of the series of wires l^5 , l^5 , l^5 , Fig. 9, or that one which is to be acted on and thus keeps the frame a^5 in the same position relative to the said wire, that is the one to be acted on, although 45 the position of the succeeding wires themselves as they successively approach this situation (being successively drawn out and placed under a new portion of the figuring

warp) may at different times vary. A frame formed similar to a lay turns on an axis in the bearings p^5 , p^5 , Fig. 2, affixed to the posts a, $a-g^5$ g^5 (see Fig. 9.) are the swords the tops of which rest against the frame v^5 . x^5 is the cross rail to connect 55 the swords together. An arm s⁵, Fig. 4, is attached to this frame on which the cam t^5 acts to move it. Fig. 5, u^5 , u^5 , represents v^5 atached to the frame-work of the machine, on which the frame v^5 , slides with a

60 horizontal reciprocating motion. spiral spring attached at one extremity to the frame v^5 at the other to the breast

The bar x^5 , Fig. 9, slides in the standard 65 on the frame v^5 with a transverse recipro-

cating motion. y^5 represents a stop attached to the bar x^5 , which determines the quantity of approach of the pliers toward the wires l^5 , l^5 , l^5 . z^5 represents a piece of iron called the evener bolted to the bar x^5 . To the bar 70 x^5 the geared pliers are affixed as represented in Fig. 8. a^6 , a^6 are standards screwed or otherwise affixed to the bar x^5 (one of which is removed in this figure) which support the axis of the blades of the pliers b^6 c^6 .

Teeth are formed on these blades at the point of contact at their centers of motion which take into each other similar to the action of two cogged wheels, so that raising and depressing the long part of the blade $b^{\mathfrak{g}}$ 80 opens and closes the pliers. d^6 represents a spring, which is attached to the bar x^5 and tends to raise the long part of the blade b^6 and open the pliers. The latch e^6 vibrates on the stud f^6 attached to the bar x^5 and is 85 acted on by the spring g^6 . The spiral spring h^6 , Fig. 6, is affixed at one extremity to the bar x^5 at the other to the frame v^5 . i^6 , Fig. 9, represents an elbow playing on the stud with its upright arm resting against a 90 stud u⁶ extending from the bar w⁵. The hook k^6 attached to the upright part of the elbow, acts on the stud e^5 and moves the cam c^5 .

The wire 16, connects the horizontal part 95 of the elbow with the treadle m⁶ the projection of which is acted on by the cam n^c , Fig. 4, affixed to the axle i^1 . The spring o^c , Fig. 9, being attached at one extremity to the horizontal part of the elbow io, at the 100 other to the frame v^5 , serves to counteract

the weights of the treadle m^6 .

The latching wire $p^{\mathfrak{c}}$, Fig. 1, is hooked at the upper extremity and connected at its lower extremity to the treadle q6, Fig. 4, 105 which is acted on by the cam ball r^6 playing on the stud s^{c} , attached to the cam u^{c} . The standard t^6 , Fig. 9, attached to the v, u^5 serves to release the latch e from the blade of the pliers $b^{\mathfrak{g}}$.

Considering the position which the pliers or pincers assume after having deposited a wire under the figuring warp and returned again to a line with the wire next to be taken by them and parallel with the breast- 115 beam, as the point of commencement, we shall describe the movements of the machin-

ery specified under this operation.

The main axle i^1 turning, the notch of the cam n^6 comes around and suffers the spring 120 o^5 to raise the treadle m^6 , and horizontal part of the elbow i⁶, which motion of the elbow carries its upright part away from the stud u^{c} and allows the spring h^{c} , Fig. 6, to move the pliers toward the wires l^{c} l^{c} until the stop 125 y^5 meets the standard of the frame v^5 and prevents its farther approach. As the upright part of the elbow is thus moved back the hook k^6 , Fig. 9, acts on the stud e^5 and moves the cam c^5 toward the spring h^5 , Fig. 130

169

10. This movement of the cam raises the bar i⁵ and forces the point of it between the last of the series of wires l^5 l^5 or that one against which the guide iron n^5 rests and the one 5 next in order from it, and separates one from the other and thus prevents more than one being acted upon at the same time.

When the bar i^5 has arrived at its greatest elevation the stud f^5 strikes against the lower arm of the lever k^5 and forces the grooved side of the reverse arm against the end of the wire 15 operated as above described and forces it toward the pliers or forceps into the position seen in Fig. 9; at this instant the cam ball r^{0} , Fig. 4, acts on the treadle g^6 and depresses the latching wire p^6 which forces down the longer part of the blade bo closes the jaws of the pliers or forceps and pinches the wire tight be-

20 tween them. As the longer part of the blade b⁶ is thus depressed the shoulder of the latch c^6 locks onto its extremity and secures the grasp of the pliers on the wire after the action of the 25 cam ball r^6 is released from the treadle m^6 depresses the horizontal part of the elbow i^0 and slides the bar x^5 in the standard of the frame v5, which movement of the bar draws out the wire grasped by the pliers, 30 from under the figure wrought over it and moves them into the position seen in Fig. 6. This motion of the elbow i⁶ relieves the action of the hook k^{6} from the stud e^{5} , Fig. 10, and allows the spring h^5 to move the cam c^5 35 back against the stud g^5 , which movement of the said cam suffers the bar is to fall and causes the stud f^5 to move the lever k^5 into the positions in which they are respectively seen in Figs. 6 and 10 and in which they are prepared to act on the succeeding wires. At the proper interval the cam t5, Fig. 4, acts on the arms s^5 and slides the frame v^5 , Fig. 6 on the v^5 u^5 u^5 , and carries the pliers connected with the frame v^5 back toward 45 the suttle boxes to the proper position to place the wire under the figuring warp, at the instant they arrive at their destination another notch in the cam n^6 suffers the spring o^6 to carry the upright part of the 50 elbow i6 away from the stud u6 which movement of the said elbow allows the spring h6, Fig. 6, to draw the pliers up and place the wire they grasp under the figuring warp; just as the pliers complete their mo-55 tion in this direction the latch c^6 strikes against the standard f^{6} which releases it from the blades b^{6} and suffers the spring d⁶ to open the jaws of the pliers and drop the wire. At this instant the cam n⁶, Fig. 4, again acts on the treadle m6 and carries the pliers back a short distance to prevent their coming in contact with the wires l^5 , l^5 , Fig.

9, as they return toward the breast bream; when this part of the cam has completed

suffers the spring w^5 , Fig. 2, to draw the frame v^5 , Fig. 9, back to a line with the next wire to be acted on, or in other words the position it assumed when we began to describe the operation. When the wires 70 drop from the pliers they are not all in the same position—that is some are placed under the figuring warp farther than others, therefore to even them and prevent any failure in the operation of shifting them, 75 which might occur from their irregularity, the evener 25, as the pliers approach the warp to deposit the wire, strikes against the wire last deposited and drives it in as far as it is suffered to do, by the motion of the bar x^5 ; the wire deposited by this operation of the pliers, is driven in, in the same manner as the other—when the pliers come up to place in the next succeeding wire; all the wires being thus driven are left in an uni- 85 form position.

I do not deem it necessary to recapitulate the movements of this machine in their order of succession, as this will be apparent to every competent machinist, and the periods of the different parts of the process being nearly the same as in ordinary coach-lace looms. The pliers are armed with a wire while the weft is being inserted between the warp, and are prepared to move 95 back simultaneously with the lay at the proper interval and place it under the figuring warp.

The rest v^6 , Fig. 6, is attached to the breast beam and arranged over the lace, to 100 prevent the lace back of the breast-beam from rising up and thus carrying the wires l^5 , l^5 , away from the pliers when the warp is raised to form the sheds. w^6 represents the standard of the temples (see Fig. 12) 105 which is screwed to the inside of the breastbeam and under the cloth. x^6 , x^6 , are the guides of the temples which are fastened to the stand w^6 by the screw y^6 y^6 . The cloth passes between the guides x^6 x^6 and is thus 110 prevented from yielding when the wires l^5 $ar{l}^5$ are drawn out or pushed in.

The loom is put in motion and thrown out of gear as follows: The lever z6, Fig. 1. turns on the stud a^7 and connects the clutch 115 f^{τ} with the shifting bar b^{τ} which slides in the guides c^7 , c^7 , Fig. 1. The dotted lines at d, Fig. 7, represent a spring embedded in the bar b^{τ} . The spiral spring e^{τ} is attached at one extremity to the bar b^{τ} at the other 120 to the breast-beam u. The lever f^{τ} turns on the stud s^7 , Fig. 6, attached to the breast-beam. h^7 , Fig. 2, is a latch which vibrates on a stud attached to the post a, and has a handle at its upper extremity which the 125 weaver grasps to stop the loom. The spring j⁷, Fig. 7, being attached at one end to the latch h^{τ} at the other to the breast-beam always tends to bring the latch h^{r} toward 65 its action, the notch of the cam t^5 , Fig. 4 the lever f^7 .

180

grasps the handle k^{τ} and moves the bar b^{τ} toward the right which movement of the bar moves the clutch f' Fig. 4 and connects the cogged wheel g' with the pulley a' at this instant the spring d^7 locks on the depending arm of the lever f^7 and secures the connection.

6

To stop the loom the weaver releases the clutch h^7 and suffers the spring c^7 Fig. 6 to move the bar b^{τ} and throw the loom out of gear. In the event of the weft being exhausted, on the bobbin in the shuttle, and also in case the shuttle does not arrive at 15 its destination, it is desirable that the loom should be thrown out of gear, to prevent an imperfect place being made in the lace. Stopping the loom when the shuttle stops in its passage to and fro is effected as follows;—The protecting rod l^{r} Fig. 6 turns in the bearings on the v⁵ u⁵, u⁵, and has the arms m^7 m^7 , extending from it, the upper extremities of which rest against the shuttle binders y^3 , y^3 , Fig. 1.— n^7 represents a spring which acts on the arm m^7 and urges both the arms m^7 , m^7 , against their respective binders y^3 , y^3 ,— o^7 , Fig. 2, is the reverse arm extending from the rod l^7 and supports the bar p^{τ} , which connects with the latch h^{τ} by means of an elbow and connecting rod which are hid in the drawing under the breast-beam.

When the shuttle enters the box properly it pushes out the binder y^3 and depresses the bar p^7 and causes it to escape the lower shell of the lay as it comes forward to beat up the weft:-but in the event the shuttle does not enter the box the spring n^7 raises the bar p^7 to meet the lower shell of the 40 lay which as it comes forward strikes against the end of it and releases the latch h^{7} and suffers the spring e^{7} to throw the loom out of gear.

Stopping the loom when the weft is ex-45 hausted may be understood as follows; w^7 Fig. 11 represents the shuttle armed with the bobbin x^{τ} containing the weft.— y^{τ} is a spring affixed to the front side of the shuttle and is connected to the binder z⁷ by the wire a^8 which has a screw with the nut bs to adjust the degree of resistance offered to the bobbin by the binder z^7 .— c^8 is the guide wire which guides the weft off of the bobbin x^7 .— d^8 is the stop wire sliding in 55 holes through the guide wire c⁸ and the stand e^{s} .— $f^{\bar{s}}$ is a spiral spring encircled around the stop wire d^8 one end of which is attached to the wire d^{s} by the pin s^{s} inserted therein, the other abuts against the shuttle wood.—This spring yields to any gentle pressure on the end of the wire projecting beyond the guide wire c^8 and returns as far as suffered by the pin g^s when that pressure is removed.— h^8 is a catch, which when the stop wire ds is pushed back even with the

To put the loom in motion the weaver | outside of the guide wire cs locks into a notch in the stop wire, and prevents its returning by the action of the spring f^8 until the said catch is again released.

The lever is Fig. 6 turns on a stud at-70 tached to the breast-beam u, and extends along the side of the latch h^7 nearly to touch the shuttle guide.—When the stop wire d^8 is in the position seen in Fig. 11, the shuttle will pass to and fro without acting on the 75 lever i^8 and no effect is produced on the stop motion.—But when the filling is nearly exhausted on the bobbin the spring j^s recedes from the center as seen in the bobbin k^{s} and as it comes around releases the catch h^{s} and s_{0} suffers the spring f^s to throw forward the wire d⁸, which as the shuttle enters the left hand shuttle box strikes against the extremity of the lever i^s releases the latch h^{τ} and suffers the spring e^7 to throw the loom out 85

Contemplated variations in the arrangements of the parts to shift the wires over which the figure is wrought. The lever k^5 Fig. 10, which pushes the wires toward the 90 pliers may be dispensed with, in which event the upright part of the frame a⁵ must be removed to the reverse edge of the lace, and the bar i⁵ pass between those ends of the wires which the pliers grasp to shift them, 95 and the guide iron no must also rest against the said ends, presented to the pliers or forceps.

The standards which support the reciprocating bar x5, instead of being stationary 100 with the frame v^5 may be affixed to an axle and vibrate in bearings, attached to the frame v^5 .—The frame formed by the said axle and standards should be prevented from falling from the perpendicular toward the 105 shuttle boxes, by a stop attached to the bearings in which the axle turns or to the frame $v^{\scriptscriptstyle 5}$ which supports the said bearings. A spring is affixed to the frame v⁵ which acts on the frame formed by the said axle and 110 standards always tends to keep the said frame in a perpendicular position and against the aforesaid stop. A guide iron is affixed to the said frame, which guide iron when the pliers approach the wires to grasp 115 them glide along the side of another guide attached to the frame a^5 and guides the pliers into the right position to take the last of the series of wires without acting on the one next in order to it.

Many parts of machinery have been described above without any intention of claiming them as a new invention, but merely for the purpose of leading to and more readily illustrating the design and 125 operation of my improvements.

120

Having described my improvements in a loom to weave coach-lace, and shown by the foregoing description accompanying drawings, and model, the best mode of construct- 130 ing and adapting the same that I am acquainted with; I desire to be understood that I do not intend to confine myself to that particular form, and arrangement and materials of the parts shown in the drawings and model by which I effect my improvements in looms to weave coach-lace; as different forms and arrangements of mechanism may be found capable of effecting the same object; but those which I claim as the peculiar features of my invention are separately and singly as follows;—

1. Dividing or separating the wires over which the figure is wrought, one from the 15 other, by means of a pointed instrument

passing between them.

2. Pushing the said figuring wires successively toward the pliers, forceps, or pincers by the means of pressure exerted on the 20 reverse ends from those at which they are grasped by the pliers, forceps or pincers.

3. Withdrawing the said figuring wires from the figure wrought over them, and

placing them under a new portion of the figuring warp by means of pliers, forceps 25 or pincers.

4. A guide resting against the last of the series of wires to preserve the machinery which acts thereon in the same position relative to the said last of the series of wires.

5. Moving the machinery employed to shift the said figuring wires by means of

eccentric wheels cams or wipers.

6. The stationary shuttle boxes, employed for purpose and in the manner set forth 35 together with such variations of the parts thus claimed as may produce the same effect by means substantially the same.

In testimony of the above I have hereunto set my hand this twenty-seventh day of 40 December, in the year eighteen hundred and

thirty-six.

ERASTUS B. BIGELOW. [L. s.]

Witnesses:

DAVID C. MURDOCK, CHARLES W. HARTWELL.

[FIRST PRINTED 1914.]