

MATERIAL INSPECTION AND RECEIVING REPORT

Form Approved
OBM No. 0704-0248

The public reporting burden for this collection of information is estimated to average 30 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports, (0704-0248), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, or person shall be subject to any penalty for failing to comply with a collection of information it does not display a currently valid OMB control number.

PLEASE DO NOT RETURN YOUR COMPLETED FORM TO EITHER OF THESE ADDRESSES.
SEND THIS FORM IN ACCORDANCE WITH THE INSTRUCTIONS CONTAINED IN THE DFARS, APPENDIX F-401.

1. PROCUREMENT INSTRUMENT IDENTIFICATION (CONTRACT) NO. DTCG23-02-C-2DW001		(ORDER) NO. HSCG23-04-J-2DW206		6. INVOICE NO./DATE N/A	7. PAGE OF 1 44	8. ACCEPTANCE POINT Pascagoula, MS	
2. SHIPMENT NO.	3. DATE SHIPPED	4. B/L TCN		5. DISCOUNT TERMS			
9. PRIME CONTRACTOR Integrated Coast Guard Systems, LLC 1530 Wilson Boulevard, Suite 400 Arlington, VA 22209				10. ADMINISTERED BY COMDT (CG-9127) Deepwater System Integration Program Office (SIPO) 1530 Wilson Boulevard, Suite 400 Arlington, VA 22209			
11. SHIPPED FROM (If other than 9) Northrop Grumman Ship Building 1000 Access Road Pascagoula, MS 39567				12. PAYMENT WILL BE MADE BY USCG Finance Center 1430 Kristina Way Chesapeake, VA 23326			
13. SHIPPED TO USCG Deepwater Program Manager's Representative's Office (PMRO) 1000 Access Road Pascagoula, MS 39567				14. MARKED FOR United States Coast Guard (USCG)			
15. ITEM NO.	16. STOCK/PART NO. (Indicate number of shipping container - type of container - container number)	DESCRIPTION		17. QUANTITY SHIP/REC'D*	18. UNIT	19. UNIT PRICE	20. AMOUNT
	National Security Cutter, USCGC BERTHOLF (WMSL 750)			1	ea.		
21. CONTRACT QUALITY ASSURANCE				22. RECEIVER'S USE			
a. ORIGIN		b. DESTINATION		Quantities shown in column 17 were received in apparent good condition except as noted.			
<input type="checkbox"/> CQA <input type="checkbox"/> ACCEPTANCE of listed items has been made by me or under my supervision and they conform to contract, except as noticed herein or on supporting documents.		<input type="checkbox"/> CQA <input checked="" type="checkbox"/> ACCEPTANCE of listed items has been made by me or under my supervision and they conform to contract, except as noticed herein or on supporting documents.		5/8/08 <i>Desiree Sylver-Foust</i> DATE RECEIVED SIGNATURE OF AUTHORIZED GOVERNMENT REPRESENTATIVE			
DATE SIGNATURE OF AUTHORIZED GOVERNMENT REPRESENTATIVE		DATE SIGNATURE OF AUTHORIZED GOVERNMENT REPRESENTATIVE		TYPED NAME: DESIREE SYLVER-FOUST			
TYPED NAME:		TYPED NAME: JAMES KNIGHT		TITLE: Contracting Officer			
TITLE:		TITLE: Commander, USCG		MAILING ADDRESS:			
MAILING ADDRESS:		MAILING ADDRESS:		COMMERCIAL TELEPHONE NUMBER:			
COMMERCIAL TELEPHONE NUMBER:		COMMERCIAL TELEPHONE NUMBER:		* If quantity received by the Government is the same as quantity shipped, indicate by (X) mark, if different, enter actual quantity received below quantity shipped and encircle.			
23. CONTRACTOR USE ONLY				24. TRANSFER OF SHIP CUSTODY			
Contractor's Representative Acknowledgement of Receipt of DD-250 Only				Ship's Force Acknowledgement of Custody Transfer			
<i>Kevin J. O'Neill</i> 5/8/08 KEVIN J. O'NEILL Director of Contracts, Integrated Coast Guard Systems, LLC				<i>Patrick Stadt</i> CAPT, USCG 05/09/08 PATRICK STADT, CAPT, USCG Commanding Officer, USCGC BERTHOLF (WMSL-750)			

In addition to the outstanding items listed below, the following issues are USCG reservations regarding vessel acceptance:

1) Configuration Product Baseline

The configuration of USCGC BERTHOLF (WMSL 750) at preliminary acceptance establishes the product configuration baseline for NSC class cutters with the exception of the items included as discrepancies herein on the Material Inspection and Receiving Report continuation sheets (substitute DD Form 250c). Correction of these discrepancies and completion of unfinished work will establish the configuration product baseline for those items contained herein.

2) Proprietary Markings

The government notes that many design drawings and CDRLs developed at the sole expense of the government contain incorrect or ambiguous proprietary markings. Use of markings which read "The governments rights to use, modify, reproduce, release, perform, display or disclose these technical data are restricted by paragraph (b)(2) of the Rights in Technical Data - Noncommercial items clause contained in special H provisions (H-50,H-51 and H-53) in contact DTICG-23-020C02DW001. Any reproduction of technical data or portion thereof with this legend must also reproduce the markings. " does not provide the government with appropriate guidance regarding its rights to the information contained on this drawings. These markings shall be removed from all drawings which do not contain proprietary information. Change paper shall be issued immediately and incorporated in the next revision of each document.

The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750).

Categorization of liens:

CDRLs

Cutter Certification Matrix Sorts

Trial Cards

Corrective Action Reports (CAR)

Deferred Work (DW) Items

Contractor and ABS Material Liens

Tests

Third Party Certifications

Logistics Requirements Matrix (LRM) Items

Non Received Spares (OSI, SRI and SRIS)

Work Items

Contract Letters

Factory Acceptance Test (FAT) Items

Contact Modification and Other Activity

△The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) : **CDRLs**

(Unsubmitted or Unapproved or with comments) CDRLs

CDRL No.	Gate T/Ms)	S012-02	S025	S035-05
	L017	S012-20	S026	S035-06
I017-04	S011-17	S016	S027	S036
I021	S011-08	S017-02	S029	S038
I030	S011-12	S017-03	S030-02	S039
I032	S011-13	S017-07	S030-03	S043
I033	S011-14	S017-08	S030-04	
L016 (Stern Launch and Recovery and Stern	S011-15	S018	S030-05	
	S011-16	S020	S031	
	S011-20	S023	S032	
	S011-30	S024	S035-04	

CDRLs Pending Final Resolution

CDRL No.	S011-05	S012-01	S030-01	S037
S008	S011-24	S017-09	S034	

△The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) : **CDRL S016 Cutter Certification Matrix Sorts**

Submitted CDRL S016 Sorts with unanswered USCG comments

24	415	749	925	995
98	736	919	945	1027

USCG preliminarily accepted CDRL S016 Sorts requiring contractual submittal (Sorts not submitted)

562	627	663
569	662	

Preliminary CDRL S016 Sorts in USCG Review (Sorts not submitted)

3	89	170	388	498	575	598
5	90	174	426	507	576	601
13	91	178	427	524	577	604
14	92	180	432	536	578	607
25	106	181	438	553	579	611
38	116	185	439	554	581	612
43	140	198	441	561	582	617
44	146	219	446	563	584	618
55	147	230	452	564	586	619
57	151	241	466	565	589	620
58	152	242	481	567	590	623
59	153	243	482	568	591	624
60	160	262	485	569	592	629
63	165	353	490	570	593	630
88	168		492	571	595	633
				573	597	635

638	682	710	812	992	1069	1145
639	685	713	825	998	1075	1146
643	686	714	843	999	1077	1147
645	687	718	847	1018	1087	1148
649	688	720	852	1019	1096	1150
651	689	722	872	1029	1100	1154
652	690	731	879	1034	1101	1162
654	691	736	886	1035	1107	1165
656	694	740	906	1039	1108	1167
657	695	767	909	1040	1111	1170
659	701	786	914	1041	1125	1171
661	702	790	937	1043	1133	1172
662	703	791	953	1045	1135	1173
663	704	798	956	1048	1136	0424-1
676	705	801	966	1050	1138	
679	706	809	967	1051	1139	
680	707	811	990	1052	1143	

Unsubmitted CDRL S016 Sorts

1	129	196	566	675	880	979
2	134	197	583	677	882	980
12	137	202	596	708	887	982
30	138	206	603	709	892	987
33	142	223	606	711	895	988
37	143	229	608	712	903	989
40	144	249	626	715	908	996
41	161	346	627	716	915	1001
46	162	347	631	723	916	1020
47	163	352	636	732	921	1030
48	164	379	640	754	935	1042
49	172	384	641	771	939	1074
50	173	385	644	776	940	1093
52	175	401	650	779	943	1094
53	177	412	653	845	947	1097
64	182	450	660	855	950	1161
74	183	470	664	865	951	
87	184	494	666	866	957	
108	186	509	669	867	958	
127	190	518	672	869	975	
128	195	534	673	870	977	

Preliminary CDRL S016 Sorts that are pending final resolution (Sorts not submitted)

6	17	29	51	81	94
7	18	31	56	82	100
9	19	34	62	84	101
15	23	35	68	85	102
16	26	42	75	86	103

104	217	392	483	621	808
105	221	396	484	622	813
107	222	397	486	625	814
111	224	398	487	628	815
112	232	399	488	632	816
113	233	400	489	647	817
115	234	403	505	648	819
117	235	404	506	655	820
118	245	405	508	665	821
120	246	407	510	667	822
121	252	410	514	668	826
122	254	411	515	671	827
123	264	413	516	678	846
124	322	414	517	683	849
125	323	415	519	696	853
126	325	416	522	697	858
130	326	420	523	698	859
131	327	422	525	699	860
133	329	423	526	717	874
139	332	424	531	719	875
141	333	425	532	724	876
148	334	428	533	728	877
149	337	430	539	730	884
150	339	431	541	738	885
159	340	433	543	743	888
169	343	434	544	745	889
176	344	436	545	746	890
179	345	437	546	747	891
187	348	440	547	751	901
188	350	442	548	755	910
189	351	443	549	757	911
191	354	444	550	758	912
192	355	445	551	759	913
193	356	447	552	760	917
194	357	448	555	764	919
199	362	449	556	770	920
200	363	451	572	781	922
201	370	460	580	783	923
203	374	463	585	784	924
204	375	467	587	785	925
205	381	468	588	787	926
208	382	469	594	788	927
209	383	472	599	789	928
210	386	473	602	793	930
211	387	474	610	796	931
212	389	475	614	802	932
213	390	476	615	803	933
216	391	480	616	804	934

938	983	1025	1058	1084	1149
941	986	1026	1059	1090	1151
942	994	1027	1061	1091	1152
955	1002	1028	1063	1099	1155
959	1006	1031	1064	1102	1156
961	1008	1037	1065	1104	1159
963	1009	1038	1066	1112	1160
965	1010	1044	1067	1113	1163
968	1011	1046	1070	1117	1164
969	1012	1047	1071	1120	1166
971	1013	1049	1073	1123	1169
973	1014	1053	1078	1124	1176
974	1015	1055	1081	1131	0491-1
976	1016	1056	1082	1132	
978	1017	1057	1083	1141	

△The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) :

Contractor Responsible Trial Cards (*=INSURV starred cards)

MSL750AT-AV000301	MSL750AT-AX001701	MSL750AT-AX007201
MSL750AT-AV000801	MSL750AT-AX001801	MSL750AT-AX007301
MSL750AT-AV001201	MSL750AT-AX001901	MSL750AT-AX007501
MSL750AT-AV001301	MSL750AT-AX002001	MSL750AT-AX007601
MSL750AT-AV001501	MSL750AT-AX002101	MSL750AT-AX007901
MSL750AT-AV001601	MSL750AT-AX002201	MSL750AT-AX008301
MSL750AT-AV002001	MSL750AT-AX002301	MSL750AT-AX008701
MSL750AT-AV002101	MSL750AT-AX002401	MSL750AT-AX008901
MSL750AT-AV002201	MSL750AT-AX002501	MSL750AT-AX009001
MSL750AT-AV002401	MSL750AT-AX002801	MSL750AT-AX009101
MSL750AT-AV002501	MSL750AT-AX003801	MSL750AT-AX009301
MSL750AT-AV002601	MSL750AT-AX004001	MSL750AT-AX009501
MSL750AT-AV002701	MSL750AT-AX004101	MSL750AT-AX009701
MSL750AT-AV003201	MSL750AT-AX004201	MSL750AT-AX009901
MSL750AT-AV003301	MSL750AT-AX004301	MSL750AT-AX010601
MSL750AT-AV003401	MSL750AT-AX004401	MSL750AT-AX010701
MSL750AT-AV003501	MSL750AT-AX004501	MSL750AT-AX011101
MSL750AT-AV003801	MSL750AT-AX004601	MSL750AT-AX011501
MSL750AT-AV003901	MSL750AT-AX005601	MSL750AT-AX011701
MSL750AT-AV004001	MSL750AT-AX005701	MSL750AT-AX011901
MSL750AT-AV004101	MSL750AT-AX005801	MSL750AT-AX012001
MSL750AT-AV004201	MSL750AT-AX005901	MSL750AT-AX012101
MSL750AT-AV004301	MSL750AT-AX006201	MSL750AT-AX012301
MSL750AT-AV004401 *	MSL750AT-AX006401	MSL750AT-AX012401
MSL750AT-AX000101 *	MSL750AT-AX006601	MSL750AT-AX012501
MSL750AT-AX000201	MSL750AT-AX006701	MSL750AT-AX012601
MSL750AT-AX000301	MSL750AT-AX006801	MSL750AT-AX012901
MSL750AT-AX000401	MSL750AT-AX006901	MSL750AT-AX013101
MSL750AT-AX001601	MSL750AT-AX007101	MSL750AT-AX013301

MSL750AT-AX013401	MSL750AT-AX024601	MSL750AT-AX031901
MSL750AT-AX013501	MSL750AT-AX024701	MSL750AT-AX032001
MSL750AT-AX013601	MSL750AT-AX024801	MSL750AT-AX032101
MSL750AT-AX013701	MSL750AT-AX025101	MSL750AT-AX032301
MSL750AT-AX013801	MSL750AT-AX025301	MSL750AT-CC000201
MSL750AT-AX013901	MSL750AT-AX025401	MSL750AT-CC000701
MSL750AT-AX014001	MSL750AT-AX025501	MSL750AT-CC000901
MSL750AT-AX014101	MSL750AT-AX025701	MSL750AT-CC001201
MSL750AT-AX014201	MSL750AT-AX025801	MSL750AT-CC001801
MSL750AT-AX014301	MSL750AT-AX025901	MSL750AT-CC002001
MSL750AT-AX014401	MSL750AT-AX026001	MSL750AT-CC002101
MSL750AT-AX014601	MSL750AT-AX026201	MSL750AT-CC002201
MSL750AT-AX015101	MSL750AT-AX026301	MSL750AT-CC002301
MSL750AT-AX015901	MSL750AT-AX026401	MSL750AT-CC002401
MSL750AT-AX016301	MSL750AT-AX026501	MSL750AT-CC002501
MSL750AT-AX016501	MSL750AT-AX026601	MSL750AT-CC004401
MSL750AT-AX016601	MSL750AT-AX026701	MSL750AT-CC004801
MSL750AT-AX016901	MSL750AT-AX026801	MSL750AT-CC005101
MSL750AT-AX017001	MSL750AT-AX026901	MSL750AT-CC005201
MSL750AT-AX018001	MSL750AT-AX027001	MSL750AT-CC005701
MSL750AT-AX018101	MSL750AT-AX027101	MSL750AT-CC006301
MSL750AT-AX018601	MSL750AT-AX027201	MSL750AT-CC006401
MSL750AT-AX018701	MSL750AT-AX027401	MSL750AT-CC006501
MSL750AT-AX018801	MSL750AT-AX027801	MSL750AT-CC006601
MSL750AT-AX018901	MSL750AT-AX027901	MSL750AT-CC006701
MSL750AT-AX019001	MSL750AT-AX028301	MSL750AT-CC007701
MSL750AT-AX019401	MSL750AT-AX028401	MSL750AT-CC008401
MSL750AT-AX019501	MSL750AT-AX028601	MSL750AT-CC008601
MSL750AT-AX019701	MSL750AT-AX028701	MSL750AT-CC009301
MSL750AT-AX020801	MSL750AT-AX029201	MSL750AT-CC009401
MSL750AT-AX021301	MSL750AT-AX029301	MSL750AT-CC009501
MSL750AT-AX021401	MSL750AT-AX029401	MSL750AT-CC009601
MSL750AT-AX021901	MSL750AT-AX029501	MSL750AT-DC000101
MSL750AT-AX022001	MSL750AT-AX029601	MSL750AT-DC000301
MSL750AT-AX022101	MSL750AT-AX029701	MSL750AT-DC000901
MSL750AT-AX022601	MSL750AT-AX029801	MSL750AT-DC001301
MSL750AT-AX022701	MSL750AT-AX029901	MSL750AT-DC001401
MSL750AT-AX022801	MSL750AT-AX030001	MSL750AT-DC001901
MSL750AT-AX022901	MSL750AT-AX030201	MSL750AT-DC002001
MSL750AT-AX023101	MSL750AT-AX030501	MSL750AT-DC002101
MSL750AT-AX023201	MSL750AT-AX030601	MSL750AT-DC002501
MSL750AT-AX023301	MSL750AT-AX030901	MSL750AT-DC003601
MSL750AT-AX023401	MSL750AT-AX031001	MSL750AT-DC003901
MSL750AT-AX023501	MSL750AT-AX031101	MSL750AT-DC004801
MSL750AT-AX023701	MSL750AT-AX031201	MSL750AT-DC005501
MSL750AT-AX023901	MSL750AT-AX031301	MSL750AT-DC006501
MSL750AT-AX024201	MSL750AT-AX031401	MSL750AT-DC007001
MSL750AT-AX024301	MSL750AT-AX031501	MSL750AT-DC007201
MSL750AT-AX024401	MSL750AT-AX031601	MSL750AT-DC007301
MSL750AT-AX024501	MSL750AT-AX031801	MSL750AT-DC007302

MSL750AT-DC007303	MSL750AT-DC022001	MSL750AT-DC032901
MSL750AT-DC007304	MSL750AT-DC022101	MSL750AT-DC033001
MSL750AT-DC007305	MSL750AT-DC022201	MSL750AT-DC033101
MSL750AT-DC007306	MSL750AT-DC022301	MSL750AT-DC033301
MSL750AT-DC007307	MSL750AT-DC022401	MSL750AT-DC033501
MSL750AT-DC007308	MSL750AT-DC022501	MSL750AT-DC033601
MSL750AT-DC007601	MSL750AT-DC022601	MSL750AT-DC033801
MSL750AT-DC007901	MSL750AT-DC022701	MSL750AT-DC033901
MSL750AT-DC008001	MSL750AT-DC022801	MSL750AT-DC034001
MSL750AT-DC008201	MSL750AT-DC022901	MSL750AT-DC034201
MSL750AT-DC008301	MSL750AT-DC023001	MSL750AT-DC034401
MSL750AT-DC012001	MSL750AT-DC023101	MSL750AT-DC034501
MSL750AT-DC012601	MSL750AT-DC023201	MSL750AT-DC034601
MSL750AT-DC012701	MSL750AT-DC023301	MSL750AT-DC034801
MSL750AT-DC012801	MSL750AT-DC023401	MSL750AT-DC034901
MSL750AT-DC012901	MSL750AT-DC023501	MSL750AT-DC035001
MSL750AT-DC014301	MSL750AT-DC023801	MSL750AT-DC035201
MSL750AT-DC014601	MSL750AT-DC024001	MSL750AT-DC035301
MSL750AT-DC014602	MSL750AT-DC024101	MSL750AT-DC035401
MSL750AT-DC014603	MSL750AT-DC024201	MSL750AT-DC035501
MSL750AT-DC014604	MSL750AT-DC024301	MSL750AT-DC035601
MSL750AT-DC014605	MSL750AT-DC024401	MSL750AT-DC035701
MSL750AT-DC016101	MSL750AT-DC024501	MSL750AT-DC035801
MSL750AT-DC016201	MSL750AT-DC024601	MSL750AT-DC035901
MSL750AT-DC016301	MSL750AT-DC024701	MSL750AT-DC036001
MSL750AT-DC016401	MSL750AT-DC024801	MSL750AT-DC036101
MSL750AT-DC016501	MSL750AT-DC024901	MSL750AT-DC036201
MSL750AT-DC016601	MSL750AT-DC025001	MSL750AT-DC036301
MSL750AT-DC016701	MSL750AT-DC025101	MSL750AT-DC036401
MSL750AT-DC016801	MSL750AT-DC026401	MSL750AT-DC036501
MSL750AT-DC016901	MSL750AT-DC027201	MSL750AT-DC037501
MSL750AT-DC018401	MSL750AT-DC027301	MSL750AT-DC037601
MSL750AT-DC018701	MSL750AT-DC027501	MSL750AT-DC038901
MSL750AT-DC019001	MSL750AT-DC027801	MSL750AT-DC039001
MSL750AT-DC020401	MSL750AT-DC028001	MSL750AT-DC039101
MSL750AT-DC020501	MSL750AT-DC028301	MSL750AT-DC039201
MSL750AT-DC020601	MSL750AT-DC028501	MSL750AT-DC039301
MSL750AT-DC020701	MSL750AT-DC028601	MSL750AT-DC039501
MSL750AT-DC020801	MSL750AT-DC028801	MSL750AT-DC039601
MSL750AT-DC020901	MSL750AT-DC028901	MSL750AT-DC039801
MSL750AT-DC021001	MSL750AT-DC031901	MSL750AT-DC040601
MSL750AT-DC021101	MSL750AT-DC032001	MSL750AT-DC040901
MSL750AT-DC021201	MSL750AT-DC032101	MSL750AT-DC041101
MSL750AT-DC021301	MSL750AT-DC032201	MSL750AT-DC041201
MSL750AT-DC021401	MSL750AT-DC032301	MSL750AT-DC041601
MSL750AT-DC021501	MSL750AT-DC032401	MSL750AT-DC041701
MSL750AT-DC021601	MSL750AT-DC032501	MSL750AT-DC041801
MSL750AT-DC021701	MSL750AT-DC032601	MSL750AT-DC041901
MSL750AT-DC021801	MSL750AT-DC032701	MSL750AT-DC042001
MSL750AT-DC021901	MSL750AT-DC032801	MSL750AT-DC042101

MSL750AT-DC042201	MSL750AT-DC047701	MSL750AT-DC053401
MSL750AT-DC042301	MSL750AT-DC047801	MSL750AT-DC053501
MSL750AT-DC042401	MSL750AT-DC047901	MSL750AT-DC053601
MSL750AT-DC042501	MSL750AT-DC048101	MSL750AT-DC053701
MSL750AT-DC042601	MSL750AT-DC048201	MSL750AT-DC053901
MSL750AT-DC042701	MSL750AT-DC048301	MSL750AT-DC054701
MSL750AT-DC042801	MSL750AT-DC048401	MSL750AT-DC054901
MSL750AT-DC042901	MSL750AT-DC048501	MSL750AT-DC055001
MSL750AT-DC043001	MSL750AT-DC048601	MSL750AT-DC055201
MSL750AT-DC043101	MSL750AT-DC048701	MSL750AT-DC055701
MSL750AT-DC043201	MSL750AT-DC048801	MSL750AT-DK000101 *
MSL750AT-DC043301	MSL750AT-DC048901	MSL750AT-DK000201 *
MSL750AT-DC043401	MSL750AT-DC049001	MSL750AT-DK000301
MSL750AT-DC043501	MSL750AT-DC049101	MSL750AT-DK000401
MSL750AT-DC043601	MSL750AT-DC049201	MSL750AT-DK000501
MSL750AT-DC043701	MSL750AT-DC049301	MSL750AT-DK000601
MSL750AT-DC043801	MSL750AT-DC049501	MSL750AT-DK000901
MSL750AT-DC043901	MSL750AT-DC049601	MSL750AT-DK001001
MSL750AT-DC044001	MSL750AT-DC049701	MSL750AT-DK001201
MSL750AT-DC044201	MSL750AT-DC049801	MSL750AT-DK001301
MSL750AT-DC044401	MSL750AT-DC049901	MSL750AT-DK001501
MSL750AT-DC044501	MSL750AT-DC050001	MSL750AT-DK001701
MSL750AT-DC044601	MSL750AT-DC050101	MSL750AT-DK001801
MSL750AT-DC044701	MSL750AT-DC050201	MSL750AT-DK001901
MSL750AT-DC044801	MSL750AT-DC050301	MSL750AT-DK002001
MSL750AT-DC044901	MSL750AT-DC050401	MSL750AT-DK002101
MSL750AT-DC045001	MSL750AT-DC050501	MSL750AT-DK002201
MSL750AT-DC045101	MSL750AT-DC050701	MSL750AT-DK002301
MSL750AT-DC045301	MSL750AT-DC050801	MSL750AT-DK002401
MSL750AT-DC045401	MSL750AT-DC050901	MSL750AT-DK002501
MSL750AT-DC045501	MSL750AT-DC051001	MSL750AT-DK002601
MSL750AT-DC045701	MSL750AT-DC051101	MSL750AT-DK002701
MSL750AT-DC045801	MSL750AT-DC051201	MSL750AT-DK002801
MSL750AT-DC045901	MSL750AT-DC051301	MSL750AT-DK003001
MSL750AT-DC046001	MSL750AT-DC051401	MSL750AT-DK003101
MSL750AT-DC046101	MSL750AT-DC051501	MSL750AT-DK003301
MSL750AT-DC046201	MSL750AT-DC051601	MSL750AT-DK003801
MSL750AT-DC046301	MSL750AT-DC051701	MSL750AT-DK004001
MSL750AT-DC046401	MSL750AT-DC051801	MSL750AT-DK004101
MSL750AT-DC046601	MSL750AT-DC051901	MSL750AT-DK004401
MSL750AT-DC046701	MSL750AT-DC052001	MSL750AT-DK004601
MSL750AT-DC046801	MSL750AT-DC052101	MSL750AT-DK004701
MSL750AT-DC046901	MSL750AT-DC052201	MSL750AT-DK005201
MSL750AT-DC047001	MSL750AT-DC052301	MSL750AT-DK005301
MSL750AT-DC047101	MSL750AT-DC052501	MSL750AT-DK005501
MSL750AT-DC047201	MSL750AT-DC052601	MSL750AT-DK005601
MSL750AT-DC047301	MSL750AT-DC052901	MSL750AT-DK005701
MSL750AT-DC047401	MSL750AT-DC053101	MSL750AT-DK005801
MSL750AT-DC047501	MSL750AT-DC053201	MSL750AT-DK005901
MSL750AT-DC047601	MSL750AT-DC053301	MSL750AT-DK006001

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750AT-DK006101	MSL750AT-EL000701	MSL750AT-EP006301
MSL750AT-DK006201	MSL750AT-EL000801	MSL750AT-EP008001
MSL750AT-DK006301	MSL750AT-EL002201	MSL750AT-EP008101
MSL750AT-DK006401	MSL750AT-EL002301	MSL750AT-EP008301
MSL750AT-DK006501	MSL750AT-EL003801	MSL750AT-EP008401
MSL750AT-DK006601	MSL750AT-EL003901	MSL750AT-EP008501
MSL750AT-DK006701	MSL750AT-EL004001	MSL750AT-EP008601
MSL750AT-DK006901	MSL750AT-EL004101	MSL750AT-EP008701
MSL750AT-DK007001	MSL750AT-EL004201	MSL750AT-EP008801
MSL750AT-DK007301	MSL750AT-EL004301	MSL750AT-EP009201
MSL750AT-DK007701	MSL750AT-EL004401	MSL750AT-EP009301
MSL750AT-DK007801	MSL750AT-EL004601	MSL750AT-EP009801
MSL750AT-DK007901	MSL750AT-EL004701	MSL750AT-EP010501
MSL750AT-DK008101	MSL750AT-EL004901	MSL750AT-EP010601
MSL750AT-DK008201	MSL750AT-EL005001	MSL750AT-EP011101
MSL750AT-DK008301	MSL750AT-EL005101	MSL750AT-EP011501
MSL750AT-DK008401	MSL750AT-EL005401	MSL750AT-EP012001
MSL750AT-DK009201	MSL750AT-EL005501	MSL750AT-EP012101
MSL750AT-DK009301	MSL750AT-EL005601	MSL750AT-EP012301
MSL750AT-DK009401	MSL750AT-EL005701	MSL750AT-EP012501
MSL750AT-DK009601	MSL750AT-EL005901	MSL750AT-EP012601
MSL750AT-DK009701	MSL750AT-EL006001	MSL750AT-EP012701
MSL750AT-DK009801	MSL750AT-EL006101	MSL750AT-EP013101
MSL750AT-DK009901	MSL750AT-EL006301	MSL750AT-EP013301
MSL750AT-DK010001	MSL750AT-EL006401	MSL750AT-EP013401
MSL750AT-DK010101	MSL750AT-EL006501	MSL750AT-EP013501
MSL750AT-DK010201	MSL750AT-EL006601	MSL750AT-EP013701
MSL750AT-DK010301	MSL750AT-EL006701	MSL750AT-EP014001
MSL750AT-DK010401	MSL750AT-EL006801	MSL750AT-EP014201
MSL750AT-DK010501	MSL750AT-EL007001	MSL750AT-EP014401
MSL750AT-DK010601	MSL750AT-EP000501	MSL750AT-EP014501
MSL750AT-DK010701	MSL750AT-EP000701	MSL750AT-EP014601
MSL750AT-DK010901	MSL750AT-EP000801	MSL750AT-EP014801
MSL750AT-DK011001	MSL750AT-EP000901	MSL750AT-EP014901
MSL750AT-DK011201	MSL750AT-EP001001	MSL750AT-EP015201
MSL750AT-DK011301	MSL750AT-EP003201	MSL750AT-HB000101
MSL750AT-DK011501	MSL750AT-EP003301	MSL750AT-HB000401
MSL750AT-DK011701	MSL750AT-EP003601	MSL750AT-HB001201
MSL750AT-DK011801	MSL750AT-EP004101	MSL750AT-HB001301
MSL750AT-DK012201	MSL750AT-EP004901	MSL750AT-HB001401
MSL750AT-DK012401	MSL750AT-EP005001	MSL750AT-HB001701
MSL750AT-DK012601	MSL750AT-EP005201	MSL750AT-HB004001
MSL750AT-DK013001	MSL750AT-EP005301	MSL750AT-HB004201
MSL750AT-DK013301	MSL750AT-EP005501	MSL750AT-HB004401
MSL750AT-EL000101	MSL750AT-EP005601	MSL750AT-HB004801
MSL750AT-EL000301	MSL750AT-EP005701	MSL750AT-HB004901
MSL750AT-EL000401	MSL750AT-EP005901	MSL750AT-HB005101
MSL750AT-EL000501	MSL750AT-EP006001	MSL750AT-HB005201
MSL750AT-EL000601	MSL750AT-EP006101	MSL750AT-HB005301

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750AT-HB005401	MSL750AT-MP003701	MSL750AT-MP014501
MSL750AT-HB005501	MSL750AT-MP003801	MSL750AT-MP015301
MSL750AT-HB005801	MSL750AT-MP003901	MSL750AT-MP016101
MSL750AT-HB006001	MSL750AT-MP004101	MSL750AT-MP016201
MSL750AT-HB006101	MSL750AT-MP004301	MSL750AT-MP016301
MSL750AT-HB011301	MSL750AT-MP004701	MSL750AT-MP016701
MSL750AT-HB046201	MSL750AT-MP004901	MSL750AT-MP017001
MSL750AT-HB046401	MSL750AT-MP005001	MSL750AT-MP017101
MSL750AT-HB046501	MSL750AT-MP005101	MSL750AT-MP017201
MSL750AT-HB046601	MSL750AT-MP005201	MSL750AT-MP017701
MSL750AT-IS000101	MSL750AT-MP005301	MSL750AT-MP017801
MSL750AT-IS000201	MSL750AT-MP005401	MSL750AT-MP018601
MSL750AT-IS000301	MSL750AT-MP005501	MSL750AT-MP019101
MSL750AT-IS000401	MSL750AT-MP005601	MSL750AT-MP019501
MSL750AT-IS002001	MSL750AT-MP005801	MSL750AT-MP019801
MSL750AT-IS002501	MSL750AT-MP005901	MSL750AT-MP020101
MSL750AT-IS002601	MSL750AT-MP006001	MSL750AT-MP020301
MSL750AT-MD000101	MSL750AT-MP006201	MSL750AT-MP020401
MSL750AT-MD001601	MSL750AT-MP006701	MSL750AT-MP020601
MSL750AT-MP000101 *	MSL750AT-MP006801	MSL750AT-MP020701
MSL750AT-MP000201 *	MSL750AT-MP007201	MSL750AT-MP020901
MSL750AT-MP000301	MSL750AT-MP007301	MSL750AT-MP021001
MSL750AT-MP000401	MSL750AT-MP007401	MSL750AT-MP021501
MSL750AT-MP000501	MSL750AT-MP007501	MSL750AT-MP021601
MSL750AT-MP000601	MSL750AT-MP008201	MSL750AT-MP021701
MSL750AT-MP000701	MSL750AT-MP008501	MSL750AT-MP022001
MSL750AT-MP000801	MSL750AT-MP008701	MSL750AT-MP022701
MSL750AT-MP000901	MSL750AT-MP009201	MSL750AT-MP023001
MSL750AT-MP001001	MSL750AT-MP010301	MSL750AT-MP023101
MSL750AT-MP001101	MSL750AT-MP010501	MSL750AT-MP023201
MSL750AT-MP001201	MSL750AT-MP010601	MSL750AT-MP023301
MSL750AT-MP001301	MSL750AT-MP010701	MSL750AT-MP023401
MSL750AT-MP001401	MSL750AT-MP010801	MSL750AT-MP025701
MSL750AT-MP001801	MSL750AT-MP010901	MSL750AT-MP026501
MSL750AT-MP001901	MSL750AT-MP011001	MSL750AT-MP026601
MSL750AT-MP002101	MSL750AT-MP011101	MSL750AT-MP026701
MSL750AT-MP002201	MSL750AT-MP011201	MSL750AT-MP026801
MSL750AT-MP002301	MSL750AT-MP011301	MSL750AT-MP027001
MSL750AT-MP002401	MSL750AT-MP011401	MSL750AT-MP027101
MSL750AT-MP002501	MSL750AT-MP011601	MSL750AT-MP027701
MSL750AT-MP002801	MSL750AT-MP011701	MSL750AT-MP028101
MSL750AT-MP002901	MSL750AT-MP011801	MSL750AT-MP029201
MSL750AT-MP003001	MSL750AT-MP011901	MSL750AT-MP029501
MSL750AT-MP003101	MSL750AT-MP012401	MSL750AT-MP029701
MSL750AT-MP003201	MSL750AT-MP012501	MSL750AT-MP030101
MSL750AT-MP003301	MSL750AT-MP012601	MSL750AT-MP030601
MSL750AT-MP003401	MSL750AT-MP012701	MSL750AT-MP030801
MSL750AT-MP003501	MSL750AT-MP014201	MSL750AT-MP030901
MSL750AT-MP003601	MSL750AT-MP014301	MSL750AT-MP031001

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750AT-MP031301	MSL750AT-NV003801	MSL750AT-SP002801
MSL750AT-MP031701	MSL750AT-NV004901	MSL750AT-SP002901
MSL750AT-MP031901	MSL750AT-OH001701	MSL750AT-SP003001
MSL750AT-MP032501	MSL750AT-OH001801	MSL750AT-SP003101
MSL750AT-MP032701	MSL750AT-OH002301	MSL750AT-SP003201
MSL750AT-MP033101	MSL750AT-OH002901	MSL750AT-SP003301
MSL750AT-MP034201	MSL750AT-OH003001	MSL750AT-SP003401
MSL750AT-MP034801	MSL750AT-OH003101	MSL750AT-SP003601
MSL750AT-MP037501	MSL750AT-OH003301	MSL750AT-SP003701
MSL750AT-MP037801	MSL750AT-OP000101	MSL750AT-SP003801
MSL750AT-MP038101	MSL750AT-OP000501	MSL750AT-SP004001
MSL750AT-MP038801	MSL750AT-OP000601	MSL750AT-SP004101
MSL750AT-MP039601	MSL750AT-OP000701	MSL750AT-SP004501
MSL750AT-MP040901	MSL750AT-OP000801	MSL750AT-SP004601
MSL750AT-MP041001	MSL750AT-OP000901	MSL750AT-SP004901
MSL750AT-MP041101	MSL750AT-OP001001	MSL750AT-SP005001
MSL750AT-MP041801	MSL750AT-OP001101	MSL750AT-SP005301
MSL750AT-MP041901	MSL750AT-OP001301	MSL750AT-SP005401
MSL750AT-MP043201	MSL750AT-OP001401	MSL750AT-SP005601
MSL750AT-MP043301	MSL750AT-OP001501	MSL750AT-SP005801
MSL750AT-MP044001	MSL750AT-OP001601	MSL750AT-SP005901
MSL750AT-MP044101	MSL750AT-OP001701	MSL750AT-SP006201
MSL750AT-MP044201	MSL750AT-OP001801	MSL750AT-SP007001
MSL750AT-NV000101	MSL750AT-OP001901	MSL750AT-SP007401
MSL750AT-NV000201	MSL750AT-OP002401	MSL750AT-SP007601
MSL750AT-NV000301	MSL750AT-OP002801	MSL750AT-SP007901
MSL750AT-NV000401	MSL750AT-OP004101	MSL750AT-VT000501
MSL750AT-NV000601	MSL750AT-OP004501	MSL750AT-VT000701
MSL750AT-NV000701	MSL750AT-SP000201	MSL750AT-VT000801
MSL750AT-NV000801	MSL750AT-SP000301	MSL750AT-VT002001
MSL750AT-NV001001	MSL750AT-SP000401	MSL750AT-VT002401
MSL750AT-NV001101	MSL750AT-SP000601	MSL750AT-VT002601
MSL750AT-NV001201	MSL750AT-SP000801	MSL750AT-VT003001
MSL750AT-NV001301	MSL750AT-SP000901	MSL750AT-VT003401
MSL750AT-NV001401	MSL750AT-SP001101	MSL750AT-VT004001
MSL750AT-NV001501	MSL750AT-SP001401	MSL750AT-VT004401
MSL750AT-NV001701	MSL750AT-SP001501	MSL750AT-VT004402
MSL750AT-NV001901	MSL750AT-SP001601	MSL750AT-VT004501
MSL750AT-NV002001	MSL750AT-SP001701	MSL750AT-VT004701
MSL750AT-NV002301	MSL750AT-SP001801	MSL750AT-VT004901
MSL750AT-NV002501	MSL750AT-SP001901	MSL750AT-WP000101 *
MSL750AT-NV002601	MSL750AT-SP002001	MSL750AT-WP000801
MSL750AT-NV002801	MSL750AT-SP002101	MSL750AT-WP000901
MSL750AT-NV002901	MSL750AT-SP002201	MSL750AT-WP001101
MSL750AT-NV003101	MSL750AT-SP002301	MSL750AT-WP001601
MSL750AT-NV003201	MSL750AT-SP002401	MSL750AT-WP001701
MSL750AT-NV003301	MSL750AT-SP002501	MSL750AT-WP002101
MSL750AT-NV003401	MSL750AT-SP002601	MSL750AT-WP002201
MSL750AT-NV003601	MSL750AT-SP002701	MSL750AT-WP002401

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750AT-WP002801	MSL750BT-AX804201	MSL750BT-AX821701
MSL750AT-WP002901	MSL750BT-AX804301	MSL750BT-AX821901
MSL750AT-WP003001	MSL750BT-AX804401	MSL750BT-AX822001
MSL750AT-WP003301	MSL750BT-AX804901	MSL750BT-AX822201
MSL750AT-WP003401	MSL750BT-AX805001	MSL750BT-AX822801
MSL750AT-WP003901	MSL750BT-AX805301	MSL750BT-AX822901
MSL750AT-WP004001	MSL750BT-AX806001	MSL750BT-AX823201
MSL750AT-WP004301	MSL750BT-AX806401	MSL750BT-AX823801
MSL750BT-AV400101	MSL750BT-AX806501	MSL750BT-AX823901
MSL750BT-AV400201	MSL750BT-AX806701	MSL750BT-AX824601
MSL750BT-AV400301	MSL750BT-AX807801	MSL750BT-AX825101
MSL750BT-AV800401	MSL750BT-AX807901	MSL750BT-AX827601
MSL750BT-AV800501	MSL750BT-AX808001	MSL750BT-AX827701
MSL750BT-AV800801	MSL750BT-AX808301	MSL750BT-AX827801
MSL750BT-AV800901	MSL750BT-AX808401	MSL750BT-AX828101
MSL750BT-AV801001	MSL750BT-AX808901	MSL750BT-AX829201
MSL750BT-AV801401	MSL750BT-AX809201	MSL750BT-AX829301
MSL750BT-AV801601	MSL750BT-AX809301	MSL750BT-AX829401
MSL750BT-AV802201	MSL750BT-AX809601	MSL750BT-AX829701
MSL750BT-AV802301	MSL750BT-AX810501	MSL750BT-AX829801
MSL750BT-AV802401	MSL750BT-AX810601	MSL750BT-AX830001
MSL750BT-AV802501	MSL750BT-AX810901	MSL750BT-AX830101
MSL750BT-AV803301	MSL750BT-AX812301	MSL750BT-AX830201
MSL750BT-AV804101	MSL750BT-AX813101	MSL750BT-AX830301
MSL750BT-AV804701	MSL750BT-AX813201	MSL750BT-AX830401
MSL750BT-AV804801	MSL750BT-AX813301	MSL750BT-AX830501
MSL750BT-AV804901	MSL750BT-AX813501	MSL750BT-AX830601
MSL750BT-AV805001	MSL750BT-AX813801	MSL750BT-AX830701
MSL750BT-AX400501	MSL750BT-AX813901	MSL750BT-AX830801
MSL750BT-AX401101	MSL750BT-AX815001	MSL750BT-AX830901
MSL750BT-AX401201	MSL750BT-AX815101	MSL750BT-AX831001
MSL750BT-AX401301	MSL750BT-AX815301	MSL750BT-AX831101
MSL750BT-AX401601	MSL750BT-AX815401	MSL750BT-AX831301
MSL750BT-AX402101	MSL750BT-AX815601	MSL750BT-AX831401
MSL750BT-AX402501	MSL750BT-AX815801	MSL750BT-AX831701
MSL750BT-AX402601	MSL750BT-AX815901	MSL750BT-AX832001
MSL750BT-AX402701	MSL750BT-AX816301	MSL750BT-AX832101
MSL750BT-AX402801	MSL750BT-AX816601	MSL750BT-AX832301
MSL750BT-AX403001	MSL750BT-AX817301	MSL750BT-AX832401
MSL750BT-AX800101	MSL750BT-AX818701	MSL750BT-AX832501
MSL750BT-AX800801	MSL750BT-AX818801	MSL750BT-AX832601
MSL750BT-AX801101	MSL750BT-AX819201	MSL750BT-AX832701
MSL750BT-AX801401	MSL750BT-AX819701	MSL750BT-AX832801
MSL750BT-AX802001	MSL750BT-AX819702	MSL750BT-AX833201
MSL750BT-AX802701	MSL750BT-AX819801	MSL750BT-AX833301
MSL750BT-AX802801	MSL750BT-AX819802	MSL750BT-AX833401
MSL750BT-AX803001	MSL750BT-AX820101	MSL750BT-AX833501
MSL750BT-AX803801	MSL750BT-AX821301	MSL750BT-AX833601
MSL750BT-AX804101	MSL750BT-AX821501	MSL750BT-AX833701

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750BT-AX833801	MSL750BT-CC805301	MSL750BT-DC811301
MSL750BT-AX833901	MSL750BT-CC805401	MSL750BT-DC811401
MSL750BT-AX834001	MSL750BT-CC805601	MSL750BT-DC811501
MSL750BT-AX834201	MSL750BT-CC805701	MSL750BT-DC811601
MSL750BT-AX834301	MSL750BT-DC400201	MSL750BT-DC811701
MSL750BT-AX834401	MSL750BT-DC400301	MSL750BT-DC811901
MSL750BT-AX834501	MSL750BT-DC400401	MSL750BT-DC812101
MSL750BT-CC401401	MSL750BT-DC401001	MSL750BT-DC812301
MSL750BT-CC401501	MSL750BT-DC401101	MSL750BT-DC812401
MSL750BT-CC405201	MSL750BT-DC401201	MSL750BT-DC813101
MSL750BT-CC413101	MSL750BT-DC401701	MSL750BT-DC813201
MSL750BT-CC413301	MSL750BT-DC401801	MSL750BT-DC813401
MSL750BT-CC415601	MSL750BT-DC401901	MSL750BT-DC813801
MSL750BT-CC415801	MSL750BT-DC402301	MSL750BT-DC814301
MSL750BT-CC416101	MSL750BT-DC402401	MSL750BT-DC814701
MSL750BT-CC416301	MSL750BT-DC402501	MSL750BT-DC814801
MSL750BT-CC419001	MSL750BT-DC403001	MSL750BT-DC814901
MSL750BT-CC419101	MSL750BT-DC403701	MSL750BT-DC815001
MSL750BT-CC419201	MSL750BT-DC800101	MSL750BT-DC815201
MSL750BT-CC419801	MSL750BT-DC800301	MSL750BT-DC815301
MSL750BT-CC419901	MSL750BT-DC800701	MSL750BT-DC815601
MSL750BT-CC420301	MSL750BT-DC801601	MSL750BT-DC815701
MSL750BT-CC420601	MSL750BT-DC801801	MSL750BT-DC815901
MSL750BT-CC420701	MSL750BT-DC802501	MSL750BT-DC816101
MSL750BT-CC420801	MSL750BT-DC803101	MSL750BT-DC816201
MSL750BT-CC421001	MSL750BT-DC803201	MSL750BT-DC816401
MSL750BT-CC421101	MSL750BT-DC803501	MSL750BT-DC816701
MSL750BT-CC421201	MSL750BT-DC803801	MSL750BT-DC816801
MSL750BT-CC421701	MSL750BT-DC804101	MSL750BT-DC817101
MSL750BT-CC421801	MSL750BT-DC804901	MSL750BT-DC817201
MSL750BT-CC422101	MSL750BT-DC805001	MSL750BT-DC817301
MSL750BT-CC800101	MSL750BT-DC805101	MSL750BT-DC817401
MSL750BT-CC800301	MSL750BT-DC805201	MSL750BT-DC817501
MSL750BT-CC800501	MSL750BT-DC805901	MSL750BT-DC819101
MSL750BT-CC800601	MSL750BT-DC806101	MSL750BT-DC819201
MSL750BT-CC800801	MSL750BT-DC806301	MSL750BT-DC822601
MSL750BT-CC800901	MSL750BT-DC806401	MSL750BT-DC822801
MSL750BT-CC801001	MSL750BT-DC807201	MSL750BT-DC823001
MSL750BT-CC802001	MSL750BT-DC808001	MSL750BT-DC824901
MSL750BT-CC802101	MSL750BT-DC809401	MSL750BT-DC825301
MSL750BT-CC802501	MSL750BT-DC809701	MSL750BT-DC825401
MSL750BT-CC802701	MSL750BT-DC809801	MSL750BT-DC825801
MSL750BT-CC803001	MSL750BT-DC809901	MSL750BT-DC825901
MSL750BT-CC803801	MSL750BT-DC810501	MSL750BT-DC826001
MSL750BT-CC804001	MSL750BT-DC810701	MSL750BT-DC826201
MSL750BT-CC804301	MSL750BT-DC810801	MSL750BT-DC826801
MSL750BT-CC804501	MSL750BT-DC810901	MSL750BT-DC827001
MSL750BT-CC804601	MSL750BT-DC811001	MSL750BT-DC827201
MSL750BT-CC804801	MSL750BT-DC811101	MSL750BT-DC827601

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750BT-DC827701	MSL750BT-DK814801	MSL750BT-DK820701
MSL750BT-DC827801	MSL750BT-DK814901	MSL750BT-DK820801
MSL750BT-DC827901	MSL750BT-DK815001	MSL750BT-DK820901
MSL750BT-DC828101	MSL750BT-DK815101	MSL750BT-DK821001
MSL750BT-DC828301	MSL750BT-DK815201	MSL750BT-DK821101
MSL750BT-DC828701	MSL750BT-DK815301	MSL750BT-DK821201
MSL750BT-DC828801	MSL750BT-DK815401	MSL750BT-EL402301
MSL750BT-DC828901	MSL750BT-DK815501	MSL750BT-EL800401
MSL750BT-DC829001	MSL750BT-DK815601	MSL750BT-EL800501
MSL750BT-DC829101	MSL750BT-DK815701	MSL750BT-EL801001
MSL750BT-DC829301	MSL750BT-DK815801	MSL750BT-EL801101
MSL750BT-DC830001	MSL750BT-DK815901	MSL750BT-EL801701
MSL750BT-DC830401	MSL750BT-DK816001	MSL750BT-EL802401
MSL750BT-DC830801	MSL750BT-DK816101	MSL750BT-EL802801
MSL750BT-DC830901	MSL750BT-DK816501	MSL750BT-EL803601
MSL750BT-DC831301	MSL750BT-DK816701	MSL750BT-EL804901
MSL750BT-DK400101	MSL750BT-DK816801	MSL750BT-EL805401
MSL750BT-DK400201	MSL750BT-DK816901	MSL750BT-EL805901
MSL750BT-DK800401	MSL750BT-DK817101	MSL750BT-EL806101
MSL750BT-DK800501	MSL750BT-DK817201	MSL750BT-EL806301
MSL750BT-DK804501	MSL750BT-DK817301	MSL750BT-EL806501
MSL750BT-DK805401	MSL750BT-DK817401	MSL750BT-EL806901
MSL750BT-DK807201	MSL750BT-DK817501	MSL750BT-EL807001
MSL750BT-DK807301	MSL750BT-DK817601	MSL750BT-EL807101
MSL750BT-DK807401	MSL750BT-DK817701	MSL750BT-EL807201
MSL750BT-DK807501	MSL750BT-DK817801	MSL750BT-EL807401
MSL750BT-DK807601	MSL750BT-DK817901	MSL750BT-EL807501
MSL750BT-DK812101	MSL750BT-DK818001	MSL750BT-EL807801
MSL750BT-DK812501	MSL750BT-DK818101	MSL750BT-EL808001
MSL750BT-DK812601	MSL750BT-DK818201	MSL750BT-EL808101
MSL750BT-DK812701	MSL750BT-DK818301	MSL750BT-EL808301
MSL750BT-DK812801	MSL750BT-DK818601	MSL750BT-EL808401
MSL750BT-DK812901	MSL750BT-DK818701	MSL750BT-EL808501
MSL750BT-DK813001	MSL750BT-DK818801	MSL750BT-EL808601
MSL750BT-DK813101	MSL750BT-DK818901	MSL750BT-EL808701
MSL750BT-DK813201	MSL750BT-DK819001	MSL750BT-EL808801
MSL750BT-DK813301	MSL750BT-DK819101	MSL750BT-EL808901
MSL750BT-DK813501	MSL750BT-DK819201	MSL750BT-EL809101
MSL750BT-DK813701	MSL750BT-DK819301	MSL750BT-EL809201
MSL750BT-DK813801	MSL750BT-DK819601	MSL750BT-EL809701
MSL750BT-DK813901	MSL750BT-DK819701	MSL750BT-EL809801
MSL750BT-DK814001	MSL750BT-DK819801	MSL750BT-EL809901
MSL750BT-DK814101	MSL750BT-DK820001	MSL750BT-EL810001
MSL750BT-DK814201	MSL750BT-DK820101	MSL750BT-EL810101
MSL750BT-DK814301	MSL750BT-DK820201	MSL750BT-EL810201
MSL750BT-DK814401	MSL750BT-DK820301	MSL750BT-EL810301
MSL750BT-DK814501	MSL750BT-DK820401	MSL750BT-EL810401
MSL750BT-DK814601	MSL750BT-DK820501	MSL750BT-EL812301
MSL750BT-DK814701	MSL750BT-DK820601	MSL750BT-EL813101

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750BT-EL813701	MSL750BT-EL829801	MSL750BT-EL840001
MSL750BT-EL813901	MSL750BT-EL829901	MSL750BT-EL840301
MSL750BT-EL814101	MSL750BT-EL830001	MSL750BT-EL840401
MSL750BT-EL816201	MSL750BT-EL830101	MSL750BT-EL840501
MSL750BT-EL816301	MSL750BT-EL830201	MSL750BT-EL840701
MSL750BT-EL816601	MSL750BT-EL830301	MSL750BT-EL841001
MSL750BT-EL817401	MSL750BT-EL830401	MSL750BT-EL841301
MSL750BT-EL818901	MSL750BT-EL830501	MSL750BT-EL841401
MSL750BT-EL819101	MSL750BT-EL830701	MSL750BT-EL841501
MSL750BT-EL820601	MSL750BT-EL830901	MSL750BT-EL842001
MSL750BT-EL820801	MSL750BT-EL831001	MSL750BT-EL842101
MSL750BT-EL820901	MSL750BT-EL831101	MSL750BT-EL842201
MSL750BT-EL821001	MSL750BT-EL831201	MSL750BT-EL842501
MSL750BT-EL821701	MSL750BT-EL831301	MSL750BT-EL842601
MSL750BT-EL822001	MSL750BT-EL831501	MSL750BT-EL842701
MSL750BT-EL822101	MSL750BT-EL831901	MSL750BT-EL842801
MSL750BT-EL822501	MSL750BT-EL832001	MSL750BT-EL842901
MSL750BT-EL823001	MSL750BT-EL832201	MSL750BT-EL842902
MSL750BT-EL823901	MSL750BT-EL832601	MSL750BT-EL842904
MSL750BT-EL824201	MSL750BT-EL832901	MSL750BT-EL843001
MSL750BT-EL825001	MSL750BT-EL833001	MSL750BT-EL843101
MSL750BT-EL825101	MSL750BT-EL833501	MSL750BT-EL843201
MSL750BT-EL825301	MSL750BT-EL833801	MSL750BT-EL843301
MSL750BT-EL825401	MSL750BT-EL834501	MSL750BT-EL843501
MSL750BT-EL825501	MSL750BT-EL834901	MSL750BT-EL843601
MSL750BT-EL825601	MSL750BT-EL836101	MSL750BT-EL843701
MSL750BT-EL825701	MSL750BT-EL836301	MSL750BT-EL843801
MSL750BT-EL825801	MSL750BT-EL836601	MSL750BT-EL843901
MSL750BT-EL825901	MSL750BT-EL836901	MSL750BT-EL844201
MSL750BT-EL826001	MSL750BT-EL837201	MSL750BT-EL844302
MSL750BT-EL826101	MSL750BT-EL837401	MSL750BT-EL844304
MSL750BT-EL826201	MSL750BT-EL837501	MSL750BT-EL844401
MSL750BT-EL826301	MSL750BT-EL837601	MSL750BT-EL844501
MSL750BT-EL826401	MSL750BT-EL837701	MSL750BT-EL844701
MSL750BT-EL826501	MSL750BT-EL837801	MSL750BT-EL844801
MSL750BT-EL826601	MSL750BT-EL837901	MSL750BT-EL844901
MSL750BT-EL826701	MSL750BT-EL838001	MSL750BT-EL845001
MSL750BT-EL826801	MSL750BT-EL838101	MSL750BT-EL845601
MSL750BT-EL826901	MSL750BT-EL838301	MSL750BT-EL845801
MSL750BT-EL827001	MSL750BT-EL838401	MSL750BT-EL845803
MSL750BT-EL827301	MSL750BT-EL838501	MSL750BT-EL846101
MSL750BT-EL827801	MSL750BT-EL838701	MSL750BT-EL846301
MSL750BT-EL828401	MSL750BT-EL838901	MSL750BT-EL846401
MSL750BT-EL828601	MSL750BT-EL839101	MSL750BT-EL846601
MSL750BT-EL828801	MSL750BT-EL839201	MSL750BT-EL846801
MSL750BT-EL829101	MSL750BT-EL839301	MSL750BT-EL847401
MSL750BT-EL829201	MSL750BT-EL839601	MSL750BT-EL847501
MSL750BT-EL829301	MSL750BT-EL839701	MSL750BT-EL847701
MSL750BT-EL829601	MSL750BT-EL839801	MSL750BT-EL848101

USCGC BERTHOLF (WMSL 750) 5/8/2008

MSL750BT-EL849001	MSL750BT-EL867001	MSL750BT-EL872601
MSL750BT-EL849601	MSL750BT-EL867101	MSL750BT-EL872701
MSL750BT-EL849701	MSL750BT-EL867201	MSL750BT-EL872801
MSL750BT-EL850201	MSL750BT-EL867301	MSL750BT-EL872901
MSL750BT-EL850401	MSL750BT-EL867401	MSL750BT-EL873001
MSL750BT-EL852001	MSL750BT-EL867501	MSL750BT-EL873101
MSL750BT-EL852601	MSL750BT-EL867601	MSL750BT-EL873201
MSL750BT-EL853201	MSL750BT-EL867701	MSL750BT-EL873301
MSL750BT-EL853401	MSL750BT-EL867801	MSL750BT-EP800601
MSL750BT-EL853501	MSL750BT-EL867901	MSL750BT-EP800701
MSL750BT-EL853601	MSL750BT-EL868001	MSL750BT-HB400401
MSL750BT-EL853901	MSL750BT-EL868201	MSL750BT-HB801201
MSL750BT-EL859001	MSL750BT-EL868301	MSL750BT-HB802501
MSL750BT-EL859301	MSL750BT-EL868401	MSL750BT-HB802901
MSL750BT-EL859801	MSL750BT-EL868501	MSL750BT-HB805601
MSL750BT-EL859901	MSL750BT-EL868601	MSL750BT-HB806101
MSL750BT-EL860101	MSL750BT-EL868701	MSL750BT-HB806601
MSL750BT-EL860601	MSL750BT-EL868801	MSL750BT-HB807401
MSL750BT-EL860701	MSL750BT-EL868901	MSL750BT-HB807501
MSL750BT-EL860801	MSL750BT-EL869001	MSL750BT-HB808001
MSL750BT-EL860901	MSL750BT-EL869101	MSL750BT-HB808401
MSL750BT-EL861001	MSL750BT-EL869301	MSL750BT-HB809401
MSL750BT-EL861101	MSL750BT-EL869401	MSL750BT-HB810401
MSL750BT-EL861201	MSL750BT-EL869501	MSL750BT-HB810701
MSL750BT-EL861301	MSL750BT-EL869701	MSL750BT-HB811001
MSL750BT-EL861401	MSL750BT-EL869801	MSL750BT-HB811501
MSL750BT-EL861601	MSL750BT-EL869901	MSL750BT-HB811601
MSL750BT-EL861701	MSL750BT-EL870001	MSL750BT-HB811701
MSL750BT-EL861801	MSL750BT-EL870101	MSL750BT-HB811801
MSL750BT-EL861901	MSL750BT-EL870301	MSL750BT-HB813401
MSL750BT-EL862001	MSL750BT-EL870401	MSL750BT-HB814101
MSL750BT-EL862101	MSL750BT-EL870601	MSL750BT-HB814901
MSL750BT-EL862201	MSL750BT-EL870701	MSL750BT-HB815601
MSL750BT-EL862801	MSL750BT-EL870801	MSL750BT-HB815701
MSL750BT-EL863001	MSL750BT-EL870901	MSL750BT-HB816101
MSL750BT-EL864001	MSL750BT-EL871001	MSL750BT-HB816301
MSL750BT-EL864101	MSL750BT-EL871101	MSL750BT-HB816701
MSL750BT-EL864401	MSL750BT-EL871201	MSL750BT-HB816901
MSL750BT-EL864701	MSL750BT-EL871301	MSL750BT-HB817401
MSL750BT-EL864801	MSL750BT-EL871401	MSL750BT-HB818101
MSL750BT-EL864901	MSL750BT-EL871501	MSL750BT-HB818201
MSL750BT-EL865101	MSL750BT-EL871701	MSL750BT-HB818301
MSL750BT-EL865201	MSL750BT-EL871801	MSL750BT-HB818401
MSL750BT-EL865301	MSL750BT-EL871901	MSL750BT-HB818501
MSL750BT-EL865401	MSL750BT-EL872001	MSL750BT-HB818601
MSL750BT-EL865601	MSL750BT-EL872101	MSL750BT-HB819701
MSL750BT-EL865701	MSL750BT-EL872201	MSL750BT-HB819901
MSL750BT-EL866301	MSL750BT-EL872301	MSL750BT-HB820001
MSL750BT-EL866401	MSL750BT-EL872501	MSL750BT-HB820201

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750BT-HB820301	MSL750BT-HB835701	MSL750BT-HB851801
MSL750BT-HB820901	MSL750BT-HB835901	MSL750BT-HB852001
MSL750BT-HB821001	MSL750BT-HB836201	MSL750BT-HB852101
MSL750BT-HB822601	MSL750BT-HB836601	MSL750BT-HB852201
MSL750BT-HB822701	MSL750BT-HB836901	MSL750BT-HB852301
MSL750BT-HB822901	MSL750BT-HB837301	MSL750BT-HB852401
MSL750BT-HB823901	MSL750BT-HB837601	MSL750BT-IS405101
MSL750BT-HB824001	MSL750BT-HB837901	MSL750BT-IS405301
MSL750BT-HB824201	MSL750BT-HB838201	MSL750BT-IS406501
MSL750BT-HB824601	MSL750BT-HB838501	MSL750BT-IS407001
MSL750BT-HB824801	MSL750BT-HB838801	MSL750BT-IS407301
MSL750BT-HB824901	MSL750BT-HB839801	MSL750BT-IS408101
MSL750BT-HB825001	MSL750BT-HB840001	MSL750BT-IS410901
MSL750BT-HB825101	MSL750BT-HB840501	MSL750BT-IS412001
MSL750BT-HB825201	MSL750BT-HB840701	MSL750BT-IS412301
MSL750BT-HB825401	MSL750BT-HB840801	MSL750BT-IS414401
MSL750BT-HB826101	MSL750BT-HB841101	MSL750BT-IS414601
MSL750BT-HB826201	MSL750BT-HB842301	MSL750BT-IS414701
MSL750BT-HB826501	MSL750BT-HB843101	MSL750BT-IS414901
MSL750BT-HB827501	MSL750BT-HB843401	MSL750BT-IS415201
MSL750BT-HB827701	MSL750BT-HB843501	MSL750BT-IS800201
MSL750BT-HB827801	MSL750BT-HB843601	MSL750BT-IS800301
MSL750BT-HB827901	MSL750BT-HB844001	MSL750BT-IS800501
MSL750BT-HB828001	MSL750BT-HB844101	MSL750BT-IS800601
MSL750BT-HB828101	MSL750BT-HB845301	MSL750BT-IS800701
MSL750BT-HB828201	MSL750BT-HB845801	MSL750BT-IS800801
MSL750BT-HB828301	MSL750BT-HB846001	MSL750BT-IS800901
MSL750BT-HB828401	MSL750BT-HB846701	MSL750BT-IS801001
MSL750BT-HB828501	MSL750BT-HB847301	MSL750BT-IS801201
MSL750BT-HB828701	MSL750BT-HB847801	MSL750BT-MD400101
MSL750BT-HB828901	MSL750BT-HB848101	MSL750BT-MD800301
MSL750BT-HB829001	MSL750BT-HB848201	MSL750BT-MD800401
MSL750BT-HB829101	MSL750BT-HB848301	MSL750BT-MD800501
MSL750BT-HB829201	MSL750BT-HB848701	MSL750BT-MD800601
MSL750BT-HB829301	MSL750BT-HB848801	MSL750BT-MD801001
MSL750BT-HB829701	MSL750BT-HB848901	MSL750BT-MD801101
MSL750BT-HB829901	MSL750BT-HB849001	MSL750BT-MD801201
MSL750BT-HB831101	MSL750BT-HB849301	MSL750BT-MD801301
MSL750BT-HB831801	MSL750BT-HB849701	MSL750BT-MD801501
MSL750BT-HB832301	MSL750BT-HB850001	MSL750BT-MD801601
MSL750BT-HB832501	MSL750BT-HB850501	MSL750BT-MD801701
MSL750BT-HB832801	MSL750BT-HB850601	MSL750BT-MD801901
MSL750BT-HB833001	MSL750BT-HB850701	MSL750BT-MD802001
MSL750BT-HB833501	MSL750BT-HB850901	MSL750BT-MD802201
MSL750BT-HB833801	MSL750BT-HB851001	MSL750BT-MD802601
MSL750BT-HB834001	MSL750BT-HB851101	MSL750BT-MD802701
MSL750BT-HB834501	MSL750BT-HB851201	MSL750BT-MD802801
MSL750BT-HB834701	MSL750BT-HB851501	MSL750BT-MD802901
MSL750BT-HB835401	MSL750BT-HB851601	MSL750BT-MD803501

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750BT-MD803601	MSL750BT-MP809201	MSL750BT-MP817601
MSL750BT-MD803701	MSL750BT-MP809401	MSL750BT-MP817701
MSL750BT-MD804101	MSL750BT-MP809501	MSL750BT-MP817801
MSL750BT-MD805001	MSL750BT-MP809601	MSL750BT-MP817901
MSL750BT-MP800101	MSL750BT-MP809701	MSL750BT-MP818001
MSL750BT-MP800701	MSL750BT-MP809901	MSL750BT-MP818101
MSL750BT-MP800801	MSL750BT-MP810001	MSL750BT-MP818201
MSL750BT-MP801001	MSL750BT-MP810201	MSL750BT-MP818301
MSL750BT-MP801101	MSL750BT-MP810301	MSL750BT-MP818401
MSL750BT-MP801201	MSL750BT-MP810401	MSL750BT-MP818501
MSL750BT-MP801401	MSL750BT-MP810501	MSL750BT-MP818601
MSL750BT-MP801501	MSL750BT-MP810601	MSL750BT-MP818701
MSL750BT-MP801601	MSL750BT-MP810801	MSL750BT-MP818801
MSL750BT-MP801701	MSL750BT-MP810901	MSL750BT-MP818901
MSL750BT-MP802701	MSL750BT-MP811101	MSL750BT-MP819001
MSL750BT-MP802801	MSL750BT-MP811401	MSL750BT-MP819101
MSL750BT-MP802901	MSL750BT-MP811501	MSL750BT-MP819301
MSL750BT-MP803001	MSL750BT-MP811601	MSL750BT-MP819401
MSL750BT-MP803101	MSL750BT-MP811701	MSL750BT-MP819701
MSL750BT-MP803701	MSL750BT-MP811801	MSL750BT-MP819801
MSL750BT-MP803801	MSL750BT-MP811901	MSL750BT-MP819901
MSL750BT-MP803901	MSL750BT-MP812001	MSL750BT-MP820201
MSL750BT-MP804301	MSL750BT-MP812101	MSL750BT-MP820401
MSL750BT-MP804601	MSL750BT-MP812201	MSL750BT-MP820501
MSL750BT-MP804701	MSL750BT-MP812501	MSL750BT-MP820601
MSL750BT-MP804801	MSL750BT-MP812801	MSL750BT-MP820701
MSL750BT-MP805101	MSL750BT-MP812901	MSL750BT-MP820801
MSL750BT-MP805201	MSL750BT-MP813001	MSL750BT-MP820901
MSL750BT-MP805301	MSL750BT-MP813101	MSL750BT-MP821201
MSL750BT-MP805401	MSL750BT-MP813301	MSL750BT-MP821301
MSL750BT-MP805501	MSL750BT-MP813401	MSL750BT-MP821401
MSL750BT-MP805601	MSL750BT-MP813501	MSL750BT-MP821501
MSL750BT-MP805701	MSL750BT-MP813601	MSL750BT-MP821601
MSL750BT-MP805801	MSL750BT-MP813801	MSL750BT-MP821701
MSL750BT-MP806001	MSL750BT-MP813901	MSL750BT-MP822001
MSL750BT-MP806101	MSL750BT-MP814301	MSL750BT-MP822101
MSL750BT-MP806201	MSL750BT-MP814601	MSL750BT-MP822201
MSL750BT-MP806401	MSL750BT-MP814701	MSL750BT-MP822401
MSL750BT-MP807101	MSL750BT-MP815001	MSL750BT-MP823001
MSL750BT-MP807501	MSL750BT-MP815101	MSL750BT-MP823101
MSL750BT-MP807801	MSL750BT-MP815401	MSL750BT-MP823301
MSL750BT-MP807901	MSL750BT-MP815701	MSL750BT-NV404601
MSL750BT-MP808001	MSL750BT-MP815801	MSL750BT-NV404701
MSL750BT-MP808101	MSL750BT-MP816201	MSL750BT-NV800101
MSL750BT-MP808401	MSL750BT-MP816301	MSL750BT-NV800301
MSL750BT-MP808501	MSL750BT-MP816401	MSL750BT-NV800401
MSL750BT-MP808701	MSL750BT-MP817101	MSL750BT-NV800501
MSL750BT-MP808801	MSL750BT-MP817201	MSL750BT-NV800601
MSL750BT-MP808901	MSL750BT-MP817401	MSL750BT-NV800701

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750BT-NV801001	MSL750BT-OH802401	MSL750BT-OP423801
MSL750BT-NV801401	MSL750BT-OH802501	MSL750BT-OP423901
MSL750BT-NV801901	MSL750BT-OH802701	MSL750BT-OP424001
MSL750BT-NV802001	MSL750BT-OH802901	MSL750BT-OP424101
MSL750BT-NV802401	MSL750BT-OH803201	MSL750BT-OP424201
MSL750BT-NV802501	MSL750BT-OH803501	MSL750BT-OP424301
MSL750BT-NV802601	MSL750BT-OH803601	MSL750BT-OP424401
MSL750BT-NV802801	MSL750BT-OH803701	MSL750BT-OP424501
MSL750BT-NV803101	MSL750BT-OH804101	MSL750BT-OP424601
MSL750BT-NV803401	MSL750BT-OH804301	MSL750BT-OP426001
MSL750BT-NV803601	MSL750BT-OH804501	MSL750BT-OP426201
MSL750BT-NV803901	MSL750BT-OH804701	MSL750BT-OP426301
MSL750BT-NV804101	MSL750BT-OH804901	MSL750BT-OP426401
MSL750BT-NV804601	MSL750BT-OH805201	MSL750BT-OP426501
MSL750BT-NV805001	MSL750BT-OH805301	MSL750BT-OP427201
MSL750BT-NV805101	MSL750BT-OH805401	MSL750BT-OP427301
MSL750BT-NV805501	MSL750BT-OH805801	MSL750BT-OP427901
MSL750BT-NV805601	MSL750BT-OH805901	MSL750BT-OP428201
MSL750BT-NV805701	MSL750BT-OH806101	MSL750BT-OP428401
MSL750BT-NV805801	MSL750BT-OH806201	MSL750BT-OP428701
MSL750BT-NV805901	MSL750BT-OH806701	MSL750BT-OP428801
MSL750BT-NV806001	MSL750BT-OP407301	MSL750BT-OP428901
MSL750BT-NV806101	MSL750BT-OP410301	MSL750BT-OP429001
MSL750BT-NV806201	MSL750BT-OP411201	MSL750BT-OP429101
MSL750BT-NV806301	MSL750BT-OP411601	MSL750BT-OP429201
MSL750BT-NV806401	MSL750BT-OP411901	MSL750BT-OP429301
MSL750BT-NV806501	MSL750BT-OP415001	MSL750BT-OP429601
MSL750BT-NV806601	MSL750BT-OP416801	MSL750BT-OP429801
MSL750BT-NV806701	MSL750BT-OP418401	MSL750BT-OP429901
MSL750BT-NV806801	MSL750BT-OP418901	MSL750BT-OP430001
MSL750BT-NV806901	MSL750BT-OP419001	MSL750BT-OP430101
MSL750BT-NV807001	MSL750BT-OP419101	MSL750BT-OP430201
MSL750BT-OH800201	MSL750BT-OP419201	MSL750BT-OP430301
MSL750BT-OH800301	MSL750BT-OP419301	MSL750BT-OP430401
MSL750BT-OH800401	MSL750BT-OP420501	MSL750BT-OP430901
MSL750BT-OH800501	MSL750BT-OP421401	MSL750BT-OP431101
MSL750BT-OH800701	MSL750BT-OP421601	MSL750BT-OP431201
MSL750BT-OH800801	MSL750BT-OP421701	MSL750BT-OP431301
MSL750BT-OH800901	MSL750BT-OP421801	MSL750BT-OP432001
MSL750BT-OH801001	MSL750BT-OP422001	MSL750BT-OP432201
MSL750BT-OH801101	MSL750BT-OP422201	MSL750BT-OP432401
MSL750BT-OH801201	MSL750BT-OP422301	MSL750BT-OP432501
MSL750BT-OH801301	MSL750BT-OP422401	MSL750BT-OP432901
MSL750BT-OH801601	MSL750BT-OP422601	MSL750BT-OP433201
MSL750BT-OH801701	MSL750BT-OP423201	MSL750BT-OP800201
MSL750BT-OH801801	MSL750BT-OP423301	MSL750BT-OP800301
MSL750BT-OH801901	MSL750BT-OP423401	MSL750BT-OP800401
MSL750BT-OH802001	MSL750BT-OP423601	MSL750BT-OP800501
MSL750BT-OH802101	MSL750BT-OP423701	MSL750BT-OP800601

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750BT-OP801001	MSL750BT-WP801301	MSL750MT-AX719501
MSL750BT-OP801101	MSL750BT-WP801501	MSL750MT-AX720001
MSL750BT-OP801301	MSL750MT-AV701701	MSL750MT-AX720101
MSL750BT-OP801401	MSL750MT-AV702201	MSL750MT-AX720201
MSL750BT-OP801501	MSL750MT-AV703001	MSL750MT-AX720401
MSL750BT-OP801801	MSL750MT-AV703201	MSL750MT-AX721001
MSL750BT-OP802201	MSL750MT-AX700701	MSL750MT-AX722701
MSL750BT-OP803001	MSL750MT-AX700801	MSL750MT-AX722801
MSL750BT-OP803101	MSL750MT-AX701801	MSL750MT-AX723101
MSL750BT-OP803201	MSL750MT-AX701901	MSL750MT-AX724101
MSL750BT-OP803401	MSL750MT-AX703201	MSL750MT-AX724501
MSL750BT-OP803801	MSL750MT-AX703701	MSL750MT-AX725101
MSL750BT-OP804301	MSL750MT-AX704301	MSL750MT-AX726001
MSL750BT-OP804501	MSL750MT-AX704401	MSL750MT-AX726101
MSL750BT-OP804601	MSL750MT-AX704701	MSL750MT-AX726401
MSL750BT-OP804701	MSL750MT-AX705701	MSL750MT-AX726402
MSL750BT-OP804801	MSL750MT-AX705901	MSL750MT-AX726601
MSL750BT-OP804901	MSL750MT-AX706201	MSL750MT-AX728101
MSL750BT-OP805001	MSL750MT-AX706601	MSL750MT-AX728301
MSL750BT-OP805101	MSL750MT-AX707101	MSL750MT-AX728801
MSL750BT-OP805301	MSL750MT-AX707501	MSL750MT-AX729201
MSL750BT-SP800101	MSL750MT-AX708701	MSL750MT-AX730101
MSL750BT-VT800301	MSL750MT-AX708901	MSL750MT-AX730701
MSL750BT-VT800701	MSL750MT-AX709101	MSL750MT-AX735201
MSL750BT-VT800801	MSL750MT-AX709601	MSL750MT-AX735301
MSL750BT-VT800901	MSL750MT-AX709701	MSL750MT-AX735501
MSL750BT-VT801001	MSL750MT-AX709801	MSL750MT-AX736001
MSL750BT-VT801301	MSL750MT-AX710401	MSL750MT-AX737701
MSL750BT-VT801401	MSL750MT-AX710501	MSL750MT-AX740301
MSL750BT-VT801601	MSL750MT-AX710601	MSL750MT-AX741001
MSL750BT-VT801801	MSL750MT-AX711801	MSL750MT-AX741201
MSL750BT-VT802201	MSL750MT-AX715101	MSL750MT-AX743201
MSL750BT-VT802301	MSL750MT-AX715201	MSL750MT-AX743301
MSL750BT-VT802501	MSL750MT-AX715401	MSL750MT-AX743401
MSL750BT-VT802801	MSL750MT-AX715801	MSL750MT-AX743501
MSL750BT-VT803101	MSL750MT-AX715901	MSL750MT-AX743801
MSL750BT-VT803301	MSL750MT-AX716301	MSL750MT-AX743901
MSL750BT-VT803501	MSL750MT-AX716401	MSL750MT-AX744101
MSL750BT-VT803701	MSL750MT-AX716701	MSL750MT-AX745601
MSL750BT-VT804001	MSL750MT-AX717301	MSL750MT-AX746001
MSL750BT-VT804201	MSL750MT-AX717401	MSL750MT-AX746501
MSL750BT-VT804301	MSL750MT-AX717501	MSL750MT-AX748101
MSL750BT-VT804401	MSL750MT-AX717901	MSL750MT-AX748401
MSL750BT-VT804601	MSL750MT-AX718801	MSL750MT-AX748501
MSL750BT-WP400801	MSL750MT-AX718901	MSL750MT-AX751701
MSL750BT-WP800301	MSL750MT-AX719001	MSL750MT-AX753301
MSL750BT-WP800501	MSL750MT-AX719101	MSL750MT-AX753401
MSL750BT-WP800601	MSL750MT-AX719301	MSL750MT-AX753601
MSL750BT-WP801201	MSL750MT-AX719401	MSL750MT-AX753701

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750MT-AX753702	MSL750MT-DC706201	MSL750MT-DC743301
MSL750MT-AX753801	MSL750MT-DC706501	MSL750MT-DC744401
MSL750MT-AX754401	MSL750MT-DC707301	MSL750MT-DC744901
MSL750MT-AX754901	MSL750MT-DC707401	MSL750MT-DC745401
MSL750MT-AX755201	MSL750MT-DC707701	MSL750MT-DC749101
MSL750MT-AX756401	MSL750MT-DC707801	MSL750MT-DC749801
MSL750MT-AX756501	MSL750MT-DC707901	MSL750MT-DC750001
MSL750MT-AX756701	MSL750MT-DC708001	MSL750MT-DK700301
MSL750MT-AX756801	MSL750MT-DC709101	MSL750MT-DK700401
MSL750MT-AX758101	MSL750MT-DC710001	MSL750MT-DK700901
MSL750MT-AX758201	MSL750MT-DC712101	MSL750MT-DK701001
MSL750MT-AX758301	MSL750MT-DC714001	MSL750MT-DK701201
MSL750MT-AX758901	MSL750MT-DC714601	MSL750MT-DK701301
MSL750MT-AX759501	MSL750MT-DC714701	MSL750MT-DK701601
MSL750MT-AX759601	MSL750MT-DC714901	MSL750MT-DK701701
MSL750MT-AX759701	MSL750MT-DC720501	MSL750MT-DK702001
MSL750MT-CC700401	MSL750MT-DC720601	MSL750MT-DK702101
MSL750MT-CC700801	MSL750MT-DC721301	MSL750MT-DK703201
MSL750MT-CC701401	MSL750MT-DC721501	MSL750MT-DK703301
MSL750MT-CC701501	MSL750MT-DC721601	MSL750MT-DK703401
MSL750MT-CC704101	MSL750MT-DC723601	MSL750MT-DK703501
MSL750MT-CC704201	MSL750MT-DC724801	MSL750MT-DK703601
MSL750MT-CC704301	MSL750MT-DC725601	MSL750MT-DK704301
MSL750MT-CC704401	MSL750MT-DC726501	MSL750MT-DK704901
MSL750MT-CC704801	MSL750MT-DC726801	MSL750MT-DK707401
MSL750MT-CC704901	MSL750MT-DC726901	MSL750MT-DK707501
MSL750MT-CC705001	MSL750MT-DC727501	MSL750MT-DK708301
MSL750MT-CC705101	MSL750MT-DC727801	MSL750MT-DK708501
MSL750MT-CC705501	MSL750MT-DC727901	MSL750MT-DK708601
MSL750MT-CC706701	MSL750MT-DC728101	MSL750MT-DK708701
MSL750MT-CC706801	MSL750MT-DC728201	MSL750MT-DK708801
MSL750MT-CC706901	MSL750MT-DC728301	MSL750MT-DK709801
MSL750MT-CC707001	MSL750MT-DC729501	MSL750MT-EL700701
MSL750MT-CC710501	MSL750MT-DC730001	MSL750MT-EL701401
MSL750MT-CC712201	MSL750MT-DC730201	MSL750MT-EL701601
MSL750MT-CC715201	MSL750MT-DC730301	MSL750MT-EL702001
MSL750MT-CC715501	MSL750MT-DC733901	MSL750MT-EL702101
MSL750MT-DC700601	MSL750MT-DC735001	MSL750MT-EL702201
MSL750MT-DC700901	MSL750MT-DC736401	MSL750MT-EL702501
MSL750MT-DC701701	MSL750MT-DC736501	MSL750MT-EL703401
MSL750MT-DC702301	MSL750MT-DC741201	MSL750MT-EL704001
MSL750MT-DC702401	MSL750MT-DC741501	MSL750MT-EL704201
MSL750MT-DC702601	MSL750MT-DC741801	MSL750MT-EL704801
MSL750MT-DC702701	MSL750MT-DC741901	MSL750MT-EL705001
MSL750MT-DC702801	MSL750MT-DC742201	MSL750MT-EL705101
MSL750MT-DC702901	MSL750MT-DC742401	MSL750MT-EL705201
MSL750MT-DC703001	MSL750MT-DC742501	MSL750MT-EL705401
MSL750MT-DC703101	MSL750MT-DC742801	MSL750MT-EL705501
MSL750MT-DC704501	MSL750MT-DC743101	MSL750MT-EL705701

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750MT-EL706501	MSL750MT-EL723801	MSL750MT-EL734601
MSL750MT-EL706701	MSL750MT-EL723901	MSL750MT-EL734701
MSL750MT-EL707601	MSL750MT-EL724201	MSL750MT-EL735301
MSL750MT-EL707801	MSL750MT-EL724301	MSL750MT-EL735801
MSL750MT-EL707901	MSL750MT-EL724501	MSL750MT-EL736301
MSL750MT-EL708001	MSL750MT-EL724801	MSL750MT-EL736901
MSL750MT-EL709501	MSL750MT-EL725001	MSL750MT-EL737101
MSL750MT-EL709701	MSL750MT-EL725101	MSL750MT-EL737201
MSL750MT-EL709801	MSL750MT-EL725201	MSL750MT-EL737601
MSL750MT-EL709901	MSL750MT-EL725401	MSL750MT-EL738001
MSL750MT-EL710001	MSL750MT-EL726201	MSL750MT-EL738401
MSL750MT-EL710501	MSL750MT-EL726301	MSL750MT-EL738601
MSL750MT-EL711601	MSL750MT-EL726401	MSL750MT-EL738701
MSL750MT-EL711701	MSL750MT-EL726501	MSL750MT-EL738801
MSL750MT-EL712001	MSL750MT-EL726601	MSL750MT-EL738901
MSL750MT-EL712201	MSL750MT-EL727401	MSL750MT-EL739001
MSL750MT-EL712301	MSL750MT-EL727501	MSL750MT-EL739101
MSL750MT-EL712801	MSL750MT-EL727601	MSL750MT-EL739201
MSL750MT-EL713501	MSL750MT-EL727901	MSL750MT-EL739401
MSL750MT-EL714901	MSL750MT-EL728101	MSL750MT-EL739601
MSL750MT-EL715001	MSL750MT-EL728201	MSL750MT-EL739701
MSL750MT-EL715101	MSL750MT-EL728301	MSL750MT-EL739901
MSL750MT-EL715201	MSL750MT-EL729001	MSL750MT-EL740101
MSL750MT-EL715301	MSL750MT-EL729101	MSL750MT-EL740201
MSL750MT-EL715401	MSL750MT-EL729201	MSL750MT-EL740701
MSL750MT-EL715501	MSL750MT-EL729401	MSL750MT-EL740801
MSL750MT-EL715601	MSL750MT-EL729801	MSL750MT-EL740901
MSL750MT-EL716001	MSL750MT-EL730001	MSL750MT-EL741001
MSL750MT-EL716401	MSL750MT-EL730801	MSL750MT-EL741201
MSL750MT-EL717001	MSL750MT-EL731001	MSL750MT-EL741301
MSL750MT-EL717101	MSL750MT-EL731501	MSL750MT-EL741401
MSL750MT-EL717501	MSL750MT-EL731601	MSL750MT-EL741501
MSL750MT-EL717901	MSL750MT-EL731701	MSL750MT-EL741601
MSL750MT-EL718001	MSL750MT-EL731801	MSL750MT-EL741701
MSL750MT-EL718201	MSL750MT-EL732301	MSL750MT-EL742001
MSL750MT-EL718801	MSL750MT-EL732501	MSL750MT-EL742101
MSL750MT-EL719301	MSL750MT-EL732601	MSL750MT-EL742201
MSL750MT-EL719601	MSL750MT-EL732901	MSL750MT-EL742301
MSL750MT-EL719701	MSL750MT-EL733101	MSL750MT-EL742401
MSL750MT-EL719801	MSL750MT-EL733201	MSL750MT-EL742501
MSL750MT-EL720401	MSL750MT-EL733301	MSL750MT-EL742601
MSL750MT-EL720501	MSL750MT-EL733501	MSL750MT-EL742701
MSL750MT-EL720601	MSL750MT-EL733601	MSL750MT-EL742801
MSL750MT-EL721001	MSL750MT-EL733801	MSL750MT-EL742901
MSL750MT-EL721101	MSL750MT-EL733901	MSL750MT-EL743101
MSL750MT-EL721301	MSL750MT-EL734001	MSL750MT-EL743201
MSL750MT-EL721601	MSL750MT-EL734101	MSL750MT-EL743301
MSL750MT-EL721801	MSL750MT-EL734301	MSL750MT-EL743401
MSL750MT-EL722901	MSL750MT-EL734401	MSL750MT-EL743501

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750MT-EL743701	MSL750MT-HB710201	MSL750MT-HB735201
MSL750MT-EL743901	MSL750MT-HB710401	MSL750MT-HB735401
MSL750MT-EL744101	MSL750MT-HB710501	MSL750MT-HB735901
MSL750MT-EL744201	MSL750MT-HB711201	MSL750MT-HB736301
MSL750MT-EL744301	MSL750MT-HB711401	MSL750MT-HB736601
MSL750MT-EL744401	MSL750MT-HB711501	MSL750MT-HB736701
MSL750MT-EL744601	MSL750MT-HB712001	MSL750MT-HB736801
MSL750MT-EL745501	MSL750MT-HB712201	MSL750MT-HB737501
MSL750MT-EL745601	MSL750MT-HB712601	MSL750MT-HB738801
MSL750MT-EP201401	MSL750MT-HB713201	MSL750MT-HB739001
MSL750MT-EP201501	MSL750MT-HB713301	MSL750MT-HB739101
MSL750MT-EP201801	MSL750MT-HB713501	MSL750MT-HB739601
MSL750MT-EP202102	MSL750MT-HB713601	MSL750MT-IS700101
MSL750MT-EP202301	MSL750MT-HB713701	MSL750MT-MD700101
MSL750MT-EP202901	MSL750MT-HB714101	MSL750MT-MD700301
MSL750MT-EP203101	MSL750MT-HB714401	MSL750MT-MP700301
MSL750MT-EP204901	MSL750MT-HB714501	MSL750MT-MP700401
MSL750MT-EP700201	MSL750MT-HB714601	MSL750MT-MP700501
MSL750MT-EP700801	MSL750MT-HB714901	MSL750MT-MP700901
MSL750MT-EP701001	MSL750MT-HB715401	MSL750MT-MP701001
MSL750MT-EP701601	MSL750MT-HB715601	MSL750MT-MP701101
MSL750MT-HB700201	MSL750MT-HB715801	MSL750MT-MP701201
MSL750MT-HB700301	MSL750MT-HB716101	MSL750MT-MP701301
MSL750MT-HB700701	MSL750MT-HB716901	MSL750MT-MP701701
MSL750MT-HB700901	MSL750MT-HB717101	MSL750MT-MP701801
MSL750MT-HB701101	MSL750MT-HB717601	MSL750MT-MP702301
MSL750MT-HB701201	MSL750MT-HB717701	MSL750MT-MP702701
MSL750MT-HB702201	MSL750MT-HB717801	MSL750MT-MP702901
MSL750MT-HB702301	MSL750MT-HB717901	MSL750MT-MP703201
MSL750MT-HB702501	MSL750MT-HB718101	MSL750MT-MP703401
MSL750MT-HB703401	MSL750MT-HB718701	MSL750MT-MP703601
MSL750MT-HB704001	MSL750MT-HB718801	MSL750MT-MP703901
MSL750MT-HB704501	MSL750MT-HB718901	MSL750MT-MP704001
MSL750MT-HB704601	MSL750MT-HB720601	MSL750MT-MP704501
MSL750MT-HB705001	MSL750MT-HB723901	MSL750MT-MP704701
MSL750MT-HB705201	MSL750MT-HB724101	MSL750MT-MP704801
MSL750MT-HB706201	MSL750MT-HB726601	MSL750MT-MP705501
MSL750MT-HB706301	MSL750MT-HB727401	MSL750MT-MP705601
MSL750MT-HB706801	MSL750MT-HB728101	MSL750MT-MP707101
MSL750MT-HB706901	MSL750MT-HB728201	MSL750MT-MP707401
MSL750MT-HB707001	MSL750MT-HB728401	MSL750MT-MP707501
MSL750MT-HB707201	MSL750MT-HB728701	MSL750MT-MP707701
MSL750MT-HB708001	MSL750MT-HB729201	MSL750MT-MP708101
MSL750MT-HB708501	MSL750MT-HB731201	MSL750MT-MP708501
MSL750MT-HB709401	MSL750MT-HB731301	MSL750MT-MP708901
MSL750MT-HB709501	MSL750MT-HB731401	MSL750MT-MP709701
MSL750MT-HB709701	MSL750MT-HB731501	MSL750MT-MP709801
MSL750MT-HB709801	MSL750MT-HB731601	MSL750MT-MP709901
MSL750MT-HB709901	MSL750MT-HB732101	MSL750MT-MP710601

USCGC BERTHOLF (WMSL 750) 5/8/2008

MSL750MT-MP710701	MSL750MT-NV702901	MSL750MT-OP703501
MSL750MT-MP711001	MSL750MT-NV703801	MSL750MT-OP703601
MSL750MT-MP712401	MSL750MT-NV704001	MSL750MT-OP703701
MSL750MT-MP712501	MSL750MT-NV704101	MSL750MT-OP703801
MSL750MT-MP712601	MSL750MT-NV704201	MSL750MT-OP703901
MSL750MT-MP712701	MSL750MT-NV704601	MSL750MT-OP704001
MSL750MT-MP713301	MSL750MT-NV704701	MSL750MT-OP704201
MSL750MT-MP713601	MSL750MT-NV705001	MSL750MT-OP704301
MSL750MT-MP713701	MSL750MT-NV705801	MSL750MT-SP700701
MSL750MT-MP714001	MSL750MT-OH700401	MSL750MT-VT700401
MSL750MT-MP714101	MSL750MT-OH700501	MSL750MT-VT701201
MSL750MT-MP714601	MSL750MT-OH700601	MSL750MT-VT701301
MSL750MT-MP714701	MSL750MT-OH700701	MSL750MT-VT701601
MSL750MT-MP714801	MSL750MT-OH700801	MSL750MT-VT701701
MSL750MT-NV700501	MSL750MT-OH700901	MSL750MT-VT701801
MSL750MT-NV700801	MSL750MT-OH701001	MSL750MT-VT701901
MSL750MT-NV701001	MSL750MT-OH701701	MSL750MT-VT703001
MSL750MT-NV701201	MSL750MT-OH701801	MSL750MT-VT703801
MSL750MT-NV701301	MSL750MT-OP702501	MSL750MT-VT703901
MSL750MT-NV701401	MSL750MT-OP702601	MSL750MT-WP702801
MSL750MT-NV701501	MSL750MT-OP703001	MSL750MT-WP703201
MSL750MT-NV702001	MSL750MT-OP703101	MSL750MT-WP703301
MSL750MT-NV702101	MSL750MT-OP703201	MSL750MT-WP703601
MSL750MT-NV702301	MSL750MT-OP703301	
MSL750MT-NV702401	MSL750MT-OP703401	

△Government and Contractor Assigned Trial Cards Pending Final Resolution

MSL750AT-SP006901	MSL750BT-OP410001	MSL750MT-AX710701
MSL750AT-SP006601	MSL750BT-CC418301	MSL750MT-AX709201
MSL750AT-SP007201	MSL750BT-OP412101	MSL750MT-DC733801
MSL750AT-SP007101	MSL750BT-CC419301	MSL750MT-AX718701
MSL750AT-AV002901	MSL750BT-CC419401	MSL750MT-EL731301
MSL750AT-SP006501	MSL750BT-CC418701	MSL750MT-EP202101
MSL750AT-SP007301	MSL750BT-CC418801	MSL750MT-AX702601
MSL750AT-NV001601	MSL750BT-EL827601	MSL750MT-AX710801
MSL750AT-VT005401	MSL750BT-EL828701	MSL750AT-CC001901
MSL750AT-DC054301	MSL750BT-EL828301	MSL750AT-SP005101
MSL750AT-AX006001	MSL750BT-HB844501	MSL750AT-SP007701
MSL750AT-CC004101	MSL750BT-EL813601	MSL750AT-SP004701
MSL750AT-CC003501	MSL750BT-EL844101	MSL750AT-SP007501
MSL750AT-CC002801	MSL750BT-AX813701	MSL750AT-EP005401
MSL750AT-CC003101	MSL750BT-HB806201	MSL750AT-EP013201
MSL750AT-CC003801	MSL750BT-DC804001	MSL750AT-HB046301
MSL750AT-CC003401	MSL750BT-DC810101	MSL750AT-SP000501
MSL750AT-CC004301	MSL750BT-EL845501	MSL750AT-AV002301
MSL750AT-CC003301	MSL750BT-EL840901	MSL750AT-AV003001
MSL750AT-OP001201	MSL750BT-IS801301	MSL750AT-EP005801

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750AT-AV003101	MSL750AT-AX015601	MSL750BT-OP427501
MSL750AT-DC036901	MSL750AT-AX015501	MSL750BT-OP431901
MSL750AT-EP000601	MSL750AT-AX016801	MSL750BT-OP431801
MSL750AT-AV001901	MSL750AT-AX016101	MSL750BT-OP417401
MSL750AT-AV003701	MSL750AT-AX016201	MSL750BT-AX402001
MSL750AT-AV001701	MSL750AT-AX016301	MSL750BT-AX401901
MSL750AT-DC000201	MSL750AT-DC053401	MSL750BT-OP420901
MSL750AT-AX003701	MSL750AT-DC033401	MSL750BT-OP425001
MSL750AT-AV003601	MSL750AT-AX019601	MSL750BT-OP424801
MSL750AT-EP000301	MSL750AT-AX019201	MSL750BT-AX400801
MSL750AT-NV002401	MSL750AT-AX014801	MSL750BT-AX402201
MSL750AT-EP000201	MSL750AT-AX014901	MSL750BT-OP421201
MSL750AT-EP015001	MSL750AT-AX017901	MSL750BT-OP421501
MSL750AT-DC023901	MSL750AT-AX014701	MSL750BT-OP420401
MSL750AT-DC023601	MSL750AT-AX016001	MSL750BT-OP420801
MSL750AT-DC055401	MSL750AT-AX016401	MSL750BT-HB400301
MSL750AT-EP006201	MSL750AT-AX016501	MSL750BT-DC400101
MSL750AT-EP005101	MSL750AT-AX016601	MSL750BT-EL815501
MSL750AT-WP000501	MSL750AT-AX016701	MSL750BT-EL815201
MSL750AT-CC000601	MSL750AT-AX020201	MSL750BT-EL815901
MSL750AT-EP006401	MSL750AT-WP003701	MSL750BT-MD803201
MSL750AT-EP003701	MSL750AT-AX019901	MSL750BT-MD803301
MSL750AT-EP014701	MSL750AT-AX015301	MSL750BT-AX814801
MSL750AT-MP043701	MSL750AT-AX020101	MSL750BT-AX814901
MSL750AT-MP041701	MSL750AT-AX020001	MSL750BT-AX814501
MSL750AT-NV000501	MSL750AT-AX020301	MSL750BT-AX818401
MSL750AT-EP013801	MSL750AT-AX020401	MSL750BT-EL815801
MSL750AT-EP009501	MSL750AT-MP018701	MSL750BT-EL828501
MSL750AT-EP013901	MSL750AT-AX009401	MSL750BT-EL831401
MSL750AT-DC025801	MSL750AT-AX030101	MSL750BT-EL829501
MSL750AT-EP014101	MSL750AT-AX004801	MSL750BT-EL829701
MSL750AT-DC034701	MSL750AT-AX004701	MSL750BT-EL829401
MSL750AT-DC028701	MSL750AT-AX018501	MSL750BT-CC805001
MSL750AT-DC028401	MSL750AT-AX015701	MSL750BT-EL827201
MSL750AT-MP027201	MSL750AT-AX003501	MSL750BT-EL827501
MSL750AT-MP027301	MSL750AT-DK010801	MSL750BT-NV804701
MSL750AT-DK009001	MSL750BT-OP400101	MSL750BT-EL828001
MSL750AT-MP044301	MSL750BT-OP400301	MSL750BT-EL828101
MSL750AT-IS002401	MSL750BT-OP400401	MSL750BT-EL827701
MSL750AT-EP007001	MSL750BT-OP415801	MSL750BT-MP812301
MSL750AT-MP042101	MSL750BT-OP416101	MSL750BT-EL819001
MSL750AT-DC034101	MSL750BT-OP414901	MSL750BT-EL843401
MSL750AT-DC023701	MSL750BT-OP425801	MSL750BT-EL841801
MSL750AT-AX025601	MSL750BT-OP429701	MSL750BT-NV803301
MSL750AT-AX028101	MSL750BT-OP432101	MSL750BT-DC817801
MSL750AT-AX028001	MSL750BT-OP431701	MSL750BT-AV800601
MSL750AT-AX017501	MSL750BT-OP431601	MSL750BT-CC803701
MSL750AT-DC055301	MSL750BT-OP431501	MSL750BT-EL835401
MSL750AT-AX019101	MSL750BT-OP431401	MSL750BT-EL831601

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750BT-NV803801	MSL750BT-EL802101	MSL750BT-DC804201
MSL750BT-DC820501	MSL750BT-EL801301	MSL750BT-HB823701
MSL750BT-EL828901	MSL750BT-EL804801	MSL750BT-EL803101
MSL750BT-NV804801	MSL750BT-EL801901	MSL750BT-EL805701
MSL750BT-MP812701	MSL750BT-EL804101	MSL750BT-HB817301
MSL750BT-AV800701	MSL750BT-MP804501	MSL750BT-EL806701
MSL750BT-EL817901	MSL750BT-HB819601	MSL750BT-EL801801
MSL750BT-NV803001	MSL750BT-AX809501	MSL750BT-EL804001
MSL750BT-NV804501	MSL750BT-EL855501	MSL750BT-EL804501
MSL750BT-AX818301	MSL750BT-OH805701	MSL750BT-DK812301
MSL750BT-AX818501	MSL750BT-EL840601	MSL750BT-DK812401
MSL750BT-EL823801	MSL750BT-EL845101	MSL750BT-EL813401
MSL750BT-AX816801	MSL750BT-DC802801	MSL750BT-MP810701
MSL750BT-AX818601	MSL750BT-EL804601	MSL750BT-EL861501
MSL750BT-EL816901	MSL750BT-EL804701	MSL750BT-EL862901
MSL750BT-AX819001	MSL750BT-EL802001	MSL750BT-HB822301
MSL750BT-EL819601	MSL750BT-EL806201	MSL750BT-HB822101
MSL750BT-AX817401	MSL750BT-EL805001	MSL750BT-HB822201
MSL750BT-AX814301	MSL750BT-EL803701	MSL750BT-HB820601
MSL750BT-AX814401	MSL750BT-EL806001	MSL750BT-HB821601
MSL750BT-AX810801	MSL750BT-HB819401	MSL750BT-EL807701
MSL750BT-AX813401	MSL750BT-HB819501	MSL750BT-EL807301
MSL750BT-HB844701	MSL750BT-EL862401	MSL750BT-EL808201
MSL750BT-HB845001	MSL750BT-HB814301	MSL750BT-EL800801
MSL750BT-EL814801	MSL750BT-HB819001	MSL750BT-AX804601
MSL750BT-EL814701	MSL750BT-AX800901	MSL750BT-HB812901
MSL750BT-MP812601	MSL750BT-EL800701	MSL750BT-HB821301
MSL750BT-AX819101	MSL750BT-EL856501	MSL750BT-HB821501
MSL750BT-AX819301	MSL750BT-EL857901	MSL750BT-EL863101
MSL750BT-MD803001	MSL750BT-EL811701	MSL750BT-EL863201
MSL750BT-HB844601	MSL750BT-DK801801	MSL750BT-HB823201
MSL750BT-EL828201	MSL750BT-MP806901	MSL750BT-EL857401
MSL750BT-EL816001	MSL750BT-MP807001	MSL750BT-EL857501
MSL750BT-EL815001	MSL750BT-MP806801	MSL750BT-MP807301
MSL750BT-EL816101	MSL750BT-AX816101	MSL750BT-MP807201
MSL750BT-EL814301	MSL750BT-AX816501	MSL750BT-DC802601
MSL750BT-EL814601	MSL750BT-AX816201	MSL750BT-EL856901
MSL750BT-VT803201	MSL750BT-EL862501	MSL750BT-EL857001
MSL750BT-AX820901	MSL750BT-HB823101	MSL750BT-EL857101
MSL750BT-AX821101	MSL750BT-EL863901	MSL750BT-EL857201
MSL750BT-AX814601	MSL750BT-EL862701	MSL750BT-EL857301
MSL750BT-AX814701	MSL750BT-AX805701	MSL750BT-EL863301
MSL750BT-AX808501	MSL750BT-EL803001	MSL750BT-EL863401
MSL750BT-EL854101	MSL750BT-EL804401	MSL750BT-EL863501
MSL750BT-EL857801	MSL750BT-EL800901	MSL750BT-EL863601
MSL750BT-HB823401	MSL750BT-EL803401	MSL750BT-EL863701
MSL750BT-EL809301	MSL750BT-EL801501	MSL750BT-EL863801
MSL750BT-EL806401	MSL750BT-DC801701	MSL750BT-EL862601
MSL750BT-EL813001	MSL750BT-AX803701	MSL750BT-EL859201

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750BT-HB823001	MSL750BT-EL854001	MSL750BT-HB849101
MSL750BT-EL859401	MSL750BT-EL855401	MSL750BT-DC827401
MSL750BT-MP807601	MSL750BT-EL855601	MSL750BT-EL864301
MSL750BT-EL801401	MSL750BT-EL855701	MSL750BT-AX831801
MSL750BT-EL802201	MSL750BT-EL855801	MSL750BT-AX831901
MSL750BT-HB813001	MSL750BT-EL855901	MSL750BT-AX834101
MSL750BT-AX801201	MSL750BT-EL856001	MSL750BT-OH807001
MSL750BT-EL857701	MSL750BT-EL856101	MSL750BT-DC828401
MSL750BT-EL858901	MSL750BT-EL856201	MSL750BT-DC828501
MSL750BT-EL858001	MSL750BT-EL859101	MSL750BT-DC828601
MSL750BT-AX809101	MSL750BT-EL811801	MSL750BT-EL865801
MSL750BT-EL858201	MSL750BT-EL812001	MSL750BT-AX829501
MSL750BT-HB811201	MSL750BT-EL812101	MSL750BT-DC829701
MSL750BT-EL858301	MSL750BT-EL812201	MSL750BT-EL872401
MSL750BT-EL858401	MSL750BT-EL859601	MSL750BT-EL873501
MSL750BT-EL858501	MSL750BT-EL859701	MSL750BT-MP822601
MSL750BT-EL858601	MSL750BT-EL860001	MSL750BT-MP822501
MSL750BT-EL858701	MSL750BT-EL860201	MSL750BT-MP817301
MSL750BT-EL855301	MSL750BT-EL860401	MSL750BT-MP817501
MSL750BT-EL855101	MSL750BT-EL860501	MSL750BT-MP819601
MSL750BT-EL854201	MSL750BT-HB817201	MSL750BT-MP819501
MSL750BT-EL854301	MSL750BT-AX803901	MSL750BT-MP822801
MSL750BT-EL854401	MSL750BT-AX825901	MSL750BT-DK818501
MSL750BT-EL854501	MSL750BT-DK813601	MSL750MT-OH700301
MSL750BT-EL811101	MSL750BT-MP815301	MSL750MT-AX732701
MSL750BT-EL811201	MSL750BT-AX825401	MSL750MT-VT702201
MSL750BT-EL811301	MSL750BT-AX827301	MSL750MT-EL710101
MSL750BT-EL811401	MSL750BT-OH805501	MSL750MT-EL710401
MSL750BT-EL811501	MSL750BT-OH805601	MSL750MT-HB718001
MSL750BT-EL811601	MSL750BT-EL844001	MSL750MT-HB718201
MSL750BT-HB822001	MSL750BT-EL845701	MSL750MT-EL724701
MSL750BT-EL811901	MSL750BT-EL840801	MSL750MT-DK707901
MSL750BT-EL859501	MSL750BT-EL839401	MSL750MT-MP701001
MSL750BT-EL811001	MSL750BT-OH803801	MSL750MT-MP703001
MSL750BT-EL800601	MSL750BT-AX823401	MSL750MT-MP704101
MSL750BT-EL805101	MSL750BT-OH802301	MSL750MT-AX708501
MSL750BT-EL806801	MSL750BT-OH802201	MSL750MT-EL721701
MSL750BT-EL802901	MSL750BT-DC825501	MSL750MT-EL710601
MSL750BT-EL801601	MSL750BT-AX823601	MSL750MT-AX723501
MSL750BT-EL803801	MSL750BT-EL836701	MSL750MT-AX707901
MSL750BT-HB813801	MSL750BT-MP814101	MSL750MT-DC732001
MSL750BT-HB817101	MSL750BT-MP816801	MSL750MT-EL714701
MSL750BT-EL856301	MSL750BT-DC400901	MSL750MT-NV702701
MSL750BT-EL856601	MSL750BT-DC401301	MSL750MT-HB735101
MSL750BT-EL856701	MSL750BT-DC403401	MSL750MT-EL745701
MSL750BT-EL854601	MSL750BT-DC403301	MSL750MT-EL746201
MSL750BT-EL855001	MSL750BT-DC403201	MSL750MT-AX727501
MSL750BT-EL856401	MSL750BT-AX402301	MSL750MT-NV702801
MSL750BT-EL855201	MSL750BT-OP432301	MSL750MT-EL737801

USCGC BERTHOLF (WMSL 750)

5/8/2008

MSL750MT-MP710101	MSL750MT-EL722701	MSL750MT-HB732301
MSL750MT-MP706901	MSL750MT-EL728401	MSL750MT-HB733901
MSL750MT-EL732801	MSL750MT-HB700401	MSL750MT-HB736001
MSL750MT-EL734201	MSL750MT-DC721201	MSL750MT-HB733601
MSL750MT-EL732101	MSL750MT-EP701501	MSL750MT-HB733501
MSL750MT-DC738201	MSL750MT-NV703901	MSL750MT-HB733401
MSL750MT-EL728501	MSL750MT-MP708001	MSL750MT-HB733201
MSL750MT-HB703101	MSL750MT-MP707201	MSL750MT-HB733101
MSL750MT-HB703201	MSL750MT-MP710301	MSL750MT-HB733001
MSL750MT-HB710301	MSL750MT-EL726701	MSL750MT-HB732901
MSL750MT-EL710201	MSL750MT-EL737401	MSL750MT-HB732601
MSL750MT-HB717501	MSL750MT-DC733201	MSL750MT-HB735801
MSL750MT-HB709301	MSL750MT-EL701701	MSL750MT-NV705201
MSL750MT-EL713601	MSL750MT-EL700601	MSL750MT-HB736101
MSL750MT-EL708401	MSL750MT-EL706201	MSL750MT-HB736201
MSL750MT-HB713901	MSL750MT-AX726501	MSL750MT-HB736901
MSL750MT-CC709501	MSL750MT-EL728901	MSL750MT-HB737001
MSL750MT-HB731901	MSL750MT-MP713201	MSL750MT-HB737101
MSL750MT-DK702501	MSL750MT-HB734701	MSL750MT-HB737201
MSL750MT-EL718301	MSL750MT-HB737301	MSL750MT-HB737701
MSL750MT-DC729601	MSL750MT-HB737401	MSL750MT-HB737901
MSL750MT-NV700201	MSL750MT-HB737801	MSL750MT-HB738101
MSL750MT-MP706301	MSL750MT-HB737601	MSL750MT-HB738201
MSL750MT-EL721401	MSL750MT-CC714901	MSL750MT-HB738301
MSL750MT-EL721501	MSL750MT-NV705401	MSL750MT-HB738401
MSL750MT-EL713001	MSL750MT-NV705101	MSL750MT-HB738501
MSL750MT-EP201601	MSL750MT-HB732401	MSL750MT-HB738601
MSL750MT-EL736601	MSL750MT-HB734901	MSL750MT-MP715501
MSL750MT-EL736701	MSL750MT-EL746701	MSL750MT-WP701301
MSL750MT-AX704001	MSL750MT-EL741101	MSL750MT-EL744801
MSL750MT-AX702401	MSL750MT-HB732201	MSL750MT-EL745301
MSL750MT-AX702301	MSL750MT-HB733801	MSL750MT-AX756901
MSL750MT-AX730901	MSL750MT-HB734001	MSL750MT-EL746501
MSL750MT-EP200501	MSL750MT-HB735701	MSL750MT-EL746001
MSL750MT-EP204001	MSL750MT-HB735601	MSL750MT-EL745201
MSL750MT-EP201301	MSL750MT-HB735301	MSL750MT-EL745001
MSL750MT-EP205001	MSL750MT-HB735001	MSL750MT-EL746401
MSL750MT-EP204601	MSL750MT-HB734301	MSL750MT-EL746301
MSL750MT-EP201901	MSL750MT-HB734201	MSL750MT-EL745901
MSL750MT-NV703101	MSL750MT-HB734101	MSL750MT-EL746101

USCGC BERTHOLF (WMSL 750) 5/8/2008

△The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) : **Corrective Action Requests**

WMSL-750-A-122	WMSL-750-B-0219	WMSL-750-B-0269
WMSL-750-A-129	WMSL-750-B-0220	WMSL-750-B-0270
WMSL-750-A-130	WMSL-750-B-0221	WMSL-750-B-0271
WMSL-750-B-0015	WMSL-750-B-0222	WMSL-750-B-0272
WMSL-750-B-0039	WMSL-750-B-0223	WMSL-750-B-0273
WMSL-750-B-0046	WMSL-750-B-0225	WMSL-750-B-0274
WMSL-750-B-0052	WMSL-750-B-0226	WMSL-750-B-0275
WMSL-750-B-0066	WMSL-750-B-0227	WMSL-750-B-0276
WMSL-750-B-0070	WMSL-750-B-0228	WMSL-750-B-0277
WMSL-750-B-0080	WMSL-750-B-0229	WMSL-750-B-0278
WMSL-750-B-0087	WMSL-750-B-0230	WMSL-750-B-0279
WMSL-750-B-0092	WMSL-750-B-0231	WMSL-750-B-0280
WMSL-750-B-0095	WMSL-750-B-0232	WMSL-750-B-0281
WMSL-750-B-0111	WMSL-750-B-0233	WMSL-750-B-0282
WMSL-750-B-0114	WMSL-750-B-0234	WMSL-750-B-0283
WMSL-750-B-0137	WMSL-750-B-0235	WMSL-750-B-0284
WMSL-750-B-0139	WMSL-750-B-0236	WMSL-750-B-0285
WMSL-750-B-0142	WMSL-750-B-0237	WMSL-750-B-0286
WMSL-750-B-0143	WMSL-750-B-0238	WMSL-750-B-0287
WMSL-750-B-0154	WMSL-750-B-0239	WMSL-750-B-288A
WMSL-750-B-0159	WMSL-750-B-0240	
WMSL-750-B-0160	WMSL-750-B-0241	WMSL-750-B-E0033
WMSL-750-B-0161	WMSL-750-B-0243	WMSL-750-B-E0034
WMSL-750-B-0169	WMSL-750-B-0244	WMSL-750-B-E0035
WMSL-750-B-0171	WMSL-750-B-0245	WMSL-750-B-E0036
WMSL-750-B-0177	WMSL-750-B-0246	WMSL-750-B-E0037
WMSL-750-B-0178	WMSL-750-B-0247	WMSL-750-B-E0038
WMSL-750-B-0181	WMSL-750-B-0248	WMSL-750-B-E0039
WMSL-750-B-0186	WMSL-750-B-0249	WMSL-750-B-E0040
WMSL-750-B-0187	WMSL-750-B-0250	WMSL-750-B-E0041
WMSL-750-B-0189	WMSL-750-B-0251	WMSL-750-B-E0042
WMSL-750-B-0190	WMSL-750-B-0253	WMSL-750-B-E0043
WMSL-750-B-0194	WMSL-750-B-0254	WMSL-750-B-E0044
WMSL-750-B-0196	WMSL-750-B-0255	WMSL-750-B-E0045
WMSL-750-B-0198	WMSL-750-B-0256	WMSL-750-B-E0046
WMSL-750-B-0199	WMSL-750-B-0257	WMSL-750-B-E0047
WMSL-750-B-0200	WMSL-750-B-0258	WMSL-750-B-E0048
WMSL-750-B-0201	WMSL-750-B-0259	WMSL-750-B-E0049
WMSL-750-B-0204	WMSL-750-B-0260	WMSL-750-B-E0050
WMSL-750-B-0205	WMSL-750-B-0261	WMSL-750-B-E0051
WMSL-750-B-0206	WMSL-750-B-0262	WMSL-750-B-E0052
WMSL-750-B-0209	WMSL-750-B-0263	WMSL-750-B-E0053
WMSL-750-B-0211	WMSL-750-B-0264	WMSL-750-B-E0054
WMSL-750-B-0212	WMSL-750-B-0265	WMSL-750-B-E0055
WMSL-750-B-0214	WMSL-750-B-0266	WMSL-750-B-E0056
WMSL-750-B-0215	WMSL-750-B-0267	WMSL-750-B-E0057
	WMSL-750-B-0268	

USCGC BERTHOLF (WMSL 750) 5/8/2008

△The following is a list of outstanding deficiencies at time of delivery of USCGC
BERTHOLF (WMSL 750) : **Deferred Work (DW)**

DW 00207	DW 31571	DW 32674	DW 32909	DW 33336
DW 15245	DW 31574	DW 32689	DW 32914	DW 33338
DW 20805	DW 31743	DW 32690	DW 32922	DW 33341
DW 20892	DW 31745	DW 32693	DW 32928	DW 33344
DW 24046	DW 32154	DW 32695	DW 32935	DW 33350
DW 24048	DW 32155	DW 32696	DW 32936	DW 33357
DW 24057	DW 32411	DW 32698	DW 32951	DW 33358
DW 24349	DW 32412	DW 32699	DW 32955	DW 33362
DW 24352	DW 32414	DW 32700	DW 32957	DW 33363
DW 26406	DW 32416	DW 32732	DW 32958	DW 33366
DW 26464	DW 32417	DW 32733	DW 32959	DW 33372
DW 26616	DW 32441	DW 32734	DW 32962	DW 33373
DW 26693	DW 32448	DW 32735	DW 32963	DW 33375
DW 26695	DW 32449	DW 32736	DW 32969	DW 33379
DW 26696	DW 32462	DW 32737	DW 32970	DW 33380
DW 27042	DW 32470	DW 32739	DW 32971	DW 33381
DW 27072	DW 32472	DW 32740	DW 32974	DW 33383
DW 27101	DW 32475	DW 32741	DW 33201	DW 33384
DW 27180	DW 32483	DW 32742	DW 33203	DW 33385
DW 27190	DW 32501	DW 32743	DW 33209	DW 33387
DW 29114	DW 32502	DW 32745	DW 33210	DW 33390
DW 29115	DW 32522	DW 32747	DW 33211	DW 33391
DW 29127	DW 32544	DW 32748	DW 33212	DW 33394
DW 29131	DW 32556	DW 32753	DW 33216	DW 33395
DW 29141	DW 32560	DW 32754	DW 33219	DW 33398
DW 29144	DW 32564	DW 32755	DW 33220	DW 34001
DW 29150	DW 32567	DW 32758	DW 33221	DW 34003
DW 29192	DW 32568	DW 32759	DW 33232	DW 34004
DW 29194	DW 32569	DW 32760	DW 33233	DW 34005
DW 29410	DW 32570	DW 32761	DW 33234	DW 34009
DW 29456	DW 32572	DW 32764	DW 33240	DW 34010
DW 29476	DW 32574	DW 32765	DW 33243	DW 34015
DW 29477	DW 32576	DW 32870	DW 33244	DW 34029
DW 29479	DW 32578	DW 32872	DW 33247	DW 34031
DW 29480	DW 32579	DW 32873	DW 33248	DW 34033
DW 29482	DW 32581	DW 32878	DW 33249	DW 34034
DW 29589	DW 32582	DW 32879	DW 33311	DW 34037
DW 30204	DW 32584	DW 32880	DW 33312	DW 34039
DW 30206	DW 32585	DW 32889	DW 33314	DW 34044
DW 30276	DW 32595	DW 32892	DW 33317	DW 34045
DW 30280	DW 32597	DW 32895	DW 33319	DW 34478
DW 31456	DW 32668	DW 32898	DW 33323	DW 34712
DW 31505	DW 32669	DW 32899	DW 33324	DW 34720
DW 31563	DW 32670	DW 32903	DW 33333	DW 34723
DW 31569	DW 32671	DW 32907	DW 33334	DW 34732

USCGC BERTHOLF (WMSL 750) 5/8/2008

DW 34734	DW 34755	DW 34782	DW 35008	DW 35020
DW 34735	DW 34756	DW 35003	DW 35009	DW 35021
DW 34739	DW 34757	DW 35004	DW 35010	DW32961
DW 34747	DW 34758	DW 35005	DW 35011	DW33326
DW 34750	DW 34778	DW 35006	DW 35013	DW33392
DW 34751	DW 34781	DW 35007	DW 35014	

△The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) : **Contractor and ABS Liens**

Northrop Grumman Non-Conformance Report (NCR)

1594018	1638344	1652034	1633180	1649504
1594019	1641246	1652043	1633183	1649507
1596109	1643002	1652047	1633190	1649512
1601044	1643518	1652053	1633192	1649513
1606603	1643642	1652055	1638049	1649585
1607743	1643701	1652363	1641280	1649904
1607772	1644150	1652370	1641541	1650318
1608652	1644153	1652393	1646450	1650662
1608858	1645152	1652435	1646452	1650776
1615990	1645160	1652479	1646486	1650790
1616514	1645175	1652485	1646682	1652388
1617501	1645176	1652487	1646701	1653012
1617771	1645495	1652502	1648489	1653466
1622446	1645797	1652504	1648536	1653469
1622581	1645828	1652507	1648537	1654314
1622617	1646104	1652509	1648540	1654782
1626146	1646443	1652518	1648541	1654872
1626156	1646652	1652523	1648542	1654875
1626158	1646653	1652526	1648544	1656227
1626173	1646928	1652532	1648545	1656228
1627015	1647532	1652552	1648564	1656133
1629431	1647576	1652656	1648609	1655529
1630211	1648710	1652661	1648621	1656635
1633209	1649056	1652304	1649198	1655727
1633280	1649281	1653640	1649201	1655063
1633675	1649291	1653743	1649204	1656390
1634246	1649584	1654066	1649209	1655853
1634257	C176586	1654494	1649219	1655845
1635492	1650495	1654760	1649224	1656776
1636058	1650848	1654796	1649418	1656438
1637048	1650978	1654822	1649423	1656193
1637456	1651255	164175A	1649467	
1637592	1651306	1608492	1649470	
1638077	1651457	1633172	1649472	
1638125	1651776	1633174	1649473	
1638282	1651808	1633176	1649476	
1638338	1651964	1633178	1649484	

USCGC BERTHOLF (WMSL 750) 5/8/2008

**Lockheed Martin Non-Conformance Reports
(Trouble Failure Reports = TFRs), e-logs,
(Field Modification Bulletins = FMBs)**

TFRs

750G0000088A	750G0000223A	750G0000232A	750G0000243A
750G0000140A	750G0000224A	750G0000233A	750G0000246A
750G0000174A	750G0000225A	750G0000234A	750G0000247A
750G0000178A	750G0000226A	750G0000235A	750G0000248A
750G0000179A	750G0000227A	750G0000236A	
750G0000181A	750G0000228A	750G0000237A	
750G0000199A	750G0000229A	750G0000238A	
750G0000200A	750G0000230A	750G0000239A	
750G0000212A	750G0000231A	750G0000240A	

e-logs

54.1191.000.00 20519755-501

FMBs

NSC1 FMB 0102

ABS Material Liens, Card No.:

#958	#970	#976	#978
#966	#971	#977	

^The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) : **Tests**

Test Report

Comments

20222-4-202	31010-4-201	45209-4-004	52115-7-200	55510-7-200
20222-4-208	31010-4-202	45209-4-006	52810-2-201	55520-3-200
20222-4-209	31310-3-201	45209-4-007	52910-7-200	58211-4-200
20222-4-215	31412-3-200	45209-4-008	52913-4-200	58812-3-200
20222-4-226	32016-7-200	45209-4-008	53211-2-200	58818-3-200
20222-4-231	43212-3-201	45209-4-009	53211-4-200	58819-3-200
23310-2-200	44011-7-200	45209-4-010	53214-3-200	59314-4-200
23410-3-200	44019-5-200	47212-2-017	54111-3-200	59315-4-200
23411-3-200	44110-5-204	47212-2-019	54212-3-200	
25914-2-200	45010-5-201	51210-2-200	54311-3-200	
26211-2-200	45209-4-002	51218-3-200	55110-2-200	
31010-4-200	45209-4-003	52111-4-201	55510-4-200	

Test Procedure

Comments

07310-7-200	20222-4-202	20222-4-213	20222-4-218	20222-4-228
20213-5-200	20222-4-204	20222-4-215	20222-4-226	23310-4-201
20214-5-200	20222-4-211	20222-4-216	20222-4-227	26212-3-200

USCGC BERTHOLF (WMSL 750)

5/8/2008

32410-3-200	44112-2-202	52111-4-201	55510-4-200	56111-7-200
40711-4-200	51210-2-200	52910-7-200	55510-7-200	62410-2-200

Incomplete Tests

20214-5-200	44018-5-205	45510-5-004	47212-2-022	55518-2-200
20222-4-216	44112-2-202	45510-5-203	50210-6-200	56111-3-200
33013-6-200	45112-4-202	45510-7-001	50211-6-200	58314-3-200
33014-6-200.	45510-5-001	47212-2-021	54110-3-200	58315-3-200

Test Reports not received

07310-7-200	20222-4-233	43410-4-200	47212-7-014	56810-7-200
07311-7-200	30310-2-200	43712-3-200	47410-3-004	58111-7-200
07312-7-200	31410-3-200	44011-7-200	47510-4-200	58312-3-200
07313-7-200	32010-4-200	44011-7-200	48011-7-000	58310-7-200
07314-7-200	32012-3-201	44011-7-201	48210-7-001	58311-4-200
09410-7-200	32016-7-200	44011-7-201	48210-7-002	58314-3-200
09410-7-200	33013-6-200	44017-6-200	48210-7-002	58315-3-200
20012-5-200	33014-6-200	44018-5-200	49410-7-200	58811-6-000
20012-7-201	40410-2-200	44018-5-205	50210-6-200	58812-3-200
20013-2-200	40711-4-200	44110-5-203	50211-6-200	58819-3-200
20212-4-200	41011-4-201	44112-2-202	52115-7-200	58819-3-201
20212-7-200	41011-4-205	45112-4-202	52910-7-200	58819-3-202
20214-5-200	41012-2-200	45114-7-200	53110-7-200	58819-3-203
20216-3-201	42010-4-200	45114-7-200	53110-7-200	58819-7-200
20216-3-202	42010-7-201	45209-5-004	54110-3-200	62410-2-200
20222-4-205	42110-7-200	45209-7-001	55510-7-200	62510-3-200
20222-4-206	42312-2-201	45510-5-001	55518-2-200	66510-3-200
20222-4-212	42411-7-200	45510-5-003	55518-7-200	70310-3-200
20222-4-214	42411-7-200	45510-5-004	56110-3-200	70310-6-200
20222-4-216	42614-6-200	45510-5-203	56110-4-200	76014-3-200
20222-4-220	42614-7-200	45510-7-001	56110-7-200	84410-7-200
20222-4-221	42614-7-201	45510-7-001	56110-7-200	
20222-4-222	42614-7-201	47212-2-021	56111-3-200	
20222-4-223	43310-7-200	47212-2-022	56111-7-200	
20222-4-229	43311-2-201	47212-7-013	56111-7-200	

Tests that need to be reopened

20210-5-200	31010-3-202	53211-4-200	55517-4-200	MCMS
20212-4-200	52111-4-201	55112-3-200	58818-3-200	Underway Test
25610-3-200	52910-7-200	55510-4-200	MCMS In port Test	

USCGC BERTHOLF (WMSL 750) 5/8/2008

^The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) :

Contractor responsible Third Party Certifications

- Oil Pollution Abatement Inspection
- Stores Elevator Inspection
- Potable Water Purity (prior to Delivery)

Contractor support of incomplete USCG responsible Third Party Certifications

- Aviation Facilities Certification (Interim)
 - ASIST/TALON
 - TACAN
 - WMIS
 - SGSI
 - HRS
 - FDSSS
- Navigation System Certification - Interim
- Ammunition/Weapons Safety/Magizne Inspection/COT
- Weapons systems/Explosives/Ordnance Safety
 - RADHAZ Final
- IATO/ATO (transmitting classified data)
- SSAA Phase III Review & Approval SIPRNET
- SSAA Phase III Review & Approval
 - SBU LAN
- DITSCAP/DIACAP Certification and Accreditation
 - CMS (COMSEC) Safes
 - Type B Electronics Certification
 - TEMPEST Visual
 - TEMPEST Instrumented (Final)

^The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) : **Logisitcs Requirements Matrix**

- LRM No.
- J20-3 2.2
- J20-3 9.6
- J-20-2 2.13

^The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) : **Spares not received**

(Operating Space Items=OSI)
(Storeroom Items=SRI)
(Shorebased Spares=SRIS)

NGSB	DW1004498	DW8002176	DW1007156
DW1005222	DW1004427	DW1004461	DW1007242
DW1005237	DW1004428	DW1007242	DW1007156
DW1005237	DW1004434	DW1007162	DW1004475

USCGC BERTHOLF (WMSL 750)

5/8/2008

DW1004477	DW1004607	DW5006486	DW1004295
DW1004476	DW1004502	DW5005988	DW1007872
DW1007173	DW1004502	DW5000948	DW1007873
DW1007242	DW1004906	DW5001378	DW1003472
DW1010272	DW1004910	DW1016334	DW1015457
DW1016481	DW1004617	DW5003180	DW5005397
DW1004911	DW1015999	DW5001891	DW1005694
DW1004500	DW1015971	DW1016322	DW1001521
DW1004574	DW1007887	DW5003439	DW1002598
DW1004624	DW1016928	DW5005325	DW1002594
DW1004625	DW1016927	DW1007189	DW1002596
DW1004620	DW1014136	DW1004550	DW1002595
DW1004840	DW1014136	DW5004569	DW1002597
DW1004950	DW1016455	DW1016321	DW1002593
DW1016589	DW1016455	DW5004201	DW1003093
DW1016603	DW1014612	DW5004385	DW1003093
DW1016459	DW1012104	DW5003790	DW1011941
DW1016460	DW1012158	DW5002005	DW1011217
DW1016461	DW1011923	DW1016148	DW1011211
DW1016462	DW1011926	DW1016242	DW1011213
DW1016463	DW1012184	DW1011207	DW1011218
DW1016464	DW1006900	DW1007877	DW1011205
DW1016465	DW1006895	DW1001808	DW1011216
DW1016466	DW1014811	DW1005993	DW1011212
DW1016467	DW1004259	DW1006086	DW1011214
DW1016468	DW1004258	DW1005209	DW1011215
DW1016469	DW1003127	DW1016438	DW1011207
DW1016470	DW1003128	DW1016482	DW1011941
DW1016471	DW1009620	DW1016474	DW1011216
DW1016472	DW1009621	DW1016438	DW8000122
DW1016473	DW1009622	DW1016482	DW1011166
DW1016928	DW5005852	DW1016447	DW1014622
DW1016927	DW5005843	DW1016448	DW1014621
DW1003441	DW5005846	DW1016449	DW5005458
DW8002062	DW5000014	DW1016447	DW5005459
DW8002061	DW5001204	DW1016448	DW1003494
DW8002063	DW5000700	DW1016449	DW1002726
DW1015996	DW5004917	DW1016034	DW1002726
DW1015994	DW5005822	DW1016034	DW1002725
DW1015962	DW5005823	DW1014714	DW1002725
DW1016001	DW5005824	DW1004372	DW1002721
DW1015976	DW5005872	DW5006028	DW1002698
DW1015997	DW5004179	DW1002636	DW1002699
DW1004510	DW5004181	DW1001609	DW1002700
DW1004510	DW5005830	DW1015438	DW1012185
DW1004526	DW5005857	DW1004196	DW1011927
DW1004538	DW5002047	DW1004293	DW1011922
DW1004538	DW5005986	DW1004296	DW1004098
DW1004602	DW5005987	DW1004294	DW1004099

USCGC BERTHOLF (WMSL 750)

5/8/2008

DW1011929	DW1006728	DW1004078	DW1005161
DW1011923	DW1006722	DW5005610	DW1004503
DW1004092	DW1006720	DW1007871	DW1007853
DW1011925	DW1006729	DW1006626	DW1017060
DW1016184	DW1006727	DW1007853	DW1016335
DW1008225	DW1001693	DW1011414	DW1006192
DW1008226	DW1009619	DW1011415	DW1002833
DW1016443	DW1003130	DW1001614	DW1003679
DW1016443	DW1003126	DW8000051	DW1003678
PA0000050	DW1007573	DW1012263	DW1002842
DW1019229	DW1007578	DW1012264	DW1005796
PA0000052	DW1007574	DW1012259	DW1011122
DW1014839	DW1007579	DW1012271	DW1011114
DW1014404	DW1007580	DW1012265	DW1013181
DW1014551	DW1016243	DW1012266	DW1013184
PA0000053	DW1007573	DW1007693	DW1002833
DW1014637	DW1007574	DW1004205	DW1012261
DW1014636	DW1007575	DW8000051	DW1012262
DW1014377	DW1007575	DW8000094	DW1012268
DW5006034	DW1003148	DW1005772	DW1012269
DW5005607	DW1003131	DW1016026	DW1007691
DW1006842	DW1003132	DW1016196	DW1007692
DW5000894	DW1003133	DW1007288	DW1004301
DW5005199	DW1007579	DW1005588	DW1004302
DW5005408	DW1007578	DW1011414	DW1004304
DW1004905	DW1008036	DW1011415	DW1005796
DW1004905	DW1004303	DW1007853	DW1002833
DW1004937	DW1004303	DW1007423	DW1002935
DW5004953	DW1004303	DW1007432	DW1011354
DW1005209	DW1008358	DW1012256	DW1003139
DW5004172	DW1008358	DW1016026	DW1003137
DW5004588	DW8000009	DW1016172	DW1003146
DW1005645	DW1011133	DW1007751	DW1005846
DW1005645	DW8000010	DW1005588	DW1007566
DW1005642	DW1011132	DW1007436	DW1003121
DW1007017	DW1011132	DW1007414	DW1007576
DW1007726	DW1007593	DW1007434	DW1007727
DW1007728	DW1007594	DW1007419	DW1004206
DW1007729	DW1007593	DW1007420	DW1004204
DW1007727	DW1007594	DW1007440	DW1007576
DW1007726	DW1007593	DW1007416	DW1004202
DW1004260	DW1007594	DW1007442	DW1004200
DW1004257	DW1004329	DW1004600	DW1004206
DW1015453	DW1004369	DW1004602	DW1004204
DW1015454	DW1004359	DW1016198	DW5003723
DW1003485	DW1004375	DW1007867	DW5006376
DW1003486	DW1004315	DW1011414	PA0000124
DW1003187	DW1004077	DW1011415	DW5006238
DW1003185	DW1004078	DW8000051	DW5006348

USCGC BERTHOLF (WMSL 750)

5/8/2008

DW5002111	DW5006466	DW5000801	DW5006429
DW5003494	DW5006465	DW5002655	DW5006424
DW5000445	DW5004040	DW5005261	DW5006399
DW5005000	DW5004145	DW5003854	PA0000121
DW5005847	DW5003777	PA0000123	PA0000122
DW5005865	DW5006311	DW5005197	PA0000073
DW5001000	DW5006312	DW5005084	PA0000074
DW5001838	DW5006313	DW5002064	PA0000075
DW5004187	DW5001624	DW5002065	PA0000076
DW5003716	DW5004198	DW5002065	DW5000182
DW5003709	DW5003583	DW5005785	DW5000164
DW5006477	DW5003587	DW5005793	DW5000325
DW5006472	DW5003589	DW5005792	DW5001119
DW5006473	DW5003590	DW5005592	DW5000487
DW5006478	DW5001680	DW5005899	DW5000693
DW5006479	DW5001681	DW5005449	DW5000364
DW5003428	DW5002170	DW5003227	DW5000930
DW5001664	DW5006467	DW5003268	DW5000931
DW5005825	DW5004527	DW5003484	DW5005310
DW5003594	DW5004659	DW5003485	DW5001697
DW5005377	DW5003502	DW5006184	DW5001698
DW5003497	DW5000495	DW5006281	DW5003144
DW5005855	DW5000755	DW5006273	DW5002855
DW5005855	DW5004850	DW5006352	DW5001925
DW5005845	DW5001459	DW5006358	DW5006146
DW5005869	DW5001976	DW5006219	DW5000551
DW5005827	DW5005798	DW5006326	DW5000360
DW5005829	DW5002300	DW5001055	DW5000360
DW5005833	DW1016336	DW5006372	DW5000695
DW5005835	DW5003406	DW5005506	DW5001342
DW5005836	DW5000611	DW5002608	DW5003142
DW5005837	DW5004617	DW5000470	DW5002845
DW5005838	DW5001544	DW5004189	DW5002842
DW5006377	DW5000404	PA0000073	DW5002842
DW5006378	DW5002063	PA0000074	DW5002842
DW5006379	DW5002064	PA0000075	DW5000941
DW5006380	DW5004348	PA0000076	
DW5006381	DW5002063	DW5006462	
DW5006382	DW5003772	DW5006412	
DW5006383	DW5003990	DW5006410	

LMCO
DW1018015
DW1018076
DW2001098
DW2001098
DW1018078
DW8000714

DW1018077
DW1018069
DW1018013
DW1018056
DW1018033
DW2001635
DW2001637

DW8000713
5970DW5004513
DW5004513
DW5004513
DW5004513
DW5004513
DW5004513

DW5004513
DW5004513
DW5004511
5970DW5004511
DW5004511
DW5004511
DW5004511

USCGC BERTHOLF (WMSL 750) 5/8/2008

DW5004511	DW1018062	DW2001660	DW5004513
DW5004511	DW1018063	DW2001660	DW8003459
DW5004511	DW2001660	DW2001661	DW2001866
DW1018037	DW2001660	DW2001661	DW1018012
DW1018087	DW2001660	DW2001663	DW1018058
DW1018052	DW2001660	DW5004511	DW1018032
DW1018057	DW2001660	DW5004513	
DW5005937	DW5001574	5120DW1018068	DW5005914
DW2000892	DW5001574	DW1018005	DW5005914
DW1018010	DW5001574	DW1018093	DW5005914
DW5001522	DW5001574	DW1018088	DW5005914
DW5001522	DW5001574	DW1018023	DW5005914
DW5001522	DW5001574	DW1018079	DW5005914
DW5001522	DW5001574	DW1018004	DW5005914
DW5001522	DW5001574	DW1018085	DW5005914
DW5001522	DW5001574	DW1018084	DW5005914
DW5001522	DW5001574	DW5004435	DW5005914
DW5001522	DW5001574	DW5004435	DW5005914
DW5001522	5120DW5003619	DW1018064	DW5005914
DW1018020	DW1018073	DW1018086	DW5005914
DW2000950	DW5003619	DW1018006	DW5005938
DW2000950	DW5003619	DW2000947	DW5005946
DW2000950	DW5003619	6850DW1017143	DW5005930
DW2000950	DW5003619	DW1017143	DW5005931
DW2000950	DW5003619	DW1017143	DW5005932
DW2000950	DW5003619	DW1017143	DW5005933
DW2000950	DW5003619	DW1017143	DW5005934
6730DW2001665	DW5003619	DW1017143	DW5005935
DW1018034	DW5003619	DW1017143	DW5005936
DW1018094	DW5003619	DW1017143	6625DW5005926
DW1018014	DW1018090	DW1018081	6625DW5005927
DW1018019	DW1018043	DW5000342	6625DW5005928
DW1018091	5120DW1018044	DW1017143	6625DW5005929
DW1018018	DW1018072	DW1017143	DW5005923
DW5001374	DW1018095	DW5000342	DW5005924
DW5001374	DW5001766	DW5001574	DW5005925
DW1018080	DW5003563	DW5001574	DW5004186
DW2000949	DW5003563	DW5001574	DW5005948
DW1018070	DW5003563	DW5001574	DW5005948
DW1018083	DW5004500	DW5001574	DW5005963
DW5002278	5120DW1018065	DW5001766	DW5005963
DW1018047	DW1018003	DW5003726	DW5005964
5120DW1018025	DW1018022	DW5005939	DW5001375
DW1018075	DW5002138	DW5005905	DW5005957
7930DW5001574	5120DW1018066	1680DW5005910	DW5005947
DW5001574	DW1018074	DW5005914	DW5001374
DW5001574	5120DW1018049	DW5005914	DW5001374
DW5001574	DW5003592	DW5005914	DW5005913
DW5001574	DW1018089	DW5005914	DW5005958
DW5001574	5120DW1018067	DW5005914	DW5005958

USCGC BERTHOLF (WMSL 750) 5/8/2008

DW5005914	DW5005952	DW5005943	DW5005959
0116DW5005914	DW5005953	DW5005943	DW5005959
DW5001219	DW5005955	DW5005943	DW5005959
DW5005944	DW5005919	DW5005943	DW5005959
DW5005962	DW5004910	DW5005943	DW5005937
DW5004468	DW5005903	DW5005943	DW5005937
7920DW5003773	DW5005903	DW5005943	DW5006120
DW5003773	DW5005903	DW5005943	DW5006122
DW5003773	DW5006126	DW5005943	DW5006118
DW5003773	DW5005940	DW5005943	DW5004178
DW5003773	DW5006125	DW5005943	DW5002266
DW5003773	DW5002568	DW5005942	7240DW5002266
DW5003773	DW5003942	DW5005942	DW5002266
DW5003773	DW5005956	DW5005942	DW5002266
DW5003773	DW5005968	DW5005942	DW5002266
DW5003773	DW5005909	DW5005942	DW5002266
DW5003773	DW5001349	DW5005942	DW5002266
DW5003773	DW5005920	DW5005942	DW5002266
DW5003773	DW5006124	DW5005942	DW5002266
DW5003773	DW5003578	DW5005908	DW5002266
DW5003773	DW5000879	DW5005906	DW5002266
DW5003773	DW5000879	DW5005906	DW5002266
DW5003773	5110DW5001352	DW5005906	DW5002266
DW5003773	DW5001352	DW5005906	DW5002266
DW5003773	DW5001352	DW5005906	DW5002266
DW5005919	DW5001352	DW5005945	DW5002266
DW5006127	DW5001352	5120DW5005941	DW5002266
DW5003658	DW5001352	DW5005941	DW5002266
DW5004305	DW5001352	DW5005941	DW5002266
DW5001514	DW5001352	DW5005941	DW5002266
DW5003773	DW5001352	DW5005941	DW5002266
DW5005949	DW5001352	DW5005941	DW5002266
DW5005960	DW5001352	DW5005941	DW5002266
5120DW5005975	DW5005281	DW5005941	DW5006119
DW5005975	DW5005911	DW5005941	DW5005973
DW5005975	DW5001707	DW5005941	DW5005973
DW5005975	DW5005916	DW5005941	DW5005973
DW5005975	DW5005907	8030DW5005918	DW5005973
DW5005975	DW5006117	DW5005918	DW5005973
DW5005975	DW5005904	DW5005918	DW5005973
DW5005975	DW5005904	DW5005918	5970DW5005950
DW5005975	DW5003976	DW5005918	DW5005950
DW5005975	DW5005966	DW5005918	DW5005950
DW5005975	DW5005966	DW5005918	DW5005950
DW5005975	DW5005966	DW5005918	DW5005950
DW5005975	DW5005966	DW5005959	DW5005950
DW5005975	DW5005966	DW5005959	DW5005950
DW5005116	DW5005966	DW5005959	DW5005950
DW5004302	DW5000888	DW5005959	DW5005965
DW5006129	7920DW5005943	DW5005959	DW5005915

USCGC BERTHOLF (WMSL 750) 5/8/2008

DW5005915	DW5005974	DW5005906	DW5005937
DW5005921	DW5000724	DW5005906	DW5005950
DW5005921	DW5003773	DW5005906	DW5005950
DW5005921	DW5003773	DW5005912	DW5006123
DW5005921	DW5003773	DW5005918	DW5006128
DW5005921	DW5003773	DW5005918	
DW5005954	DW5003773	DW5005920	
DW5005397	DW5005255	DW5005922	

△The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) : **Work Items**

RO0001648536	RO0001649512	NCR0001646653	RFS-FH-000502
RO0001648537	RO0001649513	NCR0001646652	RFS-DC-000031
RO0001648540	RO0001649190	NCR0001644941	RFS-FH-000515
RO0001648541	RO0001649217	NCR0001644950	RFS-FH-000516
RO0001648542	RO0001649215	NCR0001645175	RFS-FH-000518
RO0001648544	RO0001649229	NCR0001644865	RFS-FH-000523
RO0001648545	RO0001649233	NCR0001641246	RFS-FH-000532
RO0001650790	RO0001649253	NCR0001634246	RFS-FH-000527
RO0001641280	RO0001649267	NCR0001649573	RFS-FH-000524
RO0001645485	RO0001649429	NCR0001645152/ 0001645160	RFS-FH-000539
RO0001646450	RO0001649435	NCR0001645694	PP1508-200-1
RO0001646452	RO0001649468	NCR0001643518	RFS-PF-000805
RO0001648485	RO0001638049	NCR0001646928	RFS-FH-000316
RO0001648486	RO0001649484	NCR0001645036	RFS-FH-000522
RO0001648487	RO0001649201	NCR0001641675	ANTI SWEAT & BOOTTOPPING
RO0001648488	RO0001649219	NCR0001646443	RFS-FH-000488
RO0001648489	RO0001649585	NCR0001649161	RFS-FH-000412
RO0001648635	RO0001650317	NCR0001648710	RFS-PF-000804
RO0001650318	RO0001649507	NCR0001646782	ROSE BOX
RO0001649204	RO0001649504	NCR0001647396	DW/DP00564
RO0001649207	RO0001649473	NCR0001645495	RFS-PF-000832
RO0001649470	RO0001626965	NCR0001647576	RFS-PF-000995
RO0001649472	RO0001650662	REPAIR GFE	RFS-FM-000060
RO0001649197	NCR0001641753	REPAIR LMCO	RFS-PF-000887
RO0001649209	NCR0001637592	NCR0001646696	DW/DV00130
RO0001649209	NCR0001644150	NCR0001646696	RFS-FH-000512
RO0001649476	NCR0001644153	RFS-FH-000526	RFS-FH-000512
RO0001649224	NCR0001626010	RFS-FH-000533	PP3101-953-1
RO0001646682	NCR0001630197	RFS-FH-000208	RFS-FH-000564
RO0001649198	NCR0001630211	RFS-FH-000491	RFS-FV-000255
RO0001649418	NCR0001633675	FAB & INSTL	DW/DP00619
RO0001649423	NCR0001649151	RFS-FH-000505	RFS-PF-000911
RO0001645008	NCR0001643002	RFS-FH-000490	RFS-PF-000745
RO0001646701	NCR0001645972	FDN	RFS-PF-000878
RO0001648564	NCR0001645176	RFS-FH-000394	RFS-PF-000871
RO0001627358	NCR0001645931	RFS-PF-000921	RFS-PF-000818
RO0001649467	NCR0001645216	RFS-FH-000521	RFS-PF-000870
RO0001649509	NCR0001644637	RFS-FH-000348	RFS-PF-000805

USCGC BERTHOLF (WMSL 750) 5/8/2008

RFS-PF-000528	RFS-TE-00234	RFS-TT-000039	NCR0001631098
RFS-FE-000249	RFS-TE-000225	DW/DE00198	WMSL-750-B-0198
DW/DE00962	RFS-DC-000027	NCR0001615990	SSR #094326
DW/DE00935	PP6177-125-1	5- - 44. -01- E	NCR0001622446
DW/DE00946	RFS-TE-000244	5- - 52. -01- E	NCR0001608858
RFS-FE-000250	RFS-FE-000270	2- - 89. - 0- Q	NCR0001647532
DW/DE00948	RFS-DE-000431	RCF41727	NCR0001638282
RFS-FE-000249	RFS-TE-00234	RCF48909	NCR167782
DW/DE00947	RFS-FO-000209	RCF44468	NCR173005
RFS-DC-000027	DW/DE00960	NCR0001616855	NCR0001547112
DW/DE00878	RFS-FE-000214	NCR0001623469	

^The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) :

USCG Contract Letters

08-003
08-022
08-039
08-070

USCG Contract Letters Pending Final Resolution:

06-100
06-254
07-162
07-212
08-030
08-090
08-106
08-122
08-123

^The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) : **Factory Acceptance Test Items**

SSDG

MCMS (covered by new tests)

USCGC BERTHOLF (WMSL 750) 5/8/2008

The following is a list of outstanding deficiencies at time of delivery of USCGC BERTHOLF (WMSL 750) : **Contract Modifications and other activities**

Incomplete Authorized Modification Requests:

Mod # / Activity	P00071	WA007
P00032	Waterfront	WA008
P00033	Changes	WA009
P00040	WA001	WA010
P00067	WA002	WA011
P00068	WA003	WA012
	WA006	

Undispositioned RFCs:

J001	RFC-189/J64	RFC-247 /J132
J003	RFC-190/J65	RFC-248 /J133
J004	RFC-192/J66	RFC-249 /J137
J005	RFC-193/J68	RFC-250 /J135
J006	RFC-196/J71	RFC-251 /J138
J007	RFC-199/J74	RFC-252 /J141
J008	RFC-198/J75	RFC-253 /J144
J009	RFC-191/J67	RFC-254/J156
J010	RFC-206/J81	RFC-255 /J153
J011	RFC-212/J73	RFC-256 /J142
J012	RFC-208/J86	RFC-257 /J143
J013	RFC-209/J87	RFC-258 /J149
J015	RFC-210/J88	RFC-259 /J151
J016	RFC-211/J89	RFC-260 /J134
J017	RFC-213/J90	RFC-261 /J154
J018	RFC-214/J91	RFC-262 /J154
J019	RFC-215/J92	RFC-263 /J158
J020	RFC-216/J93	RFC-264 /J139
J022	RFC-217/J94	RFC-265 /J159
J023	RFC-218/J95	RFC-266 /J150
J024	RFC-219/J96	RFC-267 /J146
J025	RFC-220/J97	RFC-268 /J160
J026	RFC-220A/J101	RFC-269 /J161
J029	RFC-222/J101	RFC-270/J157
J-35	RFC-223/J102	RFC-271 /J162
RFC-131A /J130	RFC-224/J102	RFC-272/J174
RFC-NSC-158	RFC-225/J104	RFC-273/J175
RFC-NSC-159	RFC-230/J109	RFC-274/J173
RFC -171	RFC-235/J114	RFC-275 /J163
RFC -172	RFC-236/J115	RFC-276/J183
RFC -173/J46	RFC-239/J122	RFC-277/J184
RFC-176/J49	RFC-240/J123	RFC-278/J185
RFC-177/J50	RFC-241/J124	RFC-279/J186
RFC-180/J55	RFC-242/J125	RFC-280/J187
RFC-181A/J56	RFC-243/J126	RFC-281/J188
RFC-186/J61	RFC-244/J127	
RFC-187/J62	RFC-245/J129	
RFC-188/J63	RFC-246 /J131	

USCGC BERTHOLF (WMSL 750) 5/8/2008

Undispositioned RFDs:

NSC-1016/07
NSC-1020/07
NSC-1021/07
NSC-1023-08
NSC-1025-08
NSC 1026-08

NSC 1027-08 Rev B
NSC 1029-08
NSC 1030-08
NSC 1031-08 Rev A
NSC 1034-08
NSC 1036-08

NSC 1038-08
NSC 1040-08
NSC 1041-08
DW00004909