

## DISCONTINUATION OF THE AT-MIO-64F-5

The AT-MIO-64F-5 is being discontinued. You will not be able to order this product after March 15, 1999, and you must accept delivery of the order by March 31, 1999. No warranty repairs will be authorized after March 31, 2000.

## **Important Dates**

Final Order: March 15, 1999 Final Delivery: March 31, 1999 Final RMA: March 31, 2000

## **Alternative Solutions**

The AT-MIO-64E-3 is functionally similar to the AT-MIO-64F-5 and may be used as an alternative, but there are important differences. The AT-MIO-64E-3 has a different 100-position I/O connector, requires a different I/O cable, and has a different pinout for the extended analog channels. Additionally, the channel numbers for the extended analog channels have been changed, which may require changes to existing programs.

If you have any questions about purchasing more of the AT-MIO-64F-5, please contact your local National Instruments sales representative. If you have any questions concerning replacing the AT-MIO-64F-5 with the AT-MIO-64E-3, please contact the National Instruments Applications Engineering department.