

# Pictures R-1490/URR

14-Jan-2007, VR2XGM




Fig. 5-1, Receiver, Radio R-1490/GRR-17 S/N:466, Top View with Transit Case Removed , Refer to Page 5-39



Fig. 5-2, Front Panel A1A1 S/N:466, Front View




Figure 5-3, Front Panel A1A1 S/N:466, Rear View, Refer to Page 5-41





Fig. 5-4. Front Deck A1A2 S/N:266, Bottom View, Refer to Page 5-42



Another View of Front Deck A1A2 S/N:466 Bottom, with Rear Section Folded




Fig. 5-5, Front Deck A1A2 S/N:466, Top View, Refer to Page 5-43




Figure 5-6, Rear Deck A1A3 S/N:466, Bottom View , Refer to Page 5-44





Figure 5-7, Rear Deck A1A3 S/N:466, Top View, Refer to Page 5-45



Front View, Unit S/N:466 in operation



Unit S/N:466 in operation , cover installed



Rear View , Unit S/N:466 in operation, cover installed