

ATI-AQ-005Rev 1

MODEL: **62**605

SUBJECT: Potential Hazard - Retrofit

LOCATION: Paper Decks

Detail:

Injury to the hands can occur when clearing paper jams from either of the front paper decks due to sharp edges.

Action:

Smooth edges of paper retaining plate as shown with a fine grade of emery cloth.





My thanks to Peter Mulholland of Canon Scotland for this information

Date: 24th June 1999

Issued by Product Technical Co-ordination
© Canon (UK) Limited

Page 1 of 1

Authorised: John Richards

