

SERVICE BULLETIN

Product :	LCD monitor	Bulletin No.	:	01-C/M-E0043		
Model :	S/M210T,S/M240T	Bulletin Date	:	Oct.04,2001		
		ECN Date	:	Oct.04,2001		
SUBJECT :	210T/240T speaker noise					
Background :	S/M240T monitor have some speaker noise from speaker circuit board.					
	The speaker board is assembled in speaker ass'y. Check version marked on speaker circuit board					
	ver 0.4 => Speaker noise					
	ver 1.0 => Improved					
Model name :	SyncMaster 210T / 240T					
	_					
Solution	Replace speaker board if customer complain and return.					
Solution	_Replace speaker board if customer complain	n and return.				
Solution	_Replace speaker board if customer complai The speaker board does not supplied as serv					
Solution		vice parts.				

Application Date : Oct.04,2001

					(Interchangeability	y coue .	1.0
Location	OLD (before) Parts			NEW (changed) Parts				
No.	SEC Code Description		ion	SEC Code		Description		I.C
								С
Туре	A type	B type	C type		D type	E type	F type	 >
Interchange	OLD Early	OLD	OLD 🚽	Early OLD	—►Early	Parts Addition	Parts dele	tion
Type Code	(Parts) (Prod.)	(Parts) (Prod.)	(Parts) (F	Prod.) (Parts	s) (Prod.)	(None New)	(Old D	Del.)
(* I.C)	NEW Late	NEW Late	NEW	Late NEW	∕► Late			
Application	Reference () Only	Defected set	s () (O Whol	e sets ()		
Attachment	Schematic Diagram () Component Lay-out () Exploded View ()							
	Mechanical	Diagram ()	None	()		Others ()	
Product Month :	- Aug all		Seri	al No. (~ fi	rom)			
Published by : (Published by : C.J.Oh Checked by : C.			rk Approved by : Y.K.Yoo				