

Date: 21 December 1998 Model: DV5161H

Ref No: DV5161-003 Classification: Routine

## TELEVISION TECHNICAL BULLETIN

**Subject: Corruption of NVM data** 

Page 1 of 1

**SYMPTOM** No teletext, colour or vertical size is incorrect.

**<u>CAUSE</u>** The microprocessor reset time is too short.

**ACTION** Carry out the following circuit improvement,

- 1. Increase the value of C1017 from 2.2MFD to 100MFD.
- 2. Add a 270ohm resistor in series with the positive terminal of C1017.

REF NO	<b>DESCRIPTION</b>	PART NUMBER	PRICE CODE
C1017	100MFD	VCEAGA1CW107M	AB
	270 Ohm 1/8W	VRD-RA2BE271J	AA

