

SONY car stereo Service Bulletin No.90

Technical Department
 Sony Service Company
 A Division of Sony Corporation of America
 Sony Drive, Park Ridge, New Jersey 07656

Model: XR-75/85/100

Date: October 16, 1987

Subject: Reference Number Correction -
 Wheel Ass'y, Worm

Symptom:
 (**)

The reference number for the part called the Wheel Ass'y, Worm shown in the diagram below is incorrect. This part is shown on one of the exploded views in each of the service manuals for the listed models. Please note the correct reference number as shown below. The same mistake was made for each listed model.

Solution:

Reference No.		Description	Part Number
Incorrect	Correct		
320	326	Wheel Ass'y, Worm	3-592-626-00

