

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7300

No. 104

Subject: Part Number Change - PCB,
Photo-interrupter

Date: July 29, 1988

Subject:

Symptom:
(**)

The part number for PCB, Photo-Interrupter change in the service manual.

Solution: The correct part number is listed below:

Ref No.	Description	Former	New
902	PCB Photo-Interrupter	1-623-447-11	3-596-596-01

Tuner/Tape Deck

CSA-14

Reference: TLX A880613

PRINTED IN U.S.A.
CSA-14788-1