

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-4140

No. 192

Subject: Part Number and Description
Corrections - Q102/202

Date: January 30, 1991

Symptom:
(**)

The part numbers and descriptions for Q102/202 are incorrectly listed on the parts list.

Solution: Please correct your service manual with the part numbers listed below:

Ref. No.	Description		Part Number	
	Incorrect	Correct	Incorrect	Correct
Q102	2SD1021	2SD1012	8-729-104-14	8-729-102-14
Q202				

CSA-14 Tape Deck