

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: XM-260G

No. 384


Subject: Schematic Correction.

Date: November 9, 1995

Symptom:

(**) The schematic diagram contains several errors.

Solution: Correct your schematic diagram as shown below.



Filename: CAR0384.SB
Directory: J:\SBDOC\NOV95
Template: C:\WINWORD\TEMPLATE\S_BULL.DOT
Title:
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 11/09/95 4:18 PM
Revision Number: 2
Last Saved On: 11/09/95 4:18 PM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 1 Minute
Last Printed On: 04/01/96 10:11 AM
As of Last Complete Printing
Number of Pages: 2
Number of Words: 89 (approx.)
Number of Characters: 510 (approx.)