

Model: XM-2545**No.** 421**Subject:** Part Number Correction - Reference No.
S101,S102,S201,S202, SWITCH,SLIDE**Date:** March 28, 1997**Symptom:**

(**)

The part number listed on page 20 of the Service Manual for Ref #
S101,S102,S201,S202, SWITCH,SLIDE, is incorrect.**Solution:**

Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
S101 S102 S201 S202	SWITCH,SLIDE	1-571-478-11	1-692-276-11

