

**SONY**

Car Stereo  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XES-C1

**No.** 215

**Subject:** Part Number/Description Correction: IC501/502

**Date:** October 18, 1991

**Symptom:**  
(\*\*)

The part number and descriptions shown on page 47 of the Service Manual for IC501 and IC502 are incorrect.

**Solution:**

Please make the following corrections to your Service Manual:

REF.	INCORRECT		CORRECT	
	DESCRIPTION	PART NO.	DESCRIPTION	PART NO.
IC501	$\mu$ PD75116GF-E25-3BE	8-759-154-97	$\mu$ UPD75116GF-E64-3BE	8-759-041-38
IC502	X24LC161	8-759-720-85	X24C16S1	8-759-513-44

CSA-14 CD Players