

SONY

Car Stereo Service Bulletin

Sony Service Company · Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-210A

No. 251

Subject: Part Number Information: Tape Guide; Head Plate Assembly


Date: August 14, 1992

Symptom:
(**)

Two (2) different versions of tape guides and head plate assemblies were used in production, but there is no compatibility between each version.

Solution:

Compare the tape guide and head plate assembly (in the unit being repaired) to the illustration below. Order the parts which correspond to those found in the unit being repaired.



CSA-14 Tuner/Tape Deck