

**SONY**

Hi-Fi Products  
**Service Bulletin**

**Sony Service Company** - Technical Services  
A Division of Sony Corporation of America  
Sony Drive Park Ridge, New Jersey 07656

**Model:** SEN-711CD

**No.** 209

**Subject:** Incorrect Component Model Identification For  
Cassette Deck.

**Date:** September 9, 1991

**Symptom:**  
(\*\*)

The Service Manual break-out sheet (P/N 9-956-517-11) identifies an incorrect model number for the cassette deck.

**Solution:** Correct your Service Manual with the cassette deck model number shown below:

DESCRIPTION	MODEL NUMBER	
	INCORRECT	CORRECT
CASSETTE DECK	TA-WR511	TQ-WR511

Miscellaneous  
**CSA-13**

Reference: P.R.

PRINTED IN U.S.A.  
CSA-13891-7