

**SONY**

Hi-Fi Products  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** HST-211

**No.** 243

**Subject:** Part Number For X301 Is Not Listed In  
The Service Manual.


**Date:** January 27, 1992

**Symptom:**  
(\*\*)

The part number for ceramic oscillator X301 shown in the schematic diagram on page 30 of the Service Manual is not listed in the parts list.

**Solution:** The correct part number for X301 is as follows:

REFERENCE	DESCRIPTION	PART NUMBER
X301	OSCILLATOR, CERAMIC	1-567-775-11



CSA-13 Compact System