

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
 A Division of Sony Corporation of America
 Sony Drive, Park Ridge, New Jersey 07656

Model: D-11

No.339

Subject: Description & Part Number Correction - Reference
 No. IC-801, IC CXP5024-111Q

Date: April 30, 1993

Symptom:



(**)

The description and part number listed on page 27 of the Service Manual for Ref # IC-801, IC CXP5024-111Q, is incorrect.

Solution:

Please note the correct description and part number as shown below.

REF	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
IC-801	IC CXP5024-111Q	IC CXP5084-621Q	8-752-815-51	8-752-819-91



CSA-13 CD Player



PRINTED ON RECYCLED PAPER

Reference: FPR-00306
 Autoflagged - NO

PRINTED IN U.S.A.
 CSA-13493-8