

SONY

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: HST-231

No. 355

Subject: Part Number Correction - Reference No. 53, Lid
(A) ASSY, Cassette

Date: October 12, 1993

Symptom:
(**)

The part number listed on page 33 of the Service Manual for Ref # 53, Lid (A) ASSY, Cassette, is incorrect.

Solution:

Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
53	LID (A) ASSY, CASSETTE	A-4943-222-1	X-4943-222-1

